ATR on Quality Control Check Repot. (Bungalows)

Recommendation that was made by QC: Stop further work. Submit ATR on Q Stop further work. Proceed with wor	Checked By MD on	Receipt at HO date	Receipt by QC date	Project Manager	Prepared by	Company	Bungalow No
at was made by QC: Submit ATR on QC R. Proceed with work a				A. Sueuch	S. Shaowani	VOC LLP	186
Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	MD Sign	Sign	Sign	Sign	Sign	Project	QC report stage
ceed only after recheck			_	-	S. Sharif	700	1
by QC.	For filling	Other	Other	Date	Date	Phase	SI. No.
	L SS L NO			29/10/19	29/10/19		34409

- Attach a copy of the QC report to this sheet.

 Circle each correction with a red pen tick () each circle for work completed and cross () each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

 Make 2 copied of the ATR send one to MD and other to QC.
- Enclose required photographs hard copy.

Re

		marks:
		Au
		BANGOM
		All nobles compliated

Checked By MD on Recommendation: Recommendation: Stop further work. Submit ATR on QC report to QC team. ATR on QC report to QC team. Stop further work. Proceed with work after submitting ATR on QC report to QC report. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	repared by roject Manager A SURESH 33614 Previous stage report no. MD Sign	ompany Vocallo Stage Stage No. 186 Project Sign	Quality Control Check Repot.
am. Proceed only after recheck by QC. ATR on QC report to QC team. as pointed out in the QC report. ATR not required.	Report filed and signed by PM? For filling	VCC Date	Stage: After Plastering (Villas) St. No.
	☐ Yes ☐ No	19 09 19	34409

Inspection should be done after:

brickwork & 2 coats plastering is completed

Proceed with further work. ATR not required.

water proofing, screeding in bathrooms is completed. after cleaning the Villa.

before starting painting, tiling & flooring.

Plastering Check.

Mark v for correct or minor mistake which does not require correction

Mark XXX for major mistake that cannot be corrected. Mark \times x for major mistake that requires correction by replacement or re-fixing. Mark X for minor mistake that requires minor correction.

9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".

Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")

Sill top must be of uniform thickness, correct height, at one level & without broken edges. All doors frames should have "grooves.

Page 1 of 3

_		-T.					I_		-	1	11	10	9	∞	7	6	5	4	w	2	-	S	S No
	Nomarks	Domorlio	19 Other	18 Utility		16 Portico	15 Head room	14 "Terrace/-balcony 2	13 Terrace / balcony	Lobby 2			Drawing	Toilet 4	n'4	Toilet 3 6.7	Bedroom 3 G. B	Toilet 2	Bedroom 2 K. S	Toilet 1 W. T	Bedroom I W. B		Room
		-			<		7.	2	1 4		1 3 m		1.		1	(<	1	4,	1	1		Skirting Provision (v or x)
		-			4	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	:	1	;	وريسيس المرا	1 5 4	1		1	<	ς.	<	()	C	1	7	Finishing around door frame (• or ×)
		-				. :	7		1	1)	<	1	· ·		3	4	1	1	C	1	3		Beams & columns finishing (v or x)
					و. براندسهم	***		+ Cape	******	1	9	-		()	1	4,07						Finishing of lofts (• or ×)
		-			~	a channe	<	4	<	4,000	1	< 1	<	1	1	5	4	3,	*	1.	1	5	Electrical junctions finishing (• or ×)
		-			~		<	1	<	1	<	5	5	1	1	-	, K,	<	6			1	Window check (v or x)
					<		1	(}	1	i.	1,17	1	1	1	(- Janes	<	- Libert -	(1	1	Tiles provision (• or ×)
			1			t	1	44	,	*	1	1	1	1	1	1	É	1	Ì		1)	Sink provision & size
					<	7 00 1	<	-	1	grant's		-174	5	1	1	1	-	1	,	1	5	1	Grooves for door frames (✓ or X)
			1		(C. Astron	F. Warner	5	-11-41	-	1	1	- Later 1	1	1	1	1)	Janes .	-	Balcony & terrace sill top finishing 10 (• or ×)
						*****			-	Market a	-	1	**********	10.000		-	1	· ·	1	(A APP-Pro	<	5,00	Screeding in bathroom & utility (v or x)
				1	4	***************************************	1	element.	1	47 740000	100	})	. 178)	1	1	2.17	<	1	Screeding in 6" above FFL? (v or x)

Overall quality of plastering?

Plastering of compound wall & gate pillars (v or X)

Plastering quality of parapet walls (v or X) Plastering and finishing of chajjas (v or X)

Remarks: Nice

Betore

OC Check

After plastering

Stoop I - Books

our completes

☐Yes ☐ No

Good Avg. Bad

Is plastering of compound wall and villa external walls 6" below FFL of setbacks?

Miscellaneous check

Page 3 of 3