ATR on Quality Control Check Repot.

Recommendation that was made by QC: Stop further work. Submit ATR on Q Stop further work. Proceed with work.	Checked By MD on	Receipt at HO date	Receipt by QC date	Project Manager	Prepared by	Company	Bungalow No
Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.				Sualsh A	I. Rama Brishus	noc up	253
report to QC team. Pro	MD Sign	Sign	Sign	Sign	Sign (Project	QC report stage
ceed only after recheck n QC report to QC tear				Ş	J. Kort.	NoC	146
t by QC.	For filling	Other	Other	Date	Date	Phase	SI. No.
	∐ Yes ∐ No			2119 (17	31.4	0.12	31565

- Attach a copy of the QC report to this sheet.

 Circle each correction with a red pen tick (>) each circle for work completed and cross (x) each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

 Make 2 copied of the ATR send one to MD and other to QC.
- Enclose required photographs hard copy.

			Remarks:
			M life
			All works completions
			(3)

	Quality Control Check Repot.		Stage: After Plumbing & Electrical (Villas)	Electrical (Villas)	
Bungalow no.	23	Stage		SI. No	
Company	1 ton () 0)	Project		51	33565
Dranged has	Anc Crehy		VOC	Phase	1
Frepared by	a. RAJES H	Sign	100	Date	1.1.21.4
Project Manager		Cion	1000		11 50 11
	A.SUKES H	ngia	-·	Date	11 25 1 19
Frevious stage report no.	no,	33437	Report filed and signed by PM?	d by PM?	Ves ING
Additions & alterations sheet date	is sheet datc	3	All margar diam of L		
Charlest Day MD		61170167	Au Pages signed by engineer & customer	ngineer & customer?	Yes No
Checken by Mill on		MD Sign		For filling	Yes No
Recommendation:					
Stop further work Stop further work Proceed with further Proceed with further	Stop firther work. Submit ATR on QC report Stop further work. Proceed with work after a Proceed with work after a Proceed with further work. ATR not remined Proceed with further work. ATR not remined	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed wit. further work, may after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required	eed only after recheck I QC report to QC team. Louis is the QC report 2	y QC. YTk not required.	
inspection should be done after:	affor:				

after cleaning the bungalow.

before starting painting, tiling & flooring.

electrical conduct, waterproofing & plumbing work is completed (for stage II only).

additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be

additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

2

Civil work near pipes in balcony & willby must be not so a Wigner of the near the second with the new to a second with th

W. Arm Camerica . Location, height and spirit location Location of CPVC & F. . . . Mark XX for major recommendation Max Managaria

In the second of the content of the second s

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

MISCELLATIONS CHECK	
Depth of drainage line at compound wall specified :	2'o" Depth provided: 2'O"
Fastners for external PVC/CPVC lines (v or x)	<
Setbacks properly leveled and compacted to 3" below proposed FFL?	No □No
Lawn area property leveled and compacted to 9" below lawn FFL?	√Yes □No
Electrical pipes for electric power supply & communication provided from compound wall?	ŪÝes □No
Workmanship of drainage lines	Good MAvg. Poor
Earthing provided?	☐ Yes ☑ No
Remarks	
	to control of the con

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

		_ [E.	Γ	Ι	Т	· [-	7	<u>;</u>	*			_T —	т	7	η	T-12			
		7	16 1	15	14	ū			1	-	9	∞	ŗ	6	N	4	w	2	۲	S No	
	TXICTION	Citchen	Portico	Head room	Ferrace/-balcony 2	Terrace / balcony 1	Eobby 2	Labby 1 F. 7	- 1		Drawing	Toilet 4-	Bedroom 4	Toilet 3	n 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room	-
(C)					ny-2	ny i				<u>L</u>	-+			7.3	G.B 1	いイ	C.B	M.7	M.B		
			!	•	1	7	1			1				}	1	1	Ĵ	1		near pipes in balcony & utility (or x)	Civil work
Çt °≈ ∗			1	1	1	!	+			**************************************	١			ζ,	13	3	10	À]	PVC Check	CPVC &
ا بر آد	7	<			1		\		7	\ \ \ \	1	ì		ζ.	7		3	< !		points check	Electrical
		· · · · · · · · · · · · · · · · · · ·	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		!]	J			}	2	-			<		1 8		1	ng check <)	Water
	1	;	}	1		1			*****	1 ,	7		<		! <		1			fasteners check (• or x)	Proper use of
	!	}	9	1	 -	١				<	1	1	! 1			· ·	۲٠.			DB (v or x)	Discoment of
									I I	, , 	1	12-	}	,		.])			Generator changeover (• or ×)	Diagram to f

The second secon

QUELECTICSLIFIAN UT 1787-01 NO FORTIONS FROM: A MINISTER WAS A SAME OF THE SAM

30-02-7016 19:36

l lo í

