Quality Contr
Juality Control Check Repot.
Stage: After Fir
Stage: After Finishing Stage II (Apartments)
(Apartments)

Flat No	c-007	Other		Sl. No.	27398
Company	27 C	Project	MFG	Phase	H
Prepared by	S. Sunil Human	Sign		Date	15/6/17
Project Manager	Subba Reday, Sign	Sign	relia .	Date	15/6/14
Previous stage report no.	no.	26332	Report filed and signed by	ed by PM	NYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Procer submitting ATR on ing corrections pointedired.	eed only after recheck look of the QC report to QC team do out in the QC report.	by QC. ATR not required.	

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

0							
	False ceiling to be provided?		Main door granite soffit workmanship Good Avg Poor Main door granite soffit edg	Granite soffit for main door required Yes \(\subseteq \text{No} \)	Balcony granite soffit workmanship	Granite soffit for balcony required	Main door fixed with lock & stopper Yes No
1100 41	Yes □No		☐ Good ☑Avg ☐ Poor	☐Yes ☐ No	Good Avg Poor	∠Yes □No	☐Yes ☐No
	False ceiling workmanship	polishing	Main door granite soffit edge	Granite soffit for main door provided	Balcony granite soffit workmanship	Granite soffit for balcony provided Yes \(\subseteq No	
	Good Avg Poor	0.000	Good Avg Poor	provided Yes No	☐ Good ☐ Avg ☐ Poor	Yes No	

Ren	9	∞				S	4	w	2	1	S No) its
Remarks (1) In whi	Other	Other	Utility	Kitchen	dining arca	Wash basin in	-Toilet 4	Toilet 3:	Toilet 2 G. Toi	Toilet 1 M-701	Room	Tiling & granite work
Hility (×	!	,		,	•	ζ	5	Workmanship of tiling	
9215	•		ς	١			1	•	(ζ	White cement filling around CPVC lines	
7			ς	1	1		,	,	ς.	۲	Corners finishing	Rate th
5			ς	1.	,		1	1	ζ.	ς	Finishing near doors	e quality
2000			(•	ţ		1	ļ	<	5	Finishing on top of tiles	of (Goo
2				1	•		1	ļ	(ζ.	Finishing near ventilators	id v, A
			\	٩	1		7	1	(Ź	Step at bathroom entrance / utility	Rate the quality of (Good , Avg. X, Poor – nee
シャーク			ζ	j	j	37	1	1	\	,	Step for shower / pot wash	00r – ne
			×	1	١	8	1	1	35	×	Tile joint grouting	eds corr
			١	1	1		1		1		Granite platform finishing and edge polishing	ection 🗙
			!	1	,		1)	1	١	Granite platform slope	ds correction $\mathbf{x} \mathbf{x}$, NA)
)	1	7	1)	١	1	1	Granite platform height	
			١	1	1))))	Finishing under granite platform	