Quality Control Check Repot. Stage: After Plastering (Apartments)

			2		
Flat No.	C-406 *	Other	SI. P	No.	2+248
Company	0 kg e3	Project	Visto Homes Phase	se	
Prepared by	D. D. S. L. X.	Sign	Date		19/5/17
Project Manager	-	Sign	Date		191517
Previous stage report no.	rt no.		Report filed and signed by PM?		S Zo
Checked By MD on		MD Sign	For	filling Ye	Yes No
Recommendation: Stop further worl Stop further worl Proceed with further worl Proceed with further worl Proceed with further worl Recommendation:	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck leads Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proces	oy Qo ATR	C. not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ken	0	15	14	13	12	_	10	9	8	7	6	5	4	3	2		S No
Kemarks	orles	Other	Other	Kitchen	-Utility / balcony 3~	Utility / baleen y/2	Utility/ balcony 1	Lobby-1-	Dining	Drawing	- 3	Bedroom 3 (5,-3ec)	1 3	n 2	ر ر	Bedroom I M. Bed	Room
				ζ,	1	ζ	<	ţ	1	5	1	ς	<	ς	5	ζ	Skirting Provision (v or x)
				ζ	1	メ	}	ļ	1	5	1	٢	ζ.	ς.	ς.	٢	Finishing around door frame (• or ×)
				<	1	7	<	١	1	X	1	ς	\$	ς	ζ,	(Beams & columns finishing (v or x)
				ζ	1	}	1	I	1	1	1	1	1	1	5	١	Finishing of lofts (• or ×)
				1	-	ς.	(١	١	ς	1	メ	<	×	5	Х	Electrical junctions finishing (• or ×)
				<	1	1	}	١	Ţ	f	1	\	ς	ς	5	ς.	Window check ⁶ (✓ or ×)
			•	×		′	}	1	ſ	1		\	ς	}	ς.	Į	Tiles provision (✓ or ×)
				X	1	\ \ \	[ſ	ļ	1		1	1	١	}	4	Sink provision & size (✓ or X)
			200.00	1	1	ζ	١	1		}		<	ζ.	ς.	ς.	(Grooves for door frames (• or ×)
				1	١	ļ	1	ţ	1	1		1	,	}		J	Balcony & terrace sill top finishing(v or x)*
				1		<	1	1	1	1		1	<	1	(1	Screeding in bathroom & utility (or x)
				١)	<)))	١)	١	′	١	1	١	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Apartments)