## Quality Control Check Repot. Stage: After Plastering (Apartments)

	k			21	
Flat No.	6-003	Other		SI. No.	28384
Company	Warten	Project	that have	Phase	)
Prepared by	Nex	Sign	Pay	Date	日三二十
Project Manager	1. Mashy	Sign	1 Jour May	Date	4 = 10
Previous stage report no.	t no.	とイタイン	Report filed/and signed	d by PM?	Yes   No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work  Stop further work  Proceed with fur	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR no Proceed with further work. ATR not required.	eport to QC team. Proc fter submitting ATR or king corrections pointe aired.	seed only after recheck land out in the QC report.	by QC. ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

200

	1.	Т. Т.	1	Т	Т	1	_	Т	_	Г	1	_		_		
Remarks	15	-	13	-		I	9	~	7					, ~	1	S No
arks	Other	Other	Kitchen	Utility / balcony 3	Utility / balcony 2	Utility / balcony 1	Lobby	Dining	Drawing	Toilet-3	Bedroom,3	Toilet 2 cT	Bedroom 2 65	-	<u>n</u>	
			<	1	<	<	J	<	\	1	1	<	5	7	5	Skirting Provision ( • or ×)
			5	1	1	<	ſ	(	<	-	)	<	5	5	7	Finishing around door frame ( • or ×)
			<	ſ	<	<	1	<	5	1	1	<	<	5	7	Beams & columns finishing (✓ or 🗙)
			<	1	1	1	1	<	7	1	J	)	5	)	<	Finishing of lofts ( $\checkmark$ or $\times$ )
			<	1	<	5	1	<	<	1	1	<	人	<	メ	Electrical junctions finishing ( v or x)
			<	1	1	1	1	`	7	1	J	<	<	<	5	Window check <sup>6</sup> (✓ or X)
			X	1	(	5	1	1	1	1	1	<	ſ	<	1	Tiles provision  ( • or ×)
		(	(	1	1	1		l	J	1	1	<	5	<	(	Sink provision & size ( ✓ or X)
			1	1	1	<	1	1	5	1	-	< '	<	<	<	Grooves for door frames ( v or x)
			1	1	<	)	1	)	)		1	1	5	)	)	Balcony & terrace sill top finishing( • or ×)
			1	١	1	<	1		1			1		<	1	Screeding in bathroom & utility ( • or ×)
		1	i	١	1	5	1	١	)	1			,	1		Screeding in 6" above FFL? ( • or ×)