Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	D 224	Other		SI. No.	29014
Company	PMR	Project	AME	Phase	<u> u </u>
Prepared by	M. Teja Snidher	Sign	4	Date	13/01/18
Project Manager	SHIKBH	Sign	Pe 11 1 8	Date	13/01/18
Previous stage report no.	no.	h8.9 & &	Report filed and signed by PM?	d by PM?	Mycs No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Procter submitting ATR on ing corrections pointerired.	eed only after recheck be QC report to QC team. d out in the QC report. 1	c by QC. m. .: ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	15	14	13	12	11	10	9	∞	7	6	5	4	w	2	1	S No
Remarks	Other	Other	Kitchen	Utility/balcomy3-	Utility / balcony-2	Utility/balcony 1	Lobby 1	Dining	Drawing	Toilet-3	Bedroom-3-	Toilet 2 (い)	a 2	Toilet 1 (Mr)	n 1	Room
			<	i	<	<		<u> </u>	<	ļ]	<u> </u>	<	<	<	Skirting Provision (• or ×)
			1	t	<	(_	<	(1	4	<	<	۲	Finishing around door frame (• or ×)
			<	(<	〈	-	V	<		}	✓	<	〈	<	Beams & columns finishing (v or x)
			<	{	١	Ι,		((-	J	~	~	-	-	Finishing of lofts (• or ×)
			<		~	۲	-	4	<		1	1	<u> </u>	く	<	Electrical junctions finishing (v or x)
	d R		<		\	١		<u> </u>	<	-	1	~	<	<	<	Window check ⁶ (✓ or X)
			<	1	<u> </u>	1	1	-	ſ			V	١	<	1	Tiles provision (✓ or 🗙)
			<	1	<	{		((1	١	<	1	Sink provision & size (✓ or 🗙)
			{	1	<	1		1	<	-	1	1	V	<	<	Grooves for door frames (• or ×)
			_	}	1			1			}	J	1		ſ	Balcony & terrace sill top finishing(✓ or 🗙)
				1	~			-	1	ļ)	\	1	<	1	Screeding in bathroom & utility (v or x)
			1	1	<	1		1	_	1	1	〈	1	<	-	Screeding in 6" above FFL? (• or ×)