	CHAMILY COULD	One lity Control
	Check Kepot.	
STATE OF TRACE	Stage: After Plactor	
THE LABOR CHIE	wing ( A moutance	

Checked By MD on MD Sign For filling Yes		t no. $28165$ Report filed and signed by PM?	Subba Reddy Sign 7 22 Date	M. leja Sridher Sign W Date	BNC Project MFG Phase	f-Sol , Other SI. No. $99.00$
	□Yes □No	NYes No	9.3/01/18	20 00 00	= 200	79200

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark ✔ for correct or minor mistake which does not require correction
- Mark  $\mathbf{X}$  for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.

  9"unplastered area from SFL should be left including in common areas and terraces.
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1") Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼".
- Sill top must be of uniform thickness, correct height, at one level & without broken edges. All doors frames should have 1/2" grooves.

			7	D 5	4	1 2			15	9	T∝		1 0	7	<u>۷</u>	4	<u>رب</u>	2		
			Remarks		+-		-	+-	1	-	<u> </u>				4				<u> </u>	S No
-	ļ				Other	Kitchen	Utility-/ balcony 3	tility	Utility / balcony 1	Lobby-1	Dining	Jraw	OHer-3	1000	Redroom 2	Toilet 2	Bedroom 2	Toilet 1	Bedroom	Room
			Now.			m	1-ba	//ba	y/be	Ţ	9	gar	1	THOO	3	2	moo	)t 1	moon	
		5,	, ,		,		dcon	нөөн	lcon					(dn)	2/	ہارہ		$\overline{}$	1	
		\	0				y3-	<del>y2</del>	y 1					70		-1	63	डे	MB)	þ
		West	Instiad	_		-		2	_		1	,	-	-	+	-	-			
			3			)	1	1	1		1	<	1	<	1		۲	<	<	Skirting Provision  ( • or ×)
		_	10	-		1		7				_		  -	,		-			<del></del>
			_	-			1	\	1		١	1	1				١	<	1	Finishing around door frame ( v or x)
			1.6			<		<b>〈</b>	5		<b>〈</b>	 ~		1		+	_	2		Beams & columns
	81		5	L		\	1	1	7	1		,	-{			\   	`	<u>۲</u>	۲	finishing (v or x)
			Skirting			<	,	1	1		ī	 	•	1				,	ı	Finishing of lofts
		(	3				1			1			1	,	1		1	'	1	(v or x)
		3	7				1	2		1	<	<	1	<	<	<	<		<	Electrical junctions
		(	thy			_	1			_						\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			`	finishing (v or x)
					,		,		1		(	1	1	<	<	K	4	<u>`</u>	<b>〈</b>	Window check <sup>6</sup>
	1	Ī	have		_	1	1	<u>\</u>		\ 	_									( • or <b>x</b> )
		ł	6			$\langle  $	•				(		1	1	<	1	<	,   ,	ζ	Tiles provision
	Í		Rosin	_	_	-	<u> </u>		_	_	_	1	_			<u> </u>			-	( ✓ or X)
1 1					<	\	<					<b>j</b>   '		١	<	1	<	1		Sink provision & size
			the	+	-	-	-	-		+	-	-	<u> </u>	-	_	_		_	$\downarrow$	( v or X)
			6			١,	<	1	1		<		١	<	<	<	<	<	100	Grooves for door
			=	-	-	-		+	-	+	+	-	1 ! - <del> </del>	_	_		<u> </u>	1	1	frames ( v or x)
	10,10		27				1	]]			1		1	1	ſ	ſ	1	ſ		Balcony & terrace sill top finishing( or x)
		f	· ' }	+	+	+	+	+			+-	-	+	_		5000			+	
	Î		Jone		1		<			1	1			(	<		<	1	5	Screeding in bathroom & utility ( • or ×)
			2		1	_	-		-  1		+		+	+			_	_	<u> </u> `	~ defility ( v or X)
			Place		1	1	1		1	1	)			1			<	)	5	Screeding in 6" above
			<u>e</u>	.	1/				Ľ	_			$\perp$						L	FFL? (v or x)