Quality Control Check Repot. Stage: After Plastering (Apartments)

| Flat No. | (n - 302) | Other | 1 | Sl. No. | 28760 |
|---|---|---|---|--------------------------|-----------|
| Company | VISTA HOWES | Project | VISTA HONG | Phase | |
| Prepared by | M. Teja Sindher | Sign | 1 | Date | 81/10/160 |
| Project Manager | 1. Madhu | Sign | 7 | Date | 81/10/60 |
| Previous stage report no. | no. | 2 28088 2 28088 | 2773 28088 Report filed and signed by PM? | d by PM? | √Xes □No |
| Checked By MD on | | MD Sign | | For filling | ☐Yes ☐No |
| Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth | Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required. | port to QC team. Proce ter submitting ATR on ing corrections pointed ired. | eed only after recheck by QC report to QC team. I out in the QC report. | by QC. ATR not required. | |

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed,
- before starting painting, tiling & flooring.

Plastering Check. Notes:

- Mark v for correct or minor mistake which does not require correction

 Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

| | Ren | 15 | 14 | 13 | 12 | 1 | 10 | 9 | ∞ | 7 | 6 | 5 | 4 | w | 2 | 1 | S No |
|-----|---------|-------|-------|---------|--------------------|---------------------|-------------------|---------|--------|---------|---------------------|----------------|---------------|----------------|---------------|----------------|---|
| 2 | Remarks | Other | Other | Kitchen | Utility/balcony-3- | Utility / balcony 2 | Utility≠balcony 1 | Lobby-1 | Dining | Drawing | Toilet 3 | Bedroom 3 (4b) | Toilet 2 (Cr) | Bedroom 2 (Ko) | Toilet 1 (MT) | Bedroom I (MB) | Room |
| | | | | < | 1 | 4 | < | | 1 | < | 1 | <u> </u> | < | ς | < | < | Skirting Provision (• or ×) |
| | Si . | | | < | 1 | < | < | 1 | 1 | ς | • | < | < | < | ۲ | < | Finishing around door frame (v or x) |
| | | ٠ | | < | 1 | 〈 | ς | ١ | 1 | < | - | ۷, | < | < | 5 | ς. | Beams & columns finishing (v or x) |
| | | | | < | 1 | } | } | 1 | [| 1 | į | Ţ | (| (| ſ | 1 | Finishing of lofts (v or x) |
| | | | | < | - | < | ſ | ١ | 1 | < | 1 | 1 | <u> </u> | < | \ | \ | Electrical junctions finishing (• or ×) |
| | | | | < | | ١ | ١ | 1 | 1 | } | 1 | < | < | < | < | < | Window check ⁶ (• or ×) |
| 2 | | | | < | 1 | < | 1 | Ì | 1 | 1 | i | [| < | 1 | < | 1 | Tiles provision (✓ or ×) |
| | | | | < | 1 | < | 1 | 1 | 1 | 1 | | ۷, | ٢ | < | < | ς | Sink provision & size (✓ or ×) |
| | | | | } | 1 | < | 1 | 1 | ١ | < | | ۷, | Y | \ | <u> </u> | < | Grooves for door frames (v or x) |
| u | | | | | - | į | | 1 | \ | 1 | - | 1 | 1 | 1 | 1 | ł | Balcony & terrace sill top finishing(v or x) |
| | | | | - | | - | 1 | 1 | 1 | } | - Campu | | ζ | | <u> </u> | 1 | Screeding in bathroom & utility (v or X) |
| ··· | | | | 1 | - | } | J | 1 | 1 | 1 | 1 | ١ | < | } | ζ | | Screeding in 6" above FFL? (v or x) |