## Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	8-711	Other	•	Sl. No.	4.97 to
Company	PHIR	Project	Porto	Phase	<del> -</del> ]
Prepared by	M Teja Svidher	Sign	A A	Date	41/10/12
Project Manager	K SHIRINA	Sign	3	Date	41/20/17
Previous stage report no.	10.	0626	Report filed and signed by	ed by PM?	Nyes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report  Stop further work. Proceed with work after s  Proceed with further work only after making.  Proceed with further work. ATR not required	Submit ATR on QC re Proceed with work af er work only after mak er work. ATR not requ	eport to QC team. Proceed ter submitting ATR on cing corrections pointedired.	ecommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	by QC. ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark v for correct or minor mistake which does not require correction

  Mark x for minor mistake that requires minor correction.

  Mark x for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- 98755432 Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".

  - Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Re	15	14	13	12	11	10	9	8	7	6	ک	4	ယ	2	1	S No
Remarks	Other	3 -	Kitchen	Utility/baleony 3	7	4080	Lobby-1	Dining	Drawing	Toilet 3	Bedroom 3. (46)	Toilet 2 (Cτ)	n 2	Toilet 1 (MT)	Bedroom 1 (MB)	Room
			<	100	1	<	ĺ	<b>\</b>	<	•	~	<	<	<b>V</b>	く	Skirting Provision ( v or x)
			ſ		<u> </u>	-	Ţ	1	<		~	<	<	4	<	Finishing around door frame ( v or X)
		3	<		<b>\</b>	<	ı	<	<	Ī	<	~	۷	<	<	Beams & columns finishing ( v or x)
			<	1	1	Ţ	Ţ	1	J	ĺ	ι	ſ	ı	-	1	Finishing of lofts ( • or ×)
			<		4	<	1	<	<	ļ	4	<	~	<	<	Electrical junctions finishing ( • or ×)
		8	<	(	I	1		1	1	1	<	<	<	<	<	Window check <sup>6</sup> ( • or ×)
			<	1	1	j	1	1	•	1	1	<	١	<b>Y</b>	]	Tiles provision ( • or ×)
		55.57	<	1	1	j	ı	ļ	1	[	l	<	1	<	١	Sink provision & size
		100	1	-	く	,	-	1	<	1	<u> </u>	۷	<	<	<b>〈</b>	Grooves for door frames ( ✓ or ×)
			1	ļ	1	1	[	1	J	Ţ	1	1	ſ	١	1	Balcony & terrace sill top finishing( v or x)
				1	<	-	-	1	,	Ì	\	<	١	<	j	Screeding in bathroom & utility ( • or ×)
			١	1	<	}	1	\	1		1.	\		<	}	Screeding in 6" above FFL? (v or x)