Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	Х ь ,,	Other		Sl. No.	BEERS B
Company BNC		Project	MEG	Phase	1
Prepared by Digon kings	2000	Sign	J. W.	Date	20110117
Project Manager Subba Reddy	يه دام ۲	Sign	roh	Date	4-13-10C
Previous stage report no.		25583	Report filed and signed by PM?	d by PM?	N Yes □ No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	TR on QC rewith work at lay after mal	eport to QC team. Proc fter submitting ATR or king corrections pointe	ceed only after recheck l a QC report to QC team ad out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.

 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1") All doors frames should have ½ grooves.

- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

N.G.	Tre G	15	14	13	12	=	10	9	∞	7	6	Ų,	4	ယ	2	_	S No
Nemarks	101/2	Other	Other	Kitchen	Utility/balcony 3	Utility / balcony 2	Utility / ba lcony 1	Lobby-1	Dining	Drawing	Toilet3	Bedroom-3	Toilet 2 CT	Bedroom 2 Cs	Toilet 1 MA	n 1	Room
				<	ſ	<	\	1	<	~	{		<	5	<		Skirting Provision (• or ×)
				1	{	1	5	1	1	<	ţ	1	7	5	<	<	Finishing around door frame (• or ×)
				<	,	<	<	ļ	<	5	1	1	<	/	\	<	Beams & columns finishing (• or ×)
				7	{	*	1	\	j	ſ	1	}	}	}	}	5	Finishing of lofts (v or x)
				74	1	<	<	١	<	\	(}	<u> </u>	5	<	<	Electrical junctions finishing (• or ×)
				<	J		1	\	i	<	(}	V	<	V	5	Window check ⁶ (✓ or X)
				11.	1	ſ	<	1	1	-	[)	V		7	J	Tiles provision (✓ or ×)
				<	1	1	<	}	<	(}	V	} '	V	1	Sink provision & size (• or ×)
				ļ	1	ſ	<	1	Ĭ	<	1	1	V	<	V	<	Grooves for door frames (• or ×)
	8			1	{	<	5	_	١	١	1		1		J	1	Balcony & terrace sill top finishing(• or ×)
				Í	1	1	<	}	,	}	1	Ĭ	<	١	<	1	Screeding in bathroom & utility (v or x)
				1	}	1	<	1	-)	\	}	\	1	<	1	Screeding in 6" above FFL? (• or ×)