Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.		no.	K-Shah Kin	P. Sai Kunn	2mr- !!	C-116
eport to QC team. Proc fter submitting ATR on king corrections pointe aired.	MD Sign	28783	Sign	Sign	Project	Other
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by PM?	113	P.Cdy	Pmr-13	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	✓ Yes □ No	22/12/17	41/11/14	F	28740

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Chcck,

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires corrected by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges

	Rei	15	14	13	12	11	10	9	æ	7					2	-		S No
	Remarks	Other	Other	Kitchen	Utility-/balcony 3	Utility / balcony 2	Utility / balcony 1		Dining	Drawing	Toilet 3	Bedroom-3	Toilet-2	Bedroom2	Toilet 1 (7		1 1	Room
				<	1	•	<	,	K	1	,	1	1)	<	\ \		Skirting Provision (• or ×)
				1	1	1	1	1		<	1	1	}	1	<		5	Finishing around door frame (v or X)
				<	-	1	<	1	K	K		1		j	<u> </u>			Beams & columns finishing (v or x)
				<	1)		,	1.			1		1			1	Finishing of lofts (• or ×)
			+	*)			1	3,	``	\	, ,	}	\		メ	Electrical junctions finishing (v or x)
				<	+	1 !			1	1		1	1	1	!		5	Window check ⁶ (✓ or ×)
	2			<		1	\	1	1		1		1	,)	<u> </u>	\ \	Tiles provision (✓ or 🗙)
				k		1	5	1				!	Ţ	1	{	<)	Sink provision & size
		-			Q () () ()	i	})	•	(<	•	١	1	1	<	<	Grooves for door frames (• or ×)
					١	1	1	<	•	1	1	!	١	1	ļ	1)	Balcony & terrace sill top finishing(v or x)
					(1	1	ſ		il.	1	1	,	}	<	, 1	Screeding in bathroom & utility (v or x)
					·	5	,	1	•	Ţ	1	1	1)	1	1	Screeding in 6" above FFL? (or x)

THE STATE OF THE S