Quality Control Check Repot. Stage: After Plastering (Apartments)

| Recommendation: |
|---|
| K-SHIRISH Sign 大し Date 2 29864 Report filed and signed by PM? MD Sign For filling |
| t no. |
| For filling |
| |

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proating, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

| Ren | 15 | 14 | 13 | 12 | 11 | 10 | 9 | ∞ | 7 | 6 | 5 | 4 | W | 2 | 1 | S No |
|------------------|-------|-------|---------|----------------------|---------------------|--------------------|---------|--------|---------|----------|------------|---------------|----------------|---------------|----------------|---|
| Remarks Wote, co | Other | Other | Kitchen | _Utility-/-balcony-3 | Utility / baleony-2 | Utility/ balcony 1 | Lobby-1 | Dining | Drawing | Toilet-3 | Bedroom 3- | Toilet 2 (CT) | Bedroom 2 (Kb) | Toilet 1 (Μτ) | Bedroom 1 (MB) | Room |
| Skitung | | | < | 1 | ~ | < | [| ١ | < | | I | \checkmark | ~ | く | < | Skirting Provision (• or ×) |
| | | | < | 1 | < | Specify. | | 1 | < | | ſ | 1 | < | <u>۲</u> | ς. | Finishing around door frame (• or ×) |
| hormon | | | < | 1 | <u>√</u> | ? | 1 | 1 | ζ | { | 1 | ✓ | < | < | ۲ | Beams & columns finishing (• or x) |
| 21 | | | < | (| (| } | 1 | \ | 1 | 1 | • | (| 1 | V | < | Finishing of lofts (• or ×) |
| 282 | | | < | (| < | < | 1 | 1 | < | (| | ~ | < | ~ | ς | Electrical junctions finishing (• or ×) |
| as | | | < | 1 | 1 | 1 | \ | \ | ς | 1 | ţ | <u> </u> | < | < | 5 | Window check ⁶ (• or ×) |
| Per | | | < | 1 | 1 | } | - | \ | 1 | (| 1 | < | } | ۲ | † | Tiles provision (• or ×) |
| Specif | | | < | 1 | (| j | ١ | 1 | 5 | 1 | ١ | < | 1 | < | 5 | Sink provision & size (✓ or 🗙) |
| rifications | | | | 1 | < | 1 | - | 1 | < | 1 | ļ | < | ς | ۲ | < | Grooves for door frames (v or X) |
| ٥ | | | 1 |] | 1 | ١ | 1 | 1 | 1 | l |) | 1. | 1 | J | 1 | Balcony & terrace sill top finishing(v or x) |
| | | | 1 | | < | ſ | 1 | |) | 1 |) | < | } | < | 1 | Screeding in bathroom & utility (v or x) |
| | | | | 1 | < |] | | | 1 | |) | < | | < | 1 | Screeding in 6" above FFL? (• or ×) |