## Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager   12 3 his	Prepared by S.Sur	Company Pwr-1	Flat No. C - 519
ATR on QC rewith work affuly after mak			12: shinh /cum Sign	S. Sund Kuma	ード	519
eport to QC team. Proceed ter submitting ATR on ting corrections pointed ired.	MD Sign	29120	Sign	Sign	Project	Other
eed only after recheck QC report to QC team d out in the QC report.		Report lifed and signed by	Ats.		WY -CI	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	Yes No	□Yes □No		19/03/18	\=)	29715

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.

  9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	15	14	13	12	1	10	9	∞	7	6	Ŋ	4	ယ	2	1	S No
Remarks	Other	Other	Kitchen	Utility/balcony-3	Utility/balcony-2	Utility/balcony 1	Lobby 1	Dining	Drawing	Foilet-3-	Bedroom-3	Toilet 2 CATO	Bedroom 2 & Bed	Toilet 1 M. Toi	Bedroom 1 Mages	Room
			ς.		ζ	7	1	!	5	ļ	)	(	ζ	(	ζ.	Skirting Provision
			<	1	(	ς .	٩	•	(	Į	1	(	(	(	۲	Finishing around door frame ( • or ×)
			<	1	(	(	1	j	(	1	١	(	3	(	(	Beams & columns finishing ( v or x)
		ļ	(	j	(	1	٩	•	١	•	4	١	}	1	>	Finishing of lofts
			(	1	<	<	١	1	<		•	(	ς	(	(	Electrical junctions finishing ( v or x)
		917	(	١	1	1	,	1	,	1	****	<	1	<	)	Window check <sup>6</sup>
			5	1	<	>		1	5	•		(	j	(	-	Tiles provision ( • or ×)
			.!	<b>.</b>	3	1	1	,	1	1	1	1	J	1	1	Sink provision & size
			1	•	<	ζ	1	1	(	1	1	3	ζ	(	, <	Grooves for door frames ( • or ×)
		0	1		<	(	1	9	1		1	١	١		1	Balcony & terrace sill top finishing( • or ×)
			١		<	, 1		1	1	1	-	1	1	1		Screeding in bathroon & utility ( • or ×)
			1	,	1	,	)	,	1	1	)	}	1	)	)	Screeding in 6" above FFL? ( v or x)