## Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	C-721	Other		Sl. No.	30431
Company	PMR	Project	AMR	Phase	<u>}=)</u>
Prepared by	M TcjaSidhu Sign	Sign	t d	Date	81/90/50
Project Manager	SHIRISH	Sign	122	Date	81/30/50
Previous stage report no.	no.	44368	Report filed and signed by PM?	d by PM?	√Xes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work  Stop further work  Proceed with furt  Proceed with furt	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	eport to QC team. Proc ter submitting ATR on king corrections pointe iired.	eed only after recheck of QC report to QC report of QC report.	by QC. ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

						T	T	10		Ι,		T		1.	Τ		
	Remarks	15				1	10	9	8	_		2					S No
Tokan .	arks	Other	Other	Kitchen	Litility_/_balcony_3_	Utility / balcony-2-	Litility-/balcony 1	Lebby-1-	Dining	Drawing	Toilet-3	Bedroom 3	Toilet 2 (ζτ)	2 1		n 1 (	Room
				<	1	<u> </u>	<	1	_	<	1	1	<	<	<	<	Skirting Provision ( • or ×)
				\	1	<	<	1	1	<	1	1	<u> </u>	<	Κ,	Κ.	Finishing around door frame ( • or ×)
			ä	<	1	<,	(	1	<	<	ſ	ſ	<	<	<	<	Beams & columns finishing ( • or ×)
				<		1	1	1	1	١	1	١	١	1	-	{	Finishing of lofts ( • or ×)
			•	<		<	<	1	く	5	{	١	<	<	<	<	Electrical junctions finishing ( v or x)
				<		<	<		١	<	1	1	4	<	<	<	Window check <sup>6</sup> (✓ or X)
			,	<	1	<	1	9	1	}	ļ	1	<	<	<	<	Tiles provision (✓ or X)
			-	<	Q.	<	•		1	1	1	)		1	<	•	Sink provision & size ( or x)
				١	1	<	}		1	<	1	)		<	<	<	Grooves for door frames ( • or ×)
				İ	1	1	1	1	1	1			١	)	1	J	Balcony & terrace sill top finishing( or x)
					i	4	)	1		ĵ	1		<	1	<	1	Screeding in bathroom & utility ( or x)
			/		)	<b>\</b>	]	}	]]		1		<	)	\	1	Screeding in 6" above FFL? ( ✓ or ×)