Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Abba Rody		Company BNC	1-204.	
IR on QC re vith work afi ly after mak IR not requ				M. Teja Svidhu Sign			
port to QC team. Proc ter submitting ATR on ing corrections pointed ired.	MD Sign	28050	Sign	Sign	Project	Other	
eed only after recheck l QC report to QC team d out in the QC report.		Report filed and signed by	7.86	1	P-JM-G	1	
by QC. ATR not required.	For filling	ed by PM?	Datc	Date	Phase	Sl. No.	
	☐Yes ☐No	☑Yes ☐No	41/03/05/	71/01/02		28310	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing. Mark **XXX** for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Re	15	14	13	12	1	10	9	∞	7	6	Ŋ	4	ယ	2	1	S No
Remarks	Other	Other	Kitchen	Utility / balcony 3	Utility / balcony-2	Utility / balcony 1	Lobby 1	Dining	Drawing	Feilet 3	Bedroom 3 (46)	Toilet 2 (CT)	n 2	Toilet 1 (WT)	Bedroom 1 (MB)	Room
			<		\	<	-	<	<		<u></u>	く	<u> </u>	<	<	Skirting Provision (v or x)
			1	1	<	*		.\.	<		<	く	\	<	<	Finishing around door frame (v or x)
			<	ļ	4	<	Ţ	<	<	1	<	<	<	<	<	Beams & columns finishing (• or ×)
			4	1	1	ļ	-	\	(1	(\	١	(1	Finishing of lofts (v or x)
			<	1	Ļ	<	-	く	7	ļ	۷	۷,	<	ζ.	<	Electrical junctions finishing (• or ×)
	N 10		<	1	1	ſ	1	{	1	Ţ	ا	<	く	〈	ς	Window check ⁶ (v or x)
			Х	ſ	<	1	-	1			1	<	1	<	1	Tiles provision (✓ or ×)
			<	•	-	1	1	1	1	-	\	<	\	<	1	Sink provision & size (v or x)
			{	[<	1	1	1	X	1	\	<	<u>\(\lambda \) \(\) \(\)</u>	<	<	Grooves for door frames (• or ×)
			1	Ţ	-		1	į	1	1	\	1	-		1	Balcony & terrace sill top finishing(v or x)
			1	•	\	1	1	١	1	ĺ	(<u>\</u>		<	l	Screeding in bathroom & utility (v or x)
			1	1	<	1	I	1	1		1	<	•	く	١	Screeding in 6" above FFL? (• or ×)