Quality Control Check Repot. Stage: After Plastering (Apartments)

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required	Checked By MID on	Charled Braker report no.	Previous stage Sub-			Company
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after submit ATR on QC report Proceed with further work only after making of the Proceed with further work. ATR not required.			Subba Reddy	M. Igasvidhur	BNC	D-802
port to QC team. Proce or submitting ATR on on the following corrections pointed red	MD Sign	8	Sign	Sign	Project	Other
ed only after recheck b QC report to QC team. out in the QC report. I		Report filed and signed by PM?	& Ciarbunet	94	ス元	Lancator
y QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	□Yes □No	NYes □No	4111100	41/11/68	f	28476

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment,
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check. Notes:

- Mark \checkmark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark $\times \times$ for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for tuppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ret	15	14	13	12.	11	10	9	∞	7	0	2	4	ယ	2	-	S No
Remarks	Other	Other	Kitchen	-Utility/balcony-3-	Utility / balcony-2	Utility√ balcony l	Lobby-	Dining	Drawing	-Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom l	Room
				deeny-3-	leony-2	lcony l				85.	(વહ)	(tt)	\sim		(MB)	
			<	ļ	<	5	}	<	<	1	<	<	۷.	۷,	<	Skirting Provision (• or ×)
			1	1	<	}	}	4	〈	1	<	く	~	<	く	Finishing around door frame (• or ×)
	327344794179479		<	1	<	<	1	۲,	<	Ţ	<u>ر</u>	<	<	く		Beams & columns finishing (v or x)
			<	l	1	}	1	1	1	1	(١	1	١	J	Finishing of lofts (• or ×)
			<	ì	<	<	١	4	<		4	<	<	<	<	Electrical junctions finishing (v or x)
			<	1	1	{	1	1	{	ſ	4	<	<	<	<	Window check ⁶ (✓ or X)
			<	ŧ	<	1	į	١	١	1	١	<	(<	1	Tiles provision (• or ×)
			<	(<	}	1	1	Ţ		١	<	1	<	5	Sink provision & size
				1	<	*	1	1	<	1	۷	<	<	<	<	Grooves for door frames (< or ×)
			1	1	1	ſ	1	1	1	1	1	(1	}	1	Balcony & terrace sill top finishing(• or ×)
					<	j	ſ	1	١	1	1	<		<	I	Screeding in bathroom & utility (• or ×)
				100 A	<	j	1	1	J	1	1	<	}	<	1	Screeding in 6" above FFL? (v or x)