Quality Control Check Repot. Stage: After Plastering (Apartments)

	x .				
Flat No.	E-205	Other		Sl. No.	29805
Company	BNC	Project	MFG	Phase	[=]
Prepared by	This Kimer	Sign	Pres,	Date	81/0/45
Project Manager S.W.		Sign	roll	8	8112/12
Previous stage report no.		28530	Report filed and signed by PM?		\\ Yes \ \ No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	nit ATR on QC reced with work af ork only after mak	port to QC team. Proceed the submitting ATR on the corrections pointed ired.	eed only after recheck b QC report to QC team. I out in the QC report. 2	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	I	_		Γ_	Г <u>.</u>	I	\ <u>\</u>	~	7	_		_	w	i		
em	_	14	13	2	11	10										S No
Remarks	Other	Other	Kitchen	Utility+balcony-3	Utility / balcony 2	Utility / balcony 1	Lobby 1	Dining	Drawing	Toilet-3	Bedroom 3 GB	Toilet 2 (つ)	n 2	Toilet 1 トリイイ	Bedroom 1 MB	Room
			<	١	<	\ \ \	1	<	<)	V	V	<	V	<u> </u>	Skirting Provision (• or ×)
			j	})	\	1)	<	1		<	~	V	<	Finishing around door frame (v or x)
			<	}	ς.	ς,	1	<	<	5	<	1	\ 	V	<u> </u>	Beams & columns finishing (• or ×)
			ζ.	1	1)		1	1	1		•		•	į	Finishing of lofts (v or x)
			7.	,	\	<u> </u>	,	<	<	١	X	ζ.	<	X	X	Electrical junctions finishing (v or x)
			ζ.	4	í	1	1	1	1	ſ	<	<u> </u>	<	<	<	Window check ⁶ (✓ or ×)
			7	1	}	Υ.	j	1	3	1	1	\	-	<	1	Tiles provision (• or ×)
			<u> </u>		}	<)	ζ.	1)	1	V	J	?	[Sink provision & size
			1		(<	1	· Aver-make	7	1	1	V		<		Grooves for door frames (v or x)
			1	-	<	1	1	1	-	1	}	1	\	**	J	Balcony & terrace sill top finishing(v or x)
			1	1	1	<	1	1)	1	1	<,	· ·	<		Screeding in bathroom & utility (v or x)
				4	1	<	1	1	١	1	١	<_	1	<		Screeding in 6" above FFL? (or x)