Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required.	Checked By MD on	Previous stage report no	Project Manager	Prepared by	Company	Flat No.
Submit ATR on QC re Proceed with work af er work only after mak er work. ATR not requ		no.	S. V. Subba Really	P. Si Kuna Sign	BNC	50C-3
eport to QC team. Proceed ter submitting ATR on the corrections pointe tired.	MD Sign	41488	Sign	Sign	Project	Other
scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?	7886	J. S. T.	MFG	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	Nes No	27/3/18	27/2/18	F	29811

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ker	7	15	14	13	12	11	10	9	%	7	6	5	4	3	2		S No
Kemarks	ma+l/a	Other	Other	Kitchen	Jtility/balcony-3-	Utility / balcony 2	Utility / balcony 1	-Lobby-1-	Dining	Drawing	Toilet-3	n 3 (_	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1 (MB)	Room
				V	-	V	<u> </u>	1	V	✓	ļ	\	1	1	٧.	ζ,	Skirting Provision (• or ×)
				(١	and a	~		1	<	1	~		<	<	<	Finishing around door frame (v or x)
				V	1	<,	V	-	\checkmark	<		~	1	<		ζ.	Beams & columns finishing (v or x)
				<	١	\	3	ŀ		1	-	_]	-	(Finishing of lofts (• or ×)
				く	١	<	<	1	<_	<	١	~		<u> </u>	ζ,	<,	Electrical junctions finishing (v or x)
				<,	1	Š.	-	1	.,,,,,,,,	(1	<	<	<	く	く	Window check ⁶ (✓ or X)
				7	1	Ì	<		1			April 100 and	<	Property	<		Tiles provision (✓ or ×)
				<	-		<	\ 		l		1	<	general	<		Sink provision & size
				ţ	{	1	<		•	<]	<	<	\	<	~	Grooves for door frames (v or x)
				1	١	<	1	1	1	7	Ī	Mary or compa	>	5	ļ	area.	Balcony & terrace sill top finishing(v or x)
				1	877	}	<			}	1	į	7	1	7)	Screeding in bathroom & utility (v or x)
				\	1)	<		1	1		1	7	1	<	}	Screeding in 6" above FFL? (v or x)