## Quality Control Check Repot. Stage: After Plastering (Apartments)

Company  Com						•
	Flat No.	Freed	Other	•	SI. No.	8708
	Company	)	Project	くらか ナラかり	Phase	
		S. Sund time	Sign	· - )C	Date	01/03/19
			Sign	7 while		01/03/10
	Previous stage report	no.	20x68	Report filed and signe		DYes DNo
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on		MD Sign		For filling	Yes No
Proceed with further work. ATR not required.	Recommendation:  Stop further work.  Stop further work.  Proceed with furth  Proceed with furth	Submit ATR on QC rep Proceed with work after or work only after making work. ATR not requi	port to QC team. Procer submitting ATR on ing corrections pointed red.	eed only after recheck b QC report to QC team. I out in the QC report. I	y QC.  ATR not required.	

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment,
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark for correct or minor mistake which does not require correction
- Mark  $\times$  for minor mistake that requires minor correction. Mark  $\times$  for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for happum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

<del> </del>   <del> </del>   <del> </del>   <del> </del>		<u>-</u>	14	13	12		10	9	×	7	6	S	4	ယ	2		S No
Remarks	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Other	Other	Kitchen	Utility/balcony3—	Utility/ balcony 2-	Litility/balcony l	Lobby I	Dining	Drawing	Toilet 3—	Bedroom-3>	Toilet 2 Cotol	Bedroom 2 Arbed		Bedroom 1 M. Bed	Room
				(	-	ζ	(	1	9	ς	1	1	ς	(	ζ	7	Skirting Provision ( v or x)
				(	-	5	Ţ	Į.	,	<	١	!	ς	(	<	٢	Finishing around door frame ( v or x)
				~		ζ	ζ,	II.	ز	ζ		ļ	ζ	<	(	Ţ	Beams & columns finishing ( • or ×)
			•	ζ	1	}	•	ı	ļ	1	١	ļ	1	1	}	}	Finishing of lofts ( v or x)
				ζ	1	ζ	L	ř	く	ζ	1	١	<	ζ	ζ	ζ	Electrical junctions finishing ( v or x)
				(	1	}	}		1	ţ	ļ	1	×	1	X	1	Window check <sup>6</sup> . (✓ or ×)
				X	1	ζ	9	44	;	· ·		,	<		<	1	Tiles provision ( or x)
			```	X		)	)	1	1	. !	1	t	1	,	1	1	Sink provision & size
				1		ζ		1	,	١	1	1	2	<	<	ζ	Grooves for door frames (✓ or ×)
			•	1		<	ζ	,		1	1	1	1	)	i	1	Balcony & terrace sill top finishing( v or x)
		8			-	ζ	-	1	1	· · 1		1	ζ	1	ζ	1	Screeding in bathroom & utility ( • or ×)
				)	}	<	١		j	   } 	)	1	<	,	K	5	Screeding in 6" above FFL? ( • or ×)

Quality Control Check Repot.

Stage: After Plastering (Apartments)