Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| Bungalow no. | 28 | Stage | | Sl. No. | 33 411 |
|---|--|--|---|--------------------------|----------|
| Company | Sov (TTD) | Project | Sov | Phase | X |
| Prepared by | | Sign | J. Sakath | Date | 16/04/19 |
| Project Manager | K. Puseholham | Sign | P | Date | 16/04/19 |
| Previous stage report no. | no. | 33040 | Report filed and signed by PM? | d by PM? | Yes No |
| Additions & alterations sheet date | 18 sheet date | 26/5/18 | All pages signed by engineer & customer? | | ✓Yes □No |
| Checked By MD on | | MD Sign | | For filling | ☐Yes ☐No |
| Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth | Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. | port to QC team. Proceed the submitting ATR on the submitting the submittens pointed ired. | eed only after recheck by QC report to QC team. I out in the QC report. | y QC. ATR not required. | |
| Inspection should be done after: | after: | | 8 8 8 8 8 | | |

- after cleaning the bungalow.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).

 additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| No | | | A married formed described office of the ched | λ | Vec Nin | | Revised drawing required from HO | | j |
|---------------------------------------|--|---|---|-----------------------------------|------------------|--|----------------------------------|---------------------|------|
| | ✓ Yes | | Signed by customer, | Signe | ✓ Yes □ No | أأوا | icer, | Signed by engineer, | Sign |
| | | | | | | Remarks on additions & alteration sheet: | litions & al | narks on add | Ren |
| | | | 8 0 | | 3 | | | | |
| | | | | | | | | Remarks | Ren |
| | | | | | | | | Other | 19 |
| #Dimp | | Ł | | < | * | سلمعين | | Utility | 18 |
| 1 | | ٠ | 1 | × | X | • | | Kitchen | 17 |
| 1 | | 1 | 1 | \ | 1 | ì | | Portico | 16 |
| 1 | | - | | ~ | ¥- | ١ | | Head room | 15 |
| 1 | | 1 | 1 | 1 | 1 | 1 | deeny-2 | Terrace/balcony-2 | 14 |
| 1 | | • | く | **** | | - | alcony-l | Terrace / balcony-l | 13 |
| 1 | | 1 | Ţ | 1 | - | ٩ | | Labby 2 | 12 |
| 1 | | • | 1 | 1 | 1 | 1 | | Lobby-1 | 11 |
| 1 | | - | ١ | < | - | | | Dining | 10 |
| 4 | | | 1 | ٧ | P | • | | Drawing | 9 |
| | 1 | | ١ | • | 1 | 1 | | Teilet 4- | 8 |
| • | 1 | 1 | 1 | 1 | 1 | - | 1 | Bedroom 4 | 7 |
| | ħ | 1 | 1 | 1 | Ļ | 1 | | Toilet 3- | 6 |
| 1 | ١ | - | • | 1 | ţ | , | | Bedroom-3 | 5 |
| 1 | | ١ | 1 | < | × | ١ | C1 | Toilet 2 | 4 |
| 1 | | 1 | 1 | < |) | 1 | 、大は | Bedroom 2 | 3 |
| 1 | | 1 | 1 | \ | × | 1 | 37 | Toilet 1 | 2 |
| 1 | Annual Cold (April) | } | | × | - | 1 | 70 | Bedroom 1 | 1 |
| or x) Generator changeover (• or x) | Placement of DB (\checkmark or \times) | Proper use of fasteners check (• or ×) | Water proofing check (• or ×) | Electrical points check (• or ×) | CPVC & PVC Check | Civil work near pipes in balcony & utility (• or ×) | | Room | S No |

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| Miscellaneous check | |
|--|----------------------|
| Depth of drainage line at compound wall specified: | Depth provided: 1-q" |
| Fastners for external PVC/CPVC lines (or x) | < |
| Setbacks properly leveled and compacted to 3" below proposed FFL? | √Yes □No |
| Lawn area property leveled and compacted to 9" below lawn FFL? | ্ৰYes □No |
| Electrical pipes for electric power supply & communication provided from | √Yes □No |
| compound wall? | |
| Workmanship of drainage lines | Good V Avg. Poor |
| Earthing provided? | ✓ Ycs |
| | |
| Remarks: | |
| | |
| | |
| | |