Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| Bungalow no. | 25 | Stage | | SI. No. | 33374 |
|---|--|--|---|--|------------|
| Company | מסכ (ננף) | Project | vac | Phase | - |
| Prepared by | S. Kulder | Sign | Anders- | Date | 10-04-19 |
| Project Manager | A Sueson | Sign | É | Date | 10-04-19 |
| Previous stage report no. | no. | 35558 | Report filed and signed by PM? | d by PM? | ✓Yes □No |
| Additions & alterations sheet date | ns sheet date | 39398 24 8 18 | All pages signed by er | engineer & customer? | Yes No |
| Checked By MD on | | MD Sign | | For filling | ☐ Yes ☐ No |
| Recommendation: Stop further work. Su Stop further work. Proceed with further Proceed with further | Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required. | eport to QC team. Proce ter submitting ATR on cing corrections pointed iired. | eed only after recheck bed only after recheck bed only after recheck bed only after report. 2 | k by QC. m. t. ATR not required. | |

Inspection should be done after:

- after cleaning the bungalow.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- . Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 0. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| |]Yes □No - | | Approved revised drawing attached | Appro |]Yes ☑No | from HO | required t | Revised drawing required from HO | Rev |
|------------------------|---------------------------|-------------------------|-----------------------------------|-------------------------|------------|--|----------------|----------------------------------|------|
| | Yes No | ĸ | Signed by customer, | Signed | ☐Yes ☐No | C | er, | Signed by engineer, | Sign |
| | | | | | | Remarks on additions & alteration sheet: | tions & al | narks on addi | Ren |
| | | | | , (| 100 | | | | |
| | | | bale n | 84 50 50 | want to be | × . ciwil | . @440A | Remarks | Ren |
| | | | | | | | | Other | 19 |
| 1 | • | 1 | 1- | 1 | ζ. | ţ | | Utility | 18 |
| ١ | Ţ | 1 | 1 | < | ζ. | Brusser | | Kitchen | 17 |
| 1 | ! | 1 | 1 | ļ | 1 | | | Portico | 16 |
| Ī | 1 | 1 | Ţ | ζ. | (| 1 | | Head room | 15 |
| ſ | 1 | ς . | 7 | [| < | | leony 2 | Terrace/baleony 2 | 14 |
| 1 | | 1 | - | (| \ | X | dcony 1 | Terrace / balcony l | 13 |
| 1 | | 1 | - | 1 | | 1 | | Lebby 2 | 12 |
| 1 | 1 | 1 | | 1 | Ĺ | 1 | | Lobby 1 | |
| ı (| • | ı | 1 | ζ. | • | (. | | Dining | 10 |
| | | Ţ | 1 | (| 1 | 1 | MEST DISTURBED | Drawing | 9 |
| 1 | | — : | 1 | 1 | 1 | 1 | | Toilet 4 | ∞ |
| 1 | 1 | ı | • | | | ſ | | Bedroom 4 | 7 |
| ١ | 1 | (| (| ζ | ζ | ţ | <u>-</u> 1 | Toilet 3 | 6 |
| 1 | , | , |) | , | 1 | 1 | લંક | Bedroom 3 | Ŋ |
| 1 | 1 | | , | ′ | ζ | (| 1.7 | Toilet 2 | 4 |
| 1 | 1 | | 1 | , | ! | - | B:3 | Bedroom 2 | ψ |
| 1 | 1 | 1 | < | 7 | 7 | 1 | m-1 | Toilet 1 | 2 |
| 1 | (| 1 | 1 | , | | 1 | & 3 | Bedroom 1 | _ |
| changeover (~ or ×) | | check (✓ or ×) | (vor x) | (v or x) | (• or ×) | balcony & utility (• or ×) | | Room | S No |
| Placement of Generator | Placement of DB (v or x) | Proper use of fasteners | Water proofing check | Electrical points check | PVC Check | Civil work near pipes in | | ****** | |
| | | | | - | | | | |] |

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

| Earthing provided? Remarks: | Electrical pipes for compound wall? | Setbacks properl | Depth of draina Fastners for ext | Miscellaneous check |
|------------------------------|---|---|---|---------------------|
| Earthing provided? Remarks: | Electrical pipes for electric power supply & communication provided from compound wall? | Setbacks properly leveled and compacted to 3" below proposed FFL? Lawn area property leveled and compacted to 9" below lawn FFL? | e at compound wall specified: PVC/CPVC lines (or x) | ls check |
| | | | 12611 | |
| Yes No | ☐ Good ☐ Aver ☐ Poor | | Depth provided: 116" | |