Bungalow no. 56	Stage	-1	SI. No.	34940
Company Sov (llp)	Project	Sov	Phase	X
Prepared by G.RAJESH	H Sign	M	Date	01/2/10
Project Manager K. Duys hotham	Sign	X	Date	19 19
Previous stage report no.	33082	Report filed and signed by PM?	ed by PM?	Yes No
Additions & alterations sheet date	22 01 19	All pages signed by er	All pages signed by engineer & customer? Yes No	Yes No
Checked By MD on	MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Oreport to QC team. Prork after submitting ATR of making corrections point required.	cccd only after recheck but QC report to QC team.	by QC. ATR not required.	

inspection should be done after:

- after cleaning the bungalow.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II onty).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

ivoles:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark **X** for minor mistake that requires minor correction.
- Mark × x for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- 9. Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 0. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

	Civil work near pipes in	CPVC & PVC Check	Bleetrical points check	Water	Proper use of	Placement of	Placement of
S No Room	balcony & utility (• or ×)	(• or x)	(• or ×)	(• or ×)	check (or	(• OI ×)	changeover (• or ×)
1 Bedroom 1 M. B		1	1				
2 Toilet 1 M. T		<	\			1	
n 2	1	1	, (<	<	9	
4 Toilet 2 KT	\	,			7	Distance of	gramma en l'en en
n 3	Camera	, ,		*	<	Grands had	j
		. !					i i
Bedroom-4	El Caracter de la Car	<.	٠.	- delication of the second	ξ.	¢	1
8 Feilet 4			· `.				d'alian
9 Drawing			· ·	5			
10 Dining		The state of the s	,			<	<
11 Lobby 1 HALL				And the second second	•		
		1		P. 1977	1	6	,
13 Terrace/ balcony 1	5		4		,		3
14 Ferrace/balcony 2		?			<	67,	
15 Head room	•		· \		. \	3	1
16 Portico	1		! <	E complete	<	(See State	9
17 Kitchen	Carried		7		* Alman	3	E
18 Utility				enser.	<		1
		<	<	Barrier and a	<	a man	Management of the state of the
Remarks							
Remarks on additions & alteration sheet:	eration sheet:						
Signed by engineer,	S	Yes No	Signed b	Signed by customer,	VYes	Zes No	
Revised drawing required from HO		Yes VNo	Approve	Approved revised drawing attached			
						-	

Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

Remarks: pass painting was (ustrage Scope	Workmanship of drainage lines Earthing provided?	Lawn area property leveled and compacted to 9" below lawn FFL? Electrical pipes for electric power supply & communication provided from compound wall?	Setbacks properly leveled and compacted to 3" below proposed 1311"	Miscellaneous check Depth of drainage line at compound wall specified:
	☐ Good ☑ Avg. ☐ Poor ☑ Yes ☐ No	Yes No		Depth provided: 1114