- 1	Juality
	Contro
	of Check Renot.
Supposed Cu	Stage Refore
Chora Zirren	Casting Slah
(CPITTA)	

Stop further work. Stop further work. Proceed with furthe Proceed with furthe	Paccaman dation	Fievious stage report no.	rioject Manager	Project N	Prency	BIOCK NO
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck less top further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		0. 33427	A. Purs hothour	T. Vimod Kumay	SOV(LLP)	28
QC team. Pr mitting ATR rections poin	MD Sign		Sign	Sign	Project	Slab No.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?	Ń	Trung human	Sov	. 02
not required.	For filling	19	Date	Date	Phase	SI. No.
	☐Yes ☐No	√Yes □No	08/05/19	98 05 119	X	33.550

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been canted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension

Slab Dimensions Check Plan enclosed?	ed?	Yes No	id Alendon actual dimension next to It.	0 It.
Staircase - mid landing1	Specified ht: $4'-5''$ Actual ht: $4'-5''$	Actual ht: 4'_5''	Within tolerance of ½"?	Yes No
Staircase - mid landing 2	Specified ht: μ'_{-5} "	Actual ht: 4'-52"	Within tolerance of 1/2"?	Yes No
Staircase width	Specified wd: 6'-6"	Actual wd: 6'-6"	Within tolerance of 1/2"?	Yes No
Staircase slab thickness	Specified: 5"	Actual: 5"	Within tolerance of 1/4"?	□Yes □No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided?	☐Yes ☐No
Quality of Bracing Provided?	☐Good ☐ Avg. ☐ Bad
Alignment of beams on outer side?	Good Avg. Bad
Shuttering leveling?	☐Good ☐ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐Correct ☐ Needs correction
Remarks:	
	The state of the s

Slab Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing.

 Mark x x for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

				Remarks:
	☐ Good ☐ Avg. ☐ Bad —		Steel check - slab extensions/ joints	16.
	☐Good ☐ Avg. ☐ Bad —		Steel check - floating columns	15.
	Good ☐ Avg. ☐ Bad	7	Electrical Conducting	14.
400	☐ Good ☑ Avg. ☐ Bad	<	Steel Check - Column steel overlapping length and cranking	13.
	☑ Good ☐ Avg. ☐ Bad	<	Covering blocks for slab	12.
	☑ Good ☐ Avg. ☐ Bad	<	Steel Check - Slab Extra Bars	11.
	☐ Good ☑ Avg. ☐ Bad	<	Steel Check - Slab cranking & chairs	10.
	☑ Good ☐ Avg. ☐ Bad		Steel Check - Slab spacing of bars	9.
	☐Good ☐ Avg. ☐ Bad	5	Steel Check - Slab size of bars	8.
	☐Good ☐ Avg. ☐ Bad	<	Depth and width of beams	7.
**************************************	☐ Good ☐ Avg. ☐ Bad		Covering blocks for beams	6.
	☐ Good Avg. ☐ Bad		Steel Check - Beams Bearing	5.
	☐ Good [Avg. ☐ Bad	<	Steel Check - Beams Overlapping & Cranking	4.
	☐Good ☐ Avg. ☐ Bad	<	Steel Check - Beams Extra Bars	3.
4 (((((((((((((((((((☑ Good ☐ Avg. ☐ Bad	<	Steel Check - Beam size of bars	2.
	Good ☐ Avg. ☐ Bad	<	Steel Check - Beam no of rods	_
	Qualitative Check (Good / Avg. / Bad)	Quantitative Check (• or ×)	Item	S No
	A. Carrier and C. Car			