### Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

Bungalow no.	24	Stage	()	SI. No.	34088
Company	VOC (LLP)	Project	V0 €	Phase	•
Prepared by	a. RAJES #	Sign	A Section of the sect	Date	27/03/19
Project Manager	A. SURESIA	Sign	Ç	Date	27/63/19
Previous stage report no.	no.	33792	Report filed and signed by PM?	d by PM?	Yes No
Additions & alterations sheet date	ns sheet date		All pages signed by engineer & customer?		☑Yes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:  Stop further work. Sub Stop further work. Pro Proceed with further w Proceed with further w	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proce ter submitting ATR on ing corrections pointed ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.	y QC.	

- after cleaning the bungalow.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

### After Plumbing & Electrical Check

### Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD

# Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

gage al	_Yes □No	ving attached   L	Approved revised drawing attached	Appr	]Yes √No	from HO	Revised drawing required from HO	Revised
,	Yes   No		Signed by customer,	Signe	✓ Yes □No		Signed by engineer,	Signed b
	1					alteration sheet:	Remarks on additions & alteration sheet:	Remarks
rastered	wasnot	P.J.inth Beam	below 6" PJ	way!	external	Villa C	<b>9</b> 0	
CONF	707	iks are	C	PVC	External	1. VILLA E	NO/06	Remarks
	to.						er	19 Other
1	- Paris	<	\	- Career of	<	<	ity	18 Utility
1 9	9	\	1	<	<		Kitchen	17 Kito
Table to the	-	Same.	1	0	Action 2000		Portico	16 Por
9	1	<	1	<.	1	- نامون بي	Head room	15 Hea
1	Barre	1	CHOST	1	geo.	مناشان	Terrace/balcony-2	14 Ter
İ	3	<	1	<	<,	×	Terrace / balcony 1	
7	1		California	granus -	grania.	page 1823	Lobby 2	12 Lob
Contraction of the Contraction o	Confinence		1	<	\$11,\$22.60m		Labby-1 12, L	11 Lob
		1	-	1	g and a second		ing	10 Dining
	<	Carrena establishment of the carrena establis	Based (i) Comme	5	) James and State of the State		Drawing	9 Dra
1	0	Service Servic	0.000		Chapter	\	et 4	8 Foilet 4
	1				Clarin	7	n-4	7 Bed
- September - Sept	1/3/aram	<	<	1	<	-	Toilet 3 K.T	6 Toil
		- American	e) cross	~		Sec. of same	n 3	5 Bed
American Services	Stanmen	•	1		<	<u> </u>		
	1		Canada de la casa de l	<u> </u>	CALL COMPANY.	-	Bedroom 2 4.6	
	Charles	<.	<	<	<	ensonerd <sup>C2</sup>		2 Toilet
9	P. C. State			,			Bedroom 1 M.B	1 Bed
( • or ×)		×		(4 25 %)	(	utility ( • or ×)		S No Room
Generator changeover	DB (v or x)	fasteners check ( • or	proofing check	points check	PVC Check	near pipes in		
Placement of	Placement of	Proper use of	Water	Electrical	CDV/C &	2		

# Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

Remarks:	Earthing provided?	Workmanship of drainage lines	Electrical pipes for electric power supply & communication provided from	Lawn area property leveled and compacted to 9" below lawn FFL?	Fastners for external PVC/CPVC lines ( or x)  1. Landad and compacted to 3" below proposed FFL?	ed:
		Good Wavg. Poor	Yes No	Yes WNo	VYes □No	16" Depth provided: 116"