Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.	on MD Sign	Previous stage report no. 3473 Report filed and signed by PM?	Project Manager Gr-Sichesh Sign Gif- Date	J. Samphath Sign	Company Nilsky (Stale) Project Nilsky (Stale) Phase	Villa No. 176 Stage 又只了为了人 SI. No
eck by QC. eam. ort. ATR not required.	For filling Yes No	V			Phase	SI. No. 71. 97.0

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark \checkmark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18		16	15	14	13	12	11	10	9	×	7	6	S	4	. w	2	-	S No
Remarks	Other	Utility	Kıtchen	Portico	Head room	Terrace/ balcony 2	Terrace / balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Torlet 4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	
			an / mare	i	1	1	1	27					D. T. L.	Ì	(capacitation)		line -	COMME	}	Skirting Provision
			Constant	ì	j	() and	3	- Constant		1	1	1	3	1	-	1		-	Ì	Finishing around door frame (• or ×)
			1	1	ì	1 2 2	ì	1	1	ì		i			1	سمسوني ۽		na-	•	Beams & columns finishing (v or x)
-			ì	1	4		3		1	5	ì	1	* ****		j		1		, ,	Finishing of lofts (• or ×)
			ì	1	,)	0.00	ì	ì	ì	ī)	1	i	1	Ç	12			Electrical junctions finishing (v or x)
			1)	1	1	1	i	a a		1	U/****	ì	1	1					Window check (• or ×)
			7	}	1	1	1	ì	1			ì			Ì					Tiles provision (• or ×)
			1	i.	7	7	7		1]]		, ,) 1	, , ,					Sink provision & size (• or ×)
			60			(E-1)	Î	1 1		j		, and design			1		j			Grooves for door frames (v or x)
		Cr. year))	j	ŝ,	; }	Ì		1	diam'			10.00	1		T Ame		Balcony & terrace sill top finishing ¹⁰ (✓ or ×)
		1				1		9-1	٦	3	ì				}			1		Screeding in bathroom & utility (• or ×)
		C.Proce		0 1					шж	Ļ))		ļ) com	F	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars (• or ×)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	√ Yes No
Plastering quality of parapet walls (or x)	
Plastering and finishing of chajjas (✓ or 🗙)	
Remarks:	4