## Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

				2	
Bungalow no.	力	Stage		SI. No.	33265
Company	C 0x (118)	Project	Sev	Phase	X
Prepared by		Sign	J. Bakella	Date	27/03/19
Project Manager	3	Sign	40	Date	1 80/52
Previous stage report no.		33029	Report filed and signed by PM?	d by PM?	Yes No
Additions & alterations sheet date	sheet date	22 /06/18	All pages signed by engineer & customer?   Yes   No	igineer & customer?	✓ Yes □ No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	ubmit ATR on QC re Proceed with work aft work only after mak work. ATR not requ	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.	ATR not required.	

Inspection should be done after:

- after cleaning the bungalow.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

### After Plumbing & Electrical Check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1"
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

# Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

	Yes No.	ing attached	Approved revised drawing attached	Appro	∏Yes ☑No	10 10 10 10 10 10 10 10 10 10 10 10 10 1	Revised drawing required from HO	Revi
	Yes No		Signed by customer,	Signe	Yes No		Signed by engineer,	Signe
						Iteration sheet:	Remarks on additions & alteration sheet:	Rema
	walls.	Extermal	at villa	mt dare	Pipes	Faching for	No Hole	Remarks
							Other	19
7	p. w.	<	1		۷.	X	Utility	18
1		7			۷	•	Kitchen	17
1	E Part	-	****	<	1		Portico	16
7	di energia	,	1	<	ÿ	3	Head room	15
-	I	1	a continue		<b>6</b> 77 st	•	Terrace/ balcony 2	14
)		*	2	1	1		Terrace / baleony-1	13
)	, , , , , , , , , , , , , , , , , , , ,	١	1	)	1	,	Lobby 2	12
)	}		1	1	1	Ì	Lobby 1	11
9	27-04-0	)	,	V	•	. —	Dining	10
<	<	ì	-	ζ	1	,	Drawing	9
<b>*</b>	in the control of the	1	g 2 January Printers .	-			Toilet 4	8
		1	1	7		<b>+</b> :	Bedroom 4	7
)	2700-	- Park	Ì	,	1		Toilet 3	6
	AT	1	}	-	1	*	Bedroom 3	5
1	1	1	١	J'	×	Al Regio	Toilet 2 C. To:	4
, present	1	]	1	ζ.		•	Bedroom 2 K.B	သ
1	1	1	1	V	×	١	Toilet 1 M-Tol	2
٦	1	L. Spermer	1	~	4. 1	E-man.	Bedroom 1 📉 😘	1
Placement of Generator changeover ( • or *)	Placement of DB ( • or ×)	Proper use of fasteners check ( • or ×)	Water proofing check ( • or ×)	Electrical points check	CPVC & PVC Check ( • or ×)	Civil work near pipes in balcony & utility ( • or ×)	Room	S No

## Quality Control Check Repot. Stage: After Plumbing & Electrical (Villas)

ı i	١-
ч	.<
1	Ξ
i	V.
П	C
١.	Œ
1	
. 1	0
'	
ij	
	Ö
.	~
1	6
1	Miscellaneous check
1	$\mathbf{c}$
1	S
1	Œ
1	C
١	7
١	
١	
1	
١	
1	
- 3	

	Remarks:	Earthing provided?	Workmanship of drainage lines	electrical pipes for electric power supply & communication provided from compound wall?	Lawn area property leveled and compacted to 9" below lawn FFL?	Setbacks properly leveled and compacted to 3" below proposed FFL?	Fastners for external PVC/CPVC lines ( or x)	ed:
		Yes No	Good Avg. Poor	Yes No	Yes WNo	Yes No	AJS	Depth provided: 1-9"