Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required		no.	Subba Reddy	M. Teja Svidhur Sign	BN C	0-963
eport to QC team. Proc fter submitting ATR or king corrections pointe nired.	MD Sign	2828	Sign	Sign	Project	Other
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.		Report filed and signed by PM'	& Ciantemy!	4	MFG	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	Yes No	41/1/160	09/12/17	T	28616

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

				1			9	%	7	6	(n)	4	رب ا	2		
Remarks	15	14	13	12	二	10		300000		3801107500						S No
arks	Other	Other	Kitchen	Utility/-balcony-3-	Utility / balcony-2	Utility/balcony 1	Lebby+	Dining	Drawing	Toilet-3	Bedroom 3(46)	Toilet 2 (CF)	Bedroom 2 (KB)	Toilet 1 (ヤイ)	Bedroom 1 (MB)	Room
			<	1	~	\ \]	<	く		く	<	く	V	<	Skirting Provision (v or x)
				-	~	<	-		<		<u> </u>	く	<	<	<	Finishing around door frame (• or ×)
			<	-	\	<	1	<	\checkmark	1	4	イ	<u> </u>	<	<	Beams & columns finishing (✓ or 🗙)
			<		1	ļ	1	1	1	1	\	(١	1	1	Finishing of lofts (v or x)
			<	ţ	~	<	1	<	<	1	<	<	<	<	<	Electrical junctions finishing (• or ×)
			<	(l	ſ	1		1	1	<	<	<	<	5	Window check ⁶ (✓ or ×)
			2	1	<	1	į		(1	ı	<	1	<	}	Tiles provision (✓ or ×)
			1	ļ	ſ	1	1	{	[1	1	<	-	<	j	Sink provision & size
				\	<	1		-	<	١	<	<	<	<	<	Grooves for door frames (v or x)
			1	1	\	1	1	1	-	1	1	1]	1	1	Balcony & terrace sill top finishing(v or x)
				-	<)	1	1	1	1	1	<	1	<	1	Screeding in bathroom & utility (• or ×)
				-	<	1		[1	1	1	<	1	<	•	Screeding in 6" above FFL? (v or x)