## Quality Control Check Repot. Stage: After Plastering (Apartments)

G-208	7 Outer	Si. 190.	28600
Company Vistor Holmes	Project	Nista Howas Phase	)
Prepared by S-Sinnel Xiwas	NG Sign	Date	07/18/17
Project Manager 7- Moofile.	Sign	Date Date	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Previous stage report no.	SDFLE	Report filed and signed by PM?	Yes No
Checked By MD on	MD Sign	For filling	□Yes □No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck less further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	QC report to QC team. Prork after submitting ATR remaking corrections point required.	oceed only after recheck by QC, on QC report to QC team. ted out in the QC report. ATR not required.	iired.

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

## Plastering Check.

## Notes:

- Mark  $\vee$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times$  for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Ren	15	14	13	12	11	10	9	8	7	6	S	4	ယ	2	1	S No
	Remarks (1) Goton es	Other	Other	Kitchen	Whility—balcony-3	Utility / baleony-2-	Utility/balcony 1	Lobby-1	Dining	Drawing	Foilet-3	n 3 G	$\sim$	n 2	Toilet 1 M. Toi	Bedroom 1 M. Bed	Room
	する			ς.	•	<	>		ζ	5	1	ζ	ς	ς.	ς.	(	Skirting Provision ( v or x)
1 1 1 1	10 Stay 2			ς.	•	ζ	(		ζ	ς.	1	ζ	ς.	٢	<	ς.	Finishing around door frame ( • or ×)
	Town S			٢	1	ς	ς.	Ţ	<	ς.	1	ζ	<	ς	<	ς.	Beams & columns finishing (✓ or 🗙)
				<	١	1	<b>terror</b>	1	1	1		1	1	<b>1</b>	1	J	Finishing of lofts ( • or ×)
	POUY			5	f	ς.	5	}	<	<	1	۲	ς.	ζ	۲	(	Electrical junctions finishing ( • or ×)
	Properly not done.	4		<	1	1	9	ì	1	1	1	<	ζ	5	<	<	Window check <sup>6</sup> (✓ or X)
	done.			ς	)	۲	8	1	ŗ	1	1		٩		ς.	444	Tiles provision (✓ or ×)
				1	1	1	1	١	1	)	1	١	1		1	gaparae	Sink provision & size (✓ or 🗙)
	:			1	7	1	1	1	1	1	1	1	1	1	1	4	Grooves for door frames (✓ or 🗙)
				١	1	X	×	1	4	1	1	١	1	1	1	•	Balcony & terrace sill top finishing( • or ×)
		22		1	7	1	1	1	١	1	1	1	ς		1		Screeding in bathroom & utility ( • or ×)
				)	1	)	7	1	7	)	)	)	4	1	r	)	Screeding in 6" above FFL? ( v or x)