

ATR on Quality Control Check Report. (Bungalows)

Bungalow No	25	QC report stage	III	Sl. No.	33873
Company	GOVLLP	Project	GOV	Phase	IX
Prepared by	Sumerin	Sign	<i>[Signature]</i>	Date	27-08-19
Project Manager	K. Subashan	Sign	<i>[Signature]</i>	Date	27-08-19
Receipt by QC date		Sign		Other	
Receipt at HO date		Sign		Other	
Checked By MD on		MD Sign		For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

Recommendation that was made by QC:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
 Stop further work. Proceed with work after submitting ATR on QC report to QC team.

Notes:

1. Attach a copy of the QC report to this sheet.
2. Circle each correction with a red pen - tick (✓) each circle for work completed and cross (X) each circle where work has not been completed.
3. Give remarks for each case where work has not completed on this sheet.
4. Make 2 copied of the ATR - send one to MD and other to QC.
5. Enclose required photographs - hard copy.

Remarks:

All works are completed.

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Flat No	25	Other		SI. No.	33873
Company	Gov (GID)	Project	Gov	Phase	IX
Prepared by	V. Sanketh	Sign	<i>[Signature]</i>	Date	25/6/19
Project Manager	K. Purushotham	Sign	<i>[Signature]</i>	Date	25/6/19
Previous stage report no.	33145	Report filed and signed by PM		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Checked By MD on		MD Sign		For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

Recommendation:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom/utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Granite soffit for main door required	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Granite soffit for main door provided <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Main door granite soffit workmanship	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	Main door granite soffit edge polishing <input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor

APPROVED FOR CONSTRUCTION
30 JUL 2019
SOHAM MODI
MANAGING DIRECTOR

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

		Rate the quality of (Good ✓, Avg. ✕, Poor - needs correction ✕✕, NA)														
S No	Tiling & granite work	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform	
																Remarks
1		Toilet 1	✓	✓	✓	✕	✓	✓	✓	✓	✓	✓	✓	✓	✓	
2		Toilet 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
3		Toilet 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4		Toilet 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
5		Wash-basin-in-dining area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
6		Kitchen	✓	✓	✓	✕	✓	✓	✓	✓	✕	✓	✓	✓	✓	
7		Utility	✓	✓	✓	✕	✓	✓	✓	✓	✓	✓	✓	✓	✓	
8		Portico	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
9		Other														
Remarks																

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

Miscellaneous check – after finishing stage II

Quality and workmanship of portico tiles	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Quality and workmanship of flooring & setbacks	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Quality and workmanship of external cladding/ texture	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Remarks:	