

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

| | | | | |
|---------------------------|----------------|-------------------------------|-------------|---|
| Flat No | 31 | Other | Sl. No. | 27215 |
| Company | Nilgiri estate | Project | Phase | II |
| Prepared by | M. Iya Sridhar | Sign | Date | 16/05/17 |
| Project Manager | Ratheshyam | Sign | Date | 16/05/17 |
| Previous stage report no. | | Report filed and signed by PM | | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| Checked By MD on | | MD Sign | For filling | <input type="checkbox"/> Yes <input type="checkbox"/> No |

Recommendation:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom/utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

| | | | |
|---------------------------------------|--|---|--|
| Main door fixed with lock & stopper | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | | |
| Granite soffit for main door required | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Granite soffit for main door provided | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| Main door granite soffit workmanship | <input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor | Main door granite soffit edge polishing | <input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor |

Quality Control Check Report Stage: After Finishing Stage II (Villas)

| Tiling & granite work | | Rate the quality of (Good ✓, Avg. ✕, Poor – needs correction ✕✕, NA) | | | | | | | | | | | | |
|-----------------------|---------------------------|--|--|-------------------|----------------------|---------------------------|----------------------------|-------------------------------------|----------------------------|---------------------|---|------------------------|-------------------------|----------------------------------|
| S No | Room | Workmanship of tiling | White cement filling around CPVC lines | Corners finishing | Finishing near doors | Finishing on top of tiles | Finishing near ventilators | Step at bathroom entrance / utility | Step for shower / pot wash | Tile joint grouting | Granite platform finishing and edge polishing | Granite platform slope | Granite platform height | Finishing under granite platform |
| 1 | Toilet 1 (MT) | ✓ | ✓ | ✓ | ✓ | ✓ | ✕✕ | ✓ | ✕✕ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 2 | Toilet 2 (CT) | ✓ | ✓ | ✓ | ✓ | ✓ | ✕✕ | ✓ | ✕✕ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 3 | Toilet-3 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 4 | Toilet-4 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 5 | Wash basin-in dining area | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 6 | Kitchen | ✓ | ✕✕ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✕✕ |
| 7 | Utility | ✓ | ✕✕ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✕✕ |
| 8 | Portico | | | | | | | | | | | | | |
| 9 | Other | | | | | | | | | | | | | |
| Remarks | | | | | | | | | | | | | | |

Quality Control Check Report Stage: After Finishing Stage II (Villas)

| S No | Room | Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA) | | | | | | | | | | |
|---------|---------------------|--|---------------------------------|--------------------|----------------------|---------------------------|---------------------------------|---------------|----------------|---|-------------------------------|--|
| | | Color variation of floor tiles | Flooring workmanship & grouting | Skirting size (3") | Skirting workmanship | Plastering above skirting | Plastering & finishing of walls | Crack filling | Loft Finishing | General quality of painting & finishing | Door & frame painting quality | Door beading, luppam and painting quality. |
| 1. | Bedroom 1 (M&S) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 2. | Bedroom 2 (K&S) | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 3. | Bedroom-3 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 4. | Bedroom-4 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 5. | Drawing | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 6. | Dining | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 7. | Lobby 1 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 8. | Lobby 2 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 9. | Terrace/ balcony-1 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 10. | Terrace / balcony-2 | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 11. | Headroom | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 12. | Porch | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 13. | Kitchen | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 14. | Utility | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| 15. | Other | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ | ✓ |
| Remarks | | | | | | | | | | | | |

Quality Control Check Report Stage: After Finishing Stage II (Villas)

Miscellaneous check -- after finishing stage II

| | | | |
|---|-------------------------------|--|-------------------------------|
| Quality and workmanship of portico tiles | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Quality and workmanship of flooring & setbacks | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |
| Quality and workmanship of external cladding/ texture | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Avg. | <input type="checkbox"/> Poor |

Remarks:

| |
|--|
| |
| |
| |