ATR on Quality Control Check Repot. (Bungalows)

Bungalow No Villa - 17 QC report stage	Stage - III	SI. No.	29245
Company LLP Project Sevene Construction	State to frame	Phase	
Prepared by G. Sivo Pragad, Sign	G. Muprosco.	Date	11/04/2018
Project Manager Syedin Sign Sign	X	Date	4/04/2018
Receipt by QC date 12-02-2018 Sign	<	Other	7.
Receipt at HO date Sign		Other	
Checked By MD on MD Sign		For filling	☐Yes ☐No
Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team.	oceed only after recheck b	y QC.	2

Enclose required photographs - hard copy.

Give remarks for each case where work has not completed on this sheet. Make 2 copied of the ATR – send one to MD and other to QC.

- Circle each correction with a red pen tick (✓) each circle for work completed and cross (X) each circle where work has not been completed. Attach a copy of the QC report to this sheet.
- Remarks: 5) Ac point switch board filted in M. bedroom: 4) Grills again fitted property Lawn Caid. Sunction box coxest pulation done. Sp Jali was fixed in toilers 1) In drawing 2 NOS grills were