# REPORT OF SOIL INVESTIGATIONS FOR THE PROPOSED BUILDINGS AT MALLAPUR (V), UPPAL (M), R. R. DISTRICT

# Prepared by

DR. N. VENKAT RAO
M. Sc. Tech, Ph. D., FAEG, MIGS
Geological / Geotechnical Consultant

# **GEO TECHNOLOGIES**

# 5-83/B, St. No. 8, Habsiguda Hyderabad – 500 027

Tele/Fax: 040-27175255; 9347275255 (M)

April, 2009

# REPORT OF SOIL INVESTIGATIONS FOR THE PROPOSED BUILDINGS AT MALLAPUR (V), UPPAL (M), R. R. DISTRICT

# 1. INTRODUCTION

M/s B & C Estates, rep. by its Partner Sri Sudhir Mehta S/o Uttamlal Mehta, are proposing to construct two buildings (A & B) in Sy. Nos. 183, 184, 191 & 2/1/1, situated at Mallapur Village, Uppal Mandal, R. R. District.

Total area of the site is 3 acres 29 guntas.

The buildings comprise RCC framed structures with 2 cellars + G + 4 upper floors.

The aim of this Report is to evaluate the nature and depth of soils at the site, and to determine the safe bearing capacity of the foundations accordingly.

#### 2. FIELD INVESTIGATIONS

One (1) trial pit was excavated at the site.

The generalized subsoil profile in the site consists of filling and loose soil in the top 1.5 m, followed by morum. No water is seen in the pits.

#### 3. LABORATORY TESTING

The soil samples from the site were tested in the Soil Mechanics Laboratory at Hyderabad. The following tests were conducted:

Specific gravity

**Bulk Density** 

Grain size distribution

Direct shear test

All the tests were conducted in accordance with IS: 2720 (Code of Practice for Testing of Soils).

#### 4. RESULTS

Table 1 gives the results of physical and engineering tests on soil samples. At 2 m depth below ground level, the soil is morum. It is designated as silty gravel (GM) as per SIS: 1498.

Isolated foundations are recommended. No correction is needed for water table.

Appendix gives the calculations for SBC.

# 5. RECOMMENDATIONS

Based on Field investigations, the following Recommendations are given:

- a) The subsoil profile in the site consists of filling and loose soil in the top 1.5 m, followed by morum.
- b) No Correction is applied for water table.
- c) Based on Field & Lab testing, SBC is tentatively recommended as 30 tonnes per sq m for foundations resting on hard morum. This is based on the assumption of isolated footings of width 2 m at 2 m depth below cellar floor level. The actual size would be based on the loads from the super structure.
- d) SBC will be finalized later after detailed investigations by drilling.
- e) All foundations should be carried to hard strata.

All foundation pits should be filled back with well-compacted morum.

(Dr. N. VENKAT RAO)

M. Sc. (Tech.), Ph. D., FAEG, MIGS. Geological & Geotechnical Consultant AP Govt. Approved Geologist No. 10432 Former Professor & Head of Geophysics Osmania University, Hyderabad

Dr. N. MINKAT RAQ

Geologica and the Land Migs \* { No: 10432 )

( A.P. (a) i d of Ceophysics Former !

Communa University, Hyd.

TABLE 1 **SUMMARY OF SOIL PROPERTIES** PROPOSED BUILDINGS AT MALLAPUR (V), UPPAL (M), R. R. DISTRICT

	Location
Property	TP 1
Specific gravity	2.61
Density, KN / cu m	18.0
Grain size distribution	
Gravel > 4.75 mm	20
Coarse sand, 4.75-2 mm	21
Medium sand, 2-0.425 mm	23
Fine sand, 0.425-0.075 mm	24
Silt, 0.075-0.002 mm	8
Clay, < 0.002 mm	4
Shear Parameters	
Cohesion	3
Angle of internal friction, deg	35

Dr. N. MINIAT RAQ

11 17 17 1 18 D., FAEG, MIGS

Geologie 17 1 1 1 Consultant

(A.P. [

· I Consultant - ₹ Net 10432)

Fermer ad of Seephysics

Csmania University, Hyd.

# **APPENDIX**

# <u>CALCULATION OF BEARING CAPACITY</u>

# PROPOSED BUILDINGS AT MALLAPUR (V), UPPAL (M), R. R. DISTRICT

# a) Shear Criterion:

Assumed width of foundation... 2 m

Assumed depth of foundation... 2 m

Unit wt. = 18.0KN / cu m

Cohesion = 3 KN / sq m (Neglected)

Angle of internal friction = 35 deg.

No correction is needed for water table.

Using IS Code 6403 – 1981 formula:

Nc = 33.53 Nq = 22.07 Nr = 29.58

Net, Ult B.C. = 1.3 c Nc + rD (Nq - 1) + 0.4 rB Nr

= 1184 KN per sq m

With a F.S. of 3.0, SBC = 394 KN per sq m

# b) Settlement Criterion:

In frictional soils as these, settlement is a better criterion. Based on the results of Direct shear test, N is taken as 22. For a permissible settlement of 40 mm,

Allowable bearing capacity = 12.3 N [(B + 0.3)/B] Rq Rd

= 311 KN per sq m

Recommended Safe Bearing Capacity is 30 tonnes per sq m.

# GEO TECHNOLOGIES

# 5-83/B, St. No. 8, Habsiguda, Hyderabad - 500 007 Tel/Fax. 040-27175255 (R), 09347275255 (M); Email: nvenkatrao2005@yahoo.com

# (Expert Geotechnical Consultants for Soil / Rock / Water Investigations)

Dr. N. VENKAT RAO,

Govt. Approved Geologist No. 10432

M. Sc. (Tech.), Ph. D., FAEG, MIGS

Former Professor & Head of Geophysics, Osmania University, Hyderabad

#### **Groundwater Feasibility Report**

Client: M/s B & C Estates, rep. by Sri Sudhir Mehta S/o Uttamlal Mehta

Address: Sy. Nos. 183, 184, 191 & 2/1/1, situated at Mallapur Village, Uppal Mandal,

Ranga Reddy District

Area: 3 acres 29 guntas

# 1. Geology:

(a) Rock Type: Granite

(b) Texture: Coarse to Medium grained

(c) Soil Type: Silty gravel

(d) Recharge Conditions: Moderate

#### 2. Geophysical Data:

- (a) No. of Vertical Electrical Soundings (VES): 3
- (b) Configuration: Schluemberger
- (c) Generalised Sequence based on VES:

 $0 - 7 \, \text{m} \dots$ Top soil

5 - 18 m ... Weathered zone

18 - 75 m ... Rock with intermittent fractures

75- 140 m ... Hard Rock with minor fractures

Below 140 m ... Hard rock with no fractures

#### 3. Recommendations:

- 1. The site has moderate potential for groundwater. One point is suggested for drilling in N-E Corner.
- 2. Type of well: Bore well

3. Size: 6 1/2 "

4. Depth: 140 m

5. Casing: 15-20 m

6. Expected yield: Moderate (1 ½ " - 2 ")

(Dr. N. Venkat Rao)

Dr. N. VINILAT RAQ Geologic Consultant

( A.P.

Copiet No: 10432)

ed of Geophysics Cash..... University, Hyd.

6