Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

I lat INO	28	Other		Sl. No.	25/25
Company	SOV(ILP)	Project	Sov	Phase	X
Prepared by T. Vinu	T. Vinual humas	Sign	T. Smodkumas	Date	12/01/20
Project Manager K. Put.		Sign	The state of the s	Date	12/01/20
Previous stage report no.		34892	Report filed and signed by PM	d by PM	Yes No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	ATR on QC rep with work after only after making ATR not requing	oort to QC team. Pro er submitting ATR o ng corrections pointe red.	ceed only after recheck bn QC report to QC team.	YCC. ATR not required.	

- Completing stage II works.

 Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

 In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.

 2. Switchboards must be fitted to plum.

 3. Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided		
Yes No		Good Avg Poor	Yes YNo		
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided		
☐ Yes ☑No		Good Avg Poor	Yes Yo		

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

	Remarks: Note: -1. Rod should be removed as	Quality and workmanship of lawn	Cleaning/painting of external cladding/texture	Painting of gates & railings	Quality and workmanship of railings	Quality and workmanship of gate	Miscellaneous check – after finishing stage III
	at head room.	Good Avg. Poor	Good YAvg. Poor	Good Awg. Poor	Good Avg. Poor	Good Avg. Poor	