Flat No Prepared by Company Project Manager Previous stage report no. Checked By MD on Recommendation: Stop further work. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Stop further work. Proceed with work after submitting ATR on Quantum or an extension of the contract of the co Proceed with further work. ATR not required. 不 Submit ATR on QC report to QC team. Proceed only after recheck by QC. J. RAJESH Pur Shathan Quality Control Check Repot. Sign Other Sign Project MD Sign 00 Stage: After Finishing Stage III (Villas) Report filed and signed by PM C report to QC team. 10N Phase SI. No. Date Date For filling Yes 9 35 Yes 80 00 (X) 818 No No 0 0

Inspection should be done after:

- Completing stage II works. Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.

- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Video door phone to be provided	Modular kitchen workman ship	Modular kitchen to be provided	Miscellaneous check:
Vyes No	Good Avg Poor	Yes No .	
Video door phone provided		Modular viction browners	Madulas bitchen provided
100		Good Avg Poor	∏Yes □No −

Ren	15	14	13	12	11	10	9	00	7	6	5	4	w	2	-	S No
Remarks Note 5	Other	Portico	Toilet 3	Toilet 2 K. 7	Toilet 1 M.7	Kitchen	Utility / balcony 3	Utility / balcony 1	Utility / balcony 1	-Lobby-1	Dining	Drawing	Bedroom-3	Bedroom 2 K. B.	Bedroom 1 M. 8	Room
00				<	7	1	<	1	1	1	1	1	1	<	5	Door, door knob & door stopper fitting
1001				<	3	1	<	1	1	1	1	<	1	1	(Door, door knob & door stopper cleaning
				<	1	1	١	1	1	1	1	1	1	1	5	Window grills & quality
401				<	5	<	1	1	1	1	1	<	1	1	5	Window grills fitting & finishing
1+12				<	<	<	1	1	1	1	1	1	1	1	1	Windows quality
				<	7	<	١	1	1	1	1	1	1	1	1	Window fitting & finishing
+				1	١	١	1	1	1	1	1	٢	1	1	1	Balcony railing quality & finishing
1:4:1				<	7	1	X	1	1	1	1	1	1	1	١	CP jali quality and fitting
t				<	7	1	1	1	1	1	<	1	1	<	1	Edge building
				<	5	7	<	1	1	1	<	7	1	<		Switch boards fitting & covering with plastic covers
				1	7	1	1	1		1	<	7	1	1	1	Junction box covers painting

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Miscellaneous check – after finishing stage III	
Quality and workmanship of gate	Good Avg. Poor
Quality and workmanship of railings	Good Avg. Poor
Painting of gates & railings	Good Avg. Poor
Cleaning/painting of external cladding/texture	Good Avg. Poor
Quality and workmanship of lawn	Good Avg. Poor
Remarks:	