Compa	any Name	: MMR Kowkur-LLP			Prepared by K.Sneha	
Project	:GHT		and the second s		The state of the s	
List of Pumps Date: 09/04/2022		and it was a company of the first terms of the firs		may considered to the contract of the contract		
S.No	Pump Description		Capacity	Units	Location	Remarks
1	Monoblock pump		5Hp	1	At Store	Working-not in use
2	Monoblock pump		1Hp	1	At Store	Working-not in use
2 3 4 5	Submersible automatic pump		1Hp	1	GHMC Park septic tank	Working
3	Submersible automatic pump		2Hp	1	B-block wells south side	Working
-	Submersible automatic pump		2Hp	1	B-block wells south side	Working
6	Submersible pump[Normal]		ЗНр	1	A-block Lift pit	Working
-	Submersible pump[Normal]		2Hp	1	A-block wells West Side	Working
7		ible automatic pump	2HP	1	A-block north side well	Working
8			1.5Hp	1	At Store	Working-not in use
9	1	sible motor	3Hp	1	At store	Working-not in use
10		ible pump[Normal]		+	B-block south east side	Working
11		ll Submersible Pump	ЗНр	1	B-block North east side	working
12		ll Submersible Pump	ЗНр	1	A-block North side	Under repair
13	Bore we	ll Submersible Pump	3Hp	1	A-DIOCK IVOI III SIGE	

List Of Pumpsore Wells Datails

Certified by: K. Sneha Aset. Engineer MEHTA & MODI REALTY KOWKUR LLP

Machinery details and location of MMR-KOWKR-LLP site

Compa	any:	MMR-	-KOWKUR-LLP				
Site:		GHT GHT		Date:	09-04-2	09-04-2022	
Report date 09-04-		2022	Prepared by:	K.Sneh	K.Sneha A SURESH		
			Approved by:	A SUR			
List of	Machinery details	of MMI	S-KOWKID III				
Sl.no	Name of equip	mont	The state of the s				
1	Generator		Make	Quantity	Installed	Status	
			Powerol Mahindra	1	At site	Working	
2	RO Plant		MM Aqua systems	1	1		
3	Fouth commit		- I I I I I I I I I I I I I I I I I I I	1	At site	Working	
3	Earth compacting machine		NA	1	At Site	Not working	
4	Earth compacting machine		NA	1	At site	Not working	
5	Drilling machine		Bosch-GBH200				
			Boscii-OBH200	1	At Site	Working	
6	Rod cutting machine		Bosch-GWS750-100	1	At site	Working	
7	Jaw crusher Machine				Tit site	Working	
			3 Phase induction motor	1	At site	Working	
8	Sand Screening Machine		Coimbarore	1	At site	Not Using	



