


Company	Silver oak villas LLP			Certified By	K Purshotham	
Project	Silver oak villas			Prepared By	B.MEENAKSHI	
Date	11-07-2022					
SLNo	Service Number	Used for	Sub Meter	Location	Remarks	
1	Electricity	3409 11504	Part-III constructions surasani and Rohankishag & VCD	149798	Laboure quaters	used for Rohan Constructions,one bore
			149782	Laboure quaters	Used for Surasani constructions ,laboure quaters,part-3 tower CC Tv and Light towers	
2	Electricity	3409 12230	Welding works	100855	Part-3 welding shed	Using SSLLP Welding works
		Labour quarters	100859	Part-3 welding shed	Using SSLLP Welding works	
			100858	Part-3 welding shed	Using SSLLP Granite Works,one bore	
3	Electricity	0905 13233	SOVOA Common aminities	100845	Club house	Club housing pump,security room,Streetlights,swimming pool,RO Plant
			3040937	Club house	Club house manjeera	
			3047186	Club house	Not running	
			149781	Villa no 33	Used for Bore	
			149795	Villa no 95	Used for Bore	
			149792	Villa no 95	Used for Bore	
4	Electricity	3409 13682	Office Building	-	-	Used for Site office
5	Electricity	3409 13683	Villa no 97	-	-	Used for Villa no 97
6	Electricity	3409 13692	Apartment Common	135205	Near transformer	Used for Bore

Certified By:
Meenakshi
 Meenakshi
 Asst. Engineer
 SILVER OAK VILLAS LLP

APPROVED BY
[Signature]
 14 JUL 2022
 K. PURSHOTHAM
 Project Manager (Super. of Villas Part-III)

Company	Silver oak villas LLP				Certified By	B Praveen
Project	Silver oak villas				Prepared By	B.Meenakshi
Date	11-07-2022					
SLNo		Service Number	Used for	Service provider		
1	Electricity	3409 12230	Welding shed & Granite cutting works	TSSPDCL		
2	Electricity	3409 13682	Site office	TSSPDCL		
3	Electricity	3409 11504	Part-III constructions surasani and Rohan&Ishaq & VCD	TSSPDCL		
4	Electricity	0905 13233	CT meter (club house, street lights, wimming pol bores, RO plant, Manjeerwater pumping, Securityroom)	TSSPDCL		
5	Electricity	3409 13692	Apartment common	TSSPDCL		
6	Electricity	3409 13683	villa no 97	TSSPDCL		
Project Manager sign		Admin Manager Sign	Audit Manager Sign			

Certified By:

 Meenakshi
 Asst. Engineer
 SILVER OAK VILLAS LLP

APPROVED BY

 11 JUL 2022
 K. PURUSHOTHAM
 Project Manager (Silver Oak Villas Part-III)

Company	Silver oak villas-III	Certified By	B Praveen
Project	Silver oak villas-III	Prepared By	M. MEENAKSHI
Date	11-07-2022		
Sl.No		Service Number	Used for
1	Bore	rewell Submireible Pump	Near Lboure quaters
2	Bore	rewell Submireible Pump	NearCC camara Tower Beside
3	Bore	rewell Submireible Pump	Near welding shed side
4	Bore	Self Priming pump	near villa no 146
5	Bore	Cutter Type pump	dewatering of water from footing while casting
6	Bore	Cutter Type pump	dewatering of water from footing while casting
			Service provider
			Working
			Working
			Working
			Working
			Working
			Working



Company	Silver oak villas LLP		Certified By	B Praveen	
Project	Silver oak villas		Prepared By	MEENAKSHI	
Date	11-07-2022				
SLNo	Details	Service Number	Used for	Service provider	
1	Bore	Submrcible Pump-1	Near office Building	Working	
2	Bore	Submrcible Pump-2	Near Transformer Beside	Working	
3	Bore	Submrcible Pump-3	Near Villa no 33 line	Working	
4	Bore	Submrcible Pump-4	Near Villa no 50 line	Working	
5	Bore	Submrcible Pump-5	Near Villa no 95 line	Working	

