## М. 2004К2ПНИ

Fabrication of Aluminium Partitions, Door's, Windows & Glazing Work's H.No. 1348, Poineer Bazar, Bolarum, Sec-bad. Cell:9849102251

GISTI	No:36BBIPM8347N1ZW	DELIVERY CHI	ALLAN
S-4-1	Ner Oak Usilas UP DATE 187/344 In Floor MU Road School CUSTON RDAT	MER D-C-NO	2-5-23
SI.	DESCRIPTION OF THE ITEMS	QUANTITY	Approx-ValueRs.
2	1800mm x 1200mm · Sia 900mm x 1050mm · Sia	1NO	
3	600 mm × 1200 mm of w	4 201 3 208	
5	600 mm x 600 mm VCHILLERY (200 mm x 1200 mm Fixed)	2 2 2	
ij	VN0!- 178		
	INWARD Inward No: 2832 Dec 2 ST3 MRN No: Da: Received By:  (Silver Oak Villas-Pane-III)	30502017	
REC	EIVED THE GOODS IN GOOD CONDITION		M. SUDARSHAN Sadolang

## **INSTALLATION REPORT**

Company/ firm:	SOV LLP	Requisition nos.:	20230425046
Project:	SOV-W	PO no.:	20230425049
Supplier:	Misudayshan	Material type:	uprc windows

Details of installation:

SI. No.	Date of installation	Unit no.	Material details	Size	Qty
1.	215/23	178	upve Sliding with mesh	1800×1200	6 No'S
2.		le	Upvc fixed	1200 X 1200	2 No!S
3.	u		Upvc Sliding with mesh	900 X/050	1 NO
4.		- 10			
5.	U	**	upvc openable	600 x 1200	4 NOS
6.			ventilator top hung	600 x 600	3 1205
7.					
8.					
9.					
10.					
11.					
12.					
13.		<del></del>			
14.					
5,					
Total:					2009 31
emar	ks:				

	Project manager	Security	Admin (Audit)
Approved by		1	
	AV.		

Note: 1. Report to be sent on completion of work. 2. For partial completion report must be sent once a month. 3. This report is required for installation of windows, french windows, balcony/ staircase railing, fire doors and such materials where PO for material + labour is issued. Exclude false ceiling, painting, water proofing where 'Advice for giving credit to contractor/supplier form' is being set to E&D. 4. One or more reports can be made per PO. Avoid multiple Pos in one report. 5. Provide report on defaults, poor quality, missing items, etc. 6. Reports to be provided regularly. However, must be provided within one working day of request from purchase.