


INSTALLATION REPORT

Company/ firm:	MRM up	Requisition nos.:	20230803006
Project:	QMR	PO no.:	20230803059
Supplier:	ARN upvc windows	Material type:	upvc windows

Details of installation: and door

Sl. No.	Date of installation	Unit no.	Material details	Size	Qty
1.	28/08/23		Upvc windows 4x31	4x31	2 nos
2.			upvc windows	6'x4'	6 Nos
3.			" "	6'x4'	1 nos
4.			upvc ventilator	22 1/2 x 21	2 nos
5.					
6.					
7.					
8.					
9.					
10.					
11.					
12.					
13.					
14.					
15.					
Total:					(3 nos)

Remarks: All work completed

Approved by	Project manager	Security	Admin (Audit)
			

Note: 1. Report to be sent on completion of work. 2. For partial completion report must be sent once a month. 3. This report is required for installation of windows, french windows, balcony/ staircase railing, fire doors and such materials where PO for material + labour is issued. Exclude false ceiling, painting, water proofing etc. *Advice for giving credit to contractor/supplier/ firm* is being set to END. 4. One or more reports can be made per PO. Avoid multiple Pos in one report. 5. Provide report on defects, poor quality, missing items, etc. 6. Reports to be provided regularly. However, must be provided within one working day of request from purchase.

157

DELIVERY CHALLAN

ARN UPVC WINDOWS AND DOORS

Plot No. 44, Surya Nagar, Beside Govt. Hospital, Mallapur, Hyderabad.

To 011 M 112

To
M/s. Mod. Realty Mallpas LLP

[illegible]

Expansion: HUN Road & C-band-500003

Phones :

Your Order No. 20230803059

Date: 26-08-2023

Customer GST No. _____

Auto :- TS10UB99025

Invoice No. Our D.C. No. 157

Date : 26-08-2023

Invoice No.	Our D.C. No.
3.No.	Description
1)	upar colndow 4'x3'
2)	" " 6'x4'
3)	" " 6'x4'
Total Quantity	9 Nos.

GST No : 36BNJPC2335M1ZY

* Goods once sold will not be taken back

INWARD

MODI REALTY MALLAPUR LLP

Ward No. 13086 D261A1

MRN NO. 208305

Receiver's Signature with Stamp

Received By _____ Sign _____

~~Authorised Signature~~