Sl.No Sl.N	May flower Platinum MPL N.Divya Description of Drawings Center line drawings Footings + Columns Total column upto 9th flat Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	Date: Quaterly Report: Drawing Received List A block	Remarks Received Received Received Received Received Received Received
Sl.No Sl.No 1	Description of Drawings Center line drawings Cootings + Columns Total column upto 9th flat Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	Drawing Received List A block	Received Received Received Received Received Received Received
SI.No 1	Description of Drawings Center line drawings Footings + Columns Total column upto 9th flat Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	A block	Received Received Received Received Received Received
1 C 2 F C 3 P 4 C 5 R 6 P 7 S 8 S 9 S	Center line drawings Footings + Columns Total column upto 9th flat Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Flab Basement 02	A block	Received Received Received Received Received Received
2 F	Footings + Columns Total column upto 9th flat] Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	A block A block A block A block A block A block	Received Received Received Received Received
2 F	Footings + Columns Total column upto 9th flat] Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	A block A block A block A block A block A block	Received Received Received Received Received
3 P 4 C 5 R 6 P 7 S 8 S 9 S	Total column upto 9th flat] Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Slab Basement 02	A block A block A block A block A block	Received Received Received Received
3 P 4 C 5 R 6 P 7 S 8 S 9 S 10 E	Plinth beam Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Stab Basement 02	A block A block A block A block	Received Received
4 C 5 R 6 P 7 S 8 S 9 S	Column upto 9th flat Retaining wall Drawings Pedestrial Drawings Stair case Drawings Slab Basement 02	A block A block A block	Received Received
5 R 6 P 7 S 8 S 9 S 10 E	Retaining wall Drawings Pedestrial Drawings Stair case Drawings Slab Basement 02	A block A block	Received
6 P 7 S 8 S 9 S 10 E	Pedestrial Drawings Stair case Drawings Slab Basement 02	A block	
7 S 8 S 9 S 0 10 E	Stair case Drawings Slab Basement 02		D
8 S 9 S C 10 E	Slab Basement 02	A blook	Received
9 S G 10 E			Received
10 E		A block	Received
10 E	Slab Basement 01	A block	Received
	Ground floor slab [beam and slab]	A block	Received
11 A	Electrical Drawings	A block	Received
	AC ducting VRF Drawings	A block	Received
	Center line drawings	A block North & west side	Received
	Cootings + Columns	A block North & west side	Received
	linth beam	A block North & west side	Received
	labs	A block North & west side	Received
	Center line drawings	B block	Received
	ootings + Columns	B block	Received
	linth beam	B block	Received
	Retaining wall Drawings	B block	Received
	ump Details	Extra Drawings	Received
	eptic tank Detail	Extra Drawings	Received
	CC of slab 01	Part 02	Received
	Vorking drawings	Part 01	Received
	lab 04 RCC Drawings	Part 01	Received
	lab 05 RCC Drawings	Part 01	Received
	lab 06 RCC Drawings	Part 01	Received
	lectrical Drawings	Part 01	Received
	abour room Drawings	-	Received
	lab 07 RCC Drawings	Part 01	Received
	lab 08 RCC Drawings	Part 01	Received
	lab 09 RCC Drawings	Part 01	Received
	lab 02 RCC Drawings	Part 02	Received
	lab 03 RCC Drawings	Part 02	Received
	th floor working drawings	Part 01	Received
	h floor working drawings	Part 01	Received
	ain arch gate RCC & Structural rawings Certified by:	-	Received
37 Sla	ab 09 RCC Drawings	Part 01	
	ab 03 RCC Drawings	Part 02	Received Received

39	Working drawings	Part 02	Received
40	RCC and Architectural drawings	Main Gate	Received
41	Slab 04 RCC Drawings	Part 02	Received
42	Slab 05 RCC Drawings	Part 02	Received
43	Slab 06 RCC Drawings	Part 02	Received
44	6th floor working drawings	Part 01	Received
45	7th floor working drawings	Part 01	Received
46	8th floor working drawings	Part 01	Received
47	9th floor working drawings	Part 01	Received
48	Slab 10 RCC Drawings	Part 01	Received
49	Slab 11 RCC Drawings	Part 01	Received
50	Slab 12 RCC Drawings	Part 01	Received
51	Ground floor Working drawings	Part 02	Received
52	1st floor Working drawings	Part 02	Received
53	2nd floor Working drawings	Part 02	Received
54	3rd floor Working drawings	Part 02	Received
55	4th floor Working drawings	Part 02	Received
56	5th floor Working drawings	Part 02	Received
57	Totlot footings RCC drawings	-	Received
58	Swimming pool drawing	-	Received
59	Compound wall drawings	South side and west side	Received
60	Driveway RCC drawings	North east side	Received
61	Electrical Drawings	-	Received
62	6th floor Working drawings	Part 02	Received
63	7th floor Working drawings	Part 02	Received
64	8th floor Working drawings	Part 02	Received
65	9th floor Working drawings	Part 02	Received
66	Terrace Architectural Drawings	Part 01	Received
67	Terrace Structural Drawings	Part 01	Received
68	1st Slab Structural Drawings	Totlot	Received
69	Retaining wall sumps Drawings	Touct	Received
70	Slab 07 RCC Drawings	Part 02	Received
71	Slab 08 RCC Drawings	Part 02	Received
72	Slab 09 RCC Drawings	Part 02	
73	Slab 10 RCC Drawings	Part 02	Received Received
74	Slab 11 RCC Drawings	Part 02	Received
75	Slab 12 RCC Drawings	Part 02	
76	Elevation drawings	Part 01	Received Received
77	Elevation drawings Elevation drawings	Part 02	
	Swimming pool side walls and duct	Part 02	Received
78	slab	-	Received
79	Compound wall painting	-	Received
80	Compound wall Railing	-	Received
81	Terrace Railing		Received
82	M.S Paragola for 1500 sft flats	-	Received
83	Road formation drawing	-	Received
84	Clubhouse elevation	and the same of th	Received
85	Clubhouse false ceiling Certified by corridor flooring and cladding	-	Received
86	corridor flooring and cladding	N .	Received

N.DIVY Admin
Assistant Eneg. Admin

N. Tu

87	Main door beading	-	Received
88	Lift cladding		Received
89	Ramp flooring	-	Received
90	Driveway drawing	-	Received
91	Landscaping drawing		Received
92	North side compound wall pipe railing drawing	-	Received
93	Landscaping flooring drawing	-	Received
94	Landscaping plant boxes drawing	-	Received
95	List of plants drawings	-	Received
96	list of parking plan	Part 01 and Part 02	Received
97	security room and security toilets	-	Received
98	Boom barrier Drawing	-	Received
No	ote: Part 01 - A1 to A8 & B1 B5 and club h	nouse	
	Part 02 - B2,B3,B4 & C1 to C6		

Certified by:

N.DIVYA

Assistant Engg/ Admin

Mny Flower Platinum