

INSTALLATION REPORT

Company/ firm:	MPMCLP	Requisition nos.:	20231121045
Project:	GMR	PO no.:	20231121060
Supplier:	M. Sudarshan	Material type:	UPVC windows

Details of installation:

Plans of installation.					
Sl. No.	Date of installation	Unit no.	Material details	Size	Qty
1.	22/11/23		UPVC ventilator	750x600.	2 Nos
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					
11.					
12.					
13.					
14.					
15.					
Total:					2 Nos.
Remarks: C-605 & D-104.					
Approved by	Project manager		Security	Admin (Audit)	
					

Notes: 1. Report to be sent on completion of work. 2. For partial completion report must be sent once a month. 3. This report is required for installation of windows, french windows, balcony staircase railing, fire doors and such materials where PO for material + labour is issued. Exclude false ceiling, painting, water proofing where "Advice for giving credit to contractor/supplier form" is being set to E&D. 4. One or more requests can be made per PO. Avoid multiple Pos in one report. 5. Provide report on defaults, poor quality, missing items, etc. 6. Reports to be provided regularly, However, must be provided within one working day of request from purchase.

M. SUDARSHAN

Fabrication of Alluminium, UPVC Partitions, Doors & Windows & Interior Works

D.No. 1348, Pioneer Bazar, Bollaram, Secunderabad-500 010. T.S.

Email : sudarshan.maheshwaram@yahoo.com

GSTIN No. : 36BBIPM8347N1ZW

M/s. Modi Reality Mallapur LLPNo. 077Address : S-4-187/244 II Floor M. U.Date : 27-11-2023Road sc-bad

Vehicle No.

GSTIN No. 36AAEFM1459R1ZPOrder No. 2023/12/060

SI No.	PARTICULARS	HSN Code	Qty.	Approx. Value Rs.
1	<u>UPVC Windows</u> 750 x 600 Kenticalew	3916	2 Nos	
INWARD MODI REALTY MALLAPUR LLP Ward No. <u>14106</u> dt <u>27/11/23</u> MRN No. <u> </u> Received By <u> </u> Sign <u> </u> 2023/12/2022.				

Received the goods in good condition.

For **M. SUDARSHAN***Sudarshan*

Receiver's Signature with Rubber Stamp

Authorised Signatory