Company:	CRESCENTIA LABS						
Project & Phase:	GV 1						
Prepared by:	QC Team						
Report Date:	02-04-2024						
Sign:							
Check list for QC at each stage.							
Notes:							
1. Report should be send once a quarter	on or before 15th of the succeedir	ng month.					
2. Where QC was done write the QC rep							
3. Mark 'X' if QC check was missed and	can be taken up now. Project Ma	nager to send req	uest immediat	ely.			
4. Mark 'XX' if QC check was missed a							
5. Mark 'NA' if QC check was not appl	icable (work done before QC was	introduced).					
6. Leave blank if work has not taken up.							
Remarks:				•			
				•			

RCC Works	Apartment Bl	locks															
S No	Block , Villa No.	Before footings	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6	OTH & lift room	drive-way col	drive-way slab
1	North Block	40913/4086 7/40926	NA	41370	41479/41683	41974	42212	42355	42541	42667	42732	42769	42835	42871			
2	South Block	41189/4120 0/41259/41		41902	41965	42055	42244		42540	42668	42716	42756	42795	42825		42731	
3	Chemical Block	42701/4270 8	42734	42753	42792	42826	42836	42872	42872								
4	Solvent Block	42726	42738	42754	42778												

Civil Works							
S No.	Block /Flat No	After brick work	After Plastering	Stage I, Plumbing & electrical	Stage II	Stage III	Remarks
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							