Modi Properties & Inv. Pvt. Ltd - Site Audit Report by M.Mahesh

Company:		GMR-LLP		Date of site visit:	11/03/2020
Site:		GMR		From / To time:	09.30 to 18.00
Visited by:		M.Mahesh		Prepared by:	Praveen. B
Sl No	Description				Remarks
1.	Creche				
	a) No	NA			
	b) Cre	NA			
	c) Av	erage no. of meals prov	у	NA	
	d) Qu	NA			
2.	Safety measu				
	a) No	06 helmets are maintaining at site office			
	b) Qu	Average			
	c) No of labours working without helmets				Majority of labours are not wearing
3. 1	Labour quar	ters			
	a) No	147			
	b) Occupied labour quarters?c) No. of labour quarters in poor condition?				125
					11
	d) No	10			
	e) No	10			
	f) No. of quarters in violation of electric supply rules.				Nil
	g) Pro	ovision of water for laborated	our quarters	?	Poor
	h) Qu	ality of toilets/washroo	m, cleanline	ess.	Poor
4.	Pumps				
	a) No	of pumps at site			2 bore pumps + 10 open well

	Submersible pump
b) No of pumps working at site	12 out of 12 pumps are working
c) No of pumps not working at site	02
d) No of pumps under repair	02
CC Cameras	
No of Cameras working at site	02
No of cameras not working at site	-
Is CC Cameras seal with bar codes	Yes
Staff welfare issues	
No of staff working at site	09
Issues	No
Equipments	
Is Auto level machine is working at site	Yes
Is laser line machine is working at site	Yes
Is Stencil is maintaining at site	Not ordered
Breathe analyzer is maintaining at site	Yes
	c) No of pumps not working at site d) No of pumps under repair CC Cameras No of Cameras working at site No of cameras not working at site Is CC Cameras seal with bar codes Staff welfare issues No of staff working at site Issues Equipments Is Auto level machine is working at site Is laser line machine is working at site Is Stencil is maintaining at site

List of audit points	checked(Yes/No)	Qualitative rating(G/A/P)
Labour quarters	Yes	Average
2. Sanitation	Yes	Poor
3. Water & electricity supply	Yes	Averge
4. Pumps	Yes	Good
5. Equipments	Yes	Good
6. Safety & measurements	Yes	Average
7. CC Cameras	Yes	Good
8. Electrical installation safety	Yes	Good

9. Crèche	Yes	Average				
10. Staff welfare	Yes	Good				
Misc	-	-				
Remarks on default in following standard procedures: Nil						
Remarks on corrections made in registers or database: Nil						
Complaints: NIL						

Suggestions: Need to dewater the drain water from old labour quarters to outside GHMC manhole.