Company	Silver oak villas LLP		Certified By	By K Purshotham	
Project	Silver oak villas		Prepared By	K.Tulasi Rani	
Date	15-04-2024				
Sl.No	Detailes	Service Number	Used for	Service provider	
1	Bore	Submrcible Pump-1	Near office Building	Working	
2	Bore	Submrcible Pump-2	Near Transformer Beside	Working	
3	Bore	Submrcible Pump-3	Near Villa no 33 line	Working	
4	Bore	Submrcible Pump-4	Near Villa no 50 line	Working	
5	Bore	Submrcible Pump-5	Near Villa no 95 line	Working	





Campony	Silver oak v	illae_III	Certified By	K Purshotham
Company	Silver oak villas-III		Prepared By	K.Tulasi Rani
Project				
Date	15-04-2024			0
Sl.No		Service Number	Used for	Service provider
1	Bore	Borewell Submreible Pump-1	Near Lboure quaters	Working
2	Bore	Borewell Submrcible Pump-1	NearCC camara Tower Beside	Working
2		Borewell Submreible Pump-1	Near welding shed side	Working
3	Bore		near villa no 146	Working
4	Bore	Self Priming pump		Working
5	Bore	Cutter Type pump	dewatering of water from footing while casting	
6	Bore	Cutter Type pump	dewatering of water from footing while casting	Working



