

Company:		GVRC						
Project & Phase:		INNOPOLIS						
Prepared by:		S. Sunil Kumar						
Report Date:		03.04.2023						
Sign:								
Check list for QC at each stage.								
Notes:								
1.	Report should be send once a quarter on or before 15th of the succeeding month.							
2.	Where QC was done write the QC report number if available or mark a 'tick'.							
3.	Mark 'X' if QC check was missed and can be taken up now. Project Manager to send request immediately.							
4.	Mark 'XX' if QC check was missed and cannot be undertaken now.							
5.	Mark 'NA' if QC check was not applicable (work done before QC was introduced).							
6.	Leave blank if work has not taken up.							
Remarks:								

Handwritten signature

RCC Works - Apartment Blocks		Block .	Before	Villa No.	Plinth	Col 1	Slab 1	Col 2	Slab 2	Col 3	Slab 3	Col 4	Slab 4	Col 5	Slab 5	Col 6	Slab 6	OTI & lift	col	drive-way	slab
1	5600		33424/3345	6/35805	0/35942	82	22														
2	5600-E		33424/3345	33995/3412	34264/360	34492/361	82	22													
			35058/3506	6/35805	0/35942																
3	2727		35058/3506	5/35084/351	68																
			35634/3566	5/35084/351	68																
			35468/3565	37017/3712	9/37254/37	90/36139	272														
4	4545		6/35408/354	9/37254/37	37622	37871	38187	38334	38589	39050	39235	39779	40513	40565	41345	40872	41188				
5	5600-C		36473	36975	37,375	37503	37650	37699	37922	37966											
6	Attum		38033/3817	4/37837	XX	39049	39207	39318	39468/395	40076	40399										
7	5600-H		38148/3815	9	38630	NA															
8	Cable		NA	NA	NA																

Civil Works								
S No.	Block / Flat No	After brick work	After Plastering	Stage I, Plumbing & electrical	Stage II	Stage III	Remarks	
1	5600	35066	35232					
2	2727	XX	XX	38199/38411/38830				
3	4545(Upper Basement)	XX						
4	4546(Ground floor)	XX	40505					
5	4545 (1st Floor)		41117					
6	4545 (2nd Floor)		40705 XX					
7	4545 (3rd Floor)		40873 XX					
8	4545 (3rd Floor)	41344	41431					
	Atthant(Upper Basement)	XX	40506					

10/04/24