

Sl. No.	Project Name	Block Name	Unit No.	Unit Area	Contractor Name	Work Type/Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill D. Category	Remarks
80311	Guinohar Residency	F	504	1360 Borela Narayana - Earthwork	AC Pipes	3.1	4150	05-Dec-23					doc_55340311160000.pdf	Ceiling plastering work done in the lift
80312	Guinohar Residency	D	406	0 Sano Das earthwork	AC Pipes	0	10364	29-Dec-23					doc_553403121700000.pdf	All works done
80313	Guinohar Residency	D	504	1600 Borela Das - Civil & Earthwork	AC Pipes	2.5	4150	30-Dec-23					doc_5534031317160000.pdf	Ceiling plastering work done in the lift
80314	Guinohar Residency	H		0 Bihu Gata - Welder	AC Pipes	0	4000	15-Dec-23					doc_553403141700000.pdf	Towards staircase pillars work and structural
80315	Guinohar Residency	Misc		0 Amalish Kumar Sharma - Carpentry	Carpentry - Door Frames	0	7000	06-Nov-23					doc_553403151700000.pdf	has to be plastered from upward construction
80316	Guinohar Residency	A		129000 Ravinder Chary	Carpentry - Door Frames	0.1	7150	22-Nov-23					doc_553403161700000.pdf	Towards door frames plastering of 5 and 6
80317	Guinohar Residency	D	104	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters	2.4	4013	17-Dec-23					doc_553403171700000.pdf	making
80318	Guinohar Residency	C	204	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters	2.4	4013	17-Dec-23					doc_553403181700000.pdf	Towards Door Shutters Plastering
80319	Guinohar Residency	C	504	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters	2.4	4013	17-Dec-23					doc_553403191700000.pdf	Towards Door Shutters Plastering
80320	Guinohar Residency	C	204	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters	2.4	4013	17-Dec-23					doc_553403201700000.pdf	Towards Door Shutters Plastering
80321	Guinohar Residency	H	307	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403211700000.pdf	Plastering of door and door frames and hardware
80322	Guinohar Residency	H	306	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403221700000.pdf	Plastering of door and door frames and hardware
80323	Guinohar Residency	H	207	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403231700000.pdf	Plastering of door and door frames and hardware
80324	Guinohar Residency	H	305	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403241700000.pdf	Plastering of door and door frames and hardware
80325	Guinohar Residency	H	402	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403251700000.pdf	Plastering of door and door frames and hardware
80326	Guinohar Residency	H	105	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403261700000.pdf	Plastering of door and door frames and hardware
80327	Guinohar Residency	H	304	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403271700000.pdf	Plastering of door and door frames and hardware
80328	Guinohar Residency	H	401	1600 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	3560	16-Dec-23					doc_553403281700000.pdf	Plastering of door and door frames and hardware
80329	Guinohar Residency	CA		0 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	0	34895	21-Nov-23					doc_553403291700000.pdf	Plastering of door and door frames and hardware
80330	Guinohar Residency	A	404	1360 Deepak kumar - Carpenter	Carpentry - Door Shutters & Hardware	2.6	10000	17-Dec-23					doc_553403301700000.pdf	Plastering of door and door frames and hardware
80331	Guinohar Residency	H	102	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403311700000.pdf	external plastering
80332	Guinohar Residency	H	103	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403321700000.pdf	external plastering
80333	Guinohar Residency	H	403	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403331700000.pdf	external plastering
80334	Guinohar Residency	H	9520	Rehni pandey	Civil - Brickwork & Plastering	1.86	7200	28-Oct-23					doc_553403341700000.pdf	external plastering
80335	Guinohar Residency	Club house		1547 Stee Srinivasa constructions	Civil - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403351700000.pdf	external plastering
80336	Guinohar Residency	Club house		1547 Stee Srinivasa constructions	Civil - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403361700000.pdf	external plastering
80337	Guinohar Residency	CA	202	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403371700000.pdf	external plastering
80338	Guinohar Residency	CA	502	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403381700000.pdf	external plastering
80339	Guinohar Residency	H	203	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403391700000.pdf	external plastering
80340	Guinohar Residency	H	303	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403401700000.pdf	external plastering
80341	Guinohar Residency	H	503	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403411700000.pdf	external plastering
80342	Guinohar Residency	H	9520	Rehni pandey	Civil - Brickwork & Plastering	1.86	7200	28-Oct-23					doc_553403421700000.pdf	external plastering
80343	Guinohar Residency	Club house		1547 Stee Srinivasa constructions	Civil - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403431700000.pdf	external plastering
80344	Guinohar Residency	Club house		1547 Stee Srinivasa constructions	Civil - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403441700000.pdf	external plastering
80345	Guinohar Residency	H	302	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403451700000.pdf	external plastering
80346	Guinohar Residency	H	602	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403461700000.pdf	external plastering
80347	Guinohar Residency	H	303	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403471700000.pdf	external plastering
80348	Guinohar Residency	H	603	1360 Kalish pandey - Civil Work	Civil - Brickwork & Plastering	3.3	44934	19-Dec-23					doc_553403481700000.pdf	external plastering
80349	Guinohar Residency	B		90400 Borela Murall - civil work	Civil Work - Brickwork & Plastering	1	99996	05-Dec-23					doc_553403491700000.pdf	external plastering
80350	Guinohar Residency	Club house		1547 Stee Srinivasa constructions	Civil Work - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403501700000.pdf	external plastering
80351	Guinohar Residency	G	405	1360 Borela Murall - civil work	Civil Work - Brickwork & Plastering	1.19	184019	26-Nov-23					doc_553403511700000.pdf	external plastering

80009	Guimohar Residency	CA	Upper Basement	31140 Rehu Pandey	Civil Work - Brickwork & Plastering	5.1	1,60,928	03-Nov-23	03-Nov-23	INR	doc_554460710c14.pdf	Upward plastering between blocks in & columns
80039	Guimohar Residency	C	Upper Basement	9600 Rehu Pandey	Civil Work - Brickwork & Plastering	3.5	34,592	03-Nov-23	03-Nov-23	INR	doc_5544608120bc.pdf	Civil works new block - ramp 1 & Upward plastering
80035	Guimohar Residency	D	Misc	0 Boreddy Murali - civil work	Civil Work - Brickwork & Plastering	0	39,800	07-Nov-23	07-Nov-23	INR	doc_554095571a019.pdf	A & B works in D Block and other misc works
80039	Guimohar Residency	Club house	IV floor	1447 Sree Srinivasa constructions	Civil Work - Brickwork & Plastering	634.4	5,81,437	26-Nov-23	26-Nov-23	INR	doc_554344e706181.pdf	Cubhouse 4th floor brickwork & internal plastering
80741	Guimohar Residency	D		407 1660 Bihni data - welder	Civil Work - LS	2.4	4,000	15-Dec-23	15-Dec-23	INR	doc_55710cab126528.pdf	Towards external plastering work and amount has to be debited from internal construction
80742	Guimohar Residency	D		604 1660 Bihni data - welder	Civil Work - LS	2.4	4,000	15-Dec-23	15-Dec-23	INR	doc_55710cab126528.pdf	Towards external plastering work and amount has to be debited from internal construction
80740	Guimohar Residency	D		403 1660 Bihni data - welder	Civil Work - LS	2.4	4,000	15-Dec-23	15-Dec-23	INR	doc_55710cab126528.pdf	Towards external plastering work and amount has to be debited from internal construction
80139	Guimohar Residency	Misc	Misc	31540 Krishna	Civil Work - Misc.	0.7	20,800	11-Nov-23	11-Nov-23	INR	doc_554724d1395d.pdf	Towards the compound wall brick work and plastering
80739	Guimohar Residency	D		502 1660 Bihni data - welder	Civil Work - Misc.	2.4	4,000	15-Dec-23	15-Dec-23	INR	doc_55710cab126528.pdf	Towards external plastering work and amount has to be debited from internal construction
80769	Guimohar Residency	CA	CA	0 Bihni data - welder	Civil Work - Misc.	0	15,000	16-Dec-23	16-Dec-23	INR	doc_55710cab126528.pdf	Towards external plastering work and amount has to be debited from internal construction
80432	Guimohar Residency	B		102 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55710cab126528.pdf	Bund making on top flooring new F.O.H
80112	Guimohar Residency	H		604 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80435	Guimohar Residency	B		402 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80115	Guimohar Residency	H		607 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80109	Guimohar Residency	H		502 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80436	Guimohar Residency	B		107 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80106	Guimohar Residency	H		505 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80431	Guimohar Residency	B		407 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80109	Guimohar Residency	H		601 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80110	Guimohar Residency	H		602 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80433	Guimohar Residency	B		202 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80113	Guimohar Residency	H		605 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80434	Guimohar Residency	B		502 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80104	Guimohar Residency	H		503 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80432	Guimohar Residency	B		207 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80433	Guimohar Residency	B		507 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80107	Guimohar Residency	H		506 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80111	Guimohar Residency	H		603 1360 Kailash Pandey - Civil Work	Civil Work - Turn key	82.5	1,12,336	06-Nov-23	06-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work
80434	Guimohar Residency	B		302 1660 Sree Srinivasa constructions	Civil Work - Turn key	40.9	67,872	28-Nov-23	28-Nov-23	INR	doc_55450d61937b9.pdf	Bill ID is 2277 B block external plastering work

PROJECT MANAGER
14 NOV 2023

80214	Guinohar Residency	H	606	1360	Kailash pandey - Civil Work	Civil Work - Turn Key	82.6	1:12.36	06-Nov-23	06-Nov-23	NR	doc_555d8f9c11f.pdf	Towards the interior partitioning work of the 606 flat
80220	Guinohar Residency	H	501	1600	Kailash pandey - Civil Work	Civil Work - Turn Key	82.6	1:12.36	06-Nov-23	06-Nov-23	NR	doc_555d8f9c12a.pdf	Towards the interior partitioning work of the 501 flat
80277	Guinohar Residency	B	602	1600	Preethi Srinivas constructions	Civil Work - Turn Key	40.3	67.872	28-Nov-23	28-Nov-23	NR	doc_555d8f9c13a.pdf	Flat ID is 22777 Block external partitioning work flats 102,103,104,105,106,107,108,109,110,111,112,113,114,115,116,117,118,119,120,121,122,123,124,125,126,127,128,129,130,131,132,133,134,135,136,137,138,139,140,141,142,143,144,145,146,147,148,149,150,151,152,153,154,155,156,157,158,159,160,161,162,163,164,165,166,167,168,169,170,171,172,173,174,175,176,177,178,179,180,181,182,183,184,185,186,187,188,189,190,191,192,193,194,195,196,197,198,199,200,201,202,203,204,205,206,207,208,209,210,211,212,213,214,215,216,217,218,219,220,221,222,223,224,225,226,227,228,229,230,231,232,233,234,235,236,237,238,239,240,241,242,243,244,245,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260,261,262,263,264,265,266,267,268,269,270,271,272,273,274,275,276,277,278,279,280,281,282,283,284,285,286,287,288,289,290,291,292,293,294,295,296,297,298,299,300,301,302,303,304,305,306,307,308,309,310,311,312,313,314,315,316,317,318,319,320,321,322,323,324,325,326,327,328,329,330,331,332,333,334,335,336,337,338,339,340,341,342,343,344,345,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360,361,362,363,364,365,366,367,368,369,370,371,372,373,374,375,376,377,378,379,380,381,382,383,384,385,386,387,388,389,390,391,392,393,394,395,396,397,398,399,400,401,402,403,404,405,406,407,408,409,410,411,412,413,414,415,416,417,418,419,420,421,422,423,424,425,426,427,428,429,430,431,432,433,434,435,436,437,438,439,440,441,442,443,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458,459,460,461,462,463,464,465,466,467,468,469,470,471,472,473,474,475,476,477,478,479,480,481,482,483,484,485,486,487,488,489,490,491,492,493,494,495,496,497,498,499,500,501,502,503,504,505,506,507,508,509,510,511,512,513,514,515,516,517,518,519,520,521,522,523,524,525,526,527,528,529,530,531,532,533,534,535,536,537,538,539,540,541,542,543,544,545,546,547,548,549,550,551,552,553,554,555,556,557,558,559,560,561,562,563,564,565,566,567,568,569,570,571,572,573,574,575,576,577,578,579,580,581,582,583,584,585,586,587,588,589,590,591,592,593,594,595,596,597,598,599,600,601,602,603,604,605,606,607,608,609,610,611,612,613,614,615,616,617,618,619,620,621,622,623,624,625,626,627,628,629,630,631,632,633,634,635,636,637,638,639,640,641,642,643,644,645,646,647,648,649,650,651,652,653,654,655,656,657,658,659,660,661,662,663,664,665,666,667,668,669,670,671,672,673,674,675,676,677,678,679,680,681,682,683,684,685,686,687,688,689,690,691,692,693,694,695,696,697,698,699,700,701,702,703,704,705,706,707,708,709,710,711,712,713,714,715,716,717,718,719,720,721,722,723,724,725,726,727,728,729,730,731,732,733,734,735,736,737,738,739,740,741,742,743,744,745,746,747,748,749,750,751,752,753,754,755,756,757,758,759,760,761,762,763,764,765,766,767,768,769,770,771,772,773,774,775,776,777,778,779,780,781,782,783,784,785,786,787,788,789,790,791,792,793,794,795,796,797,798,799,800,801,802,803,804,805,806,807,808,809,810,811,812,813,814,815,816,817,818,819,820,821,822,823,824,825,826,827,828,829,830,831,832,833,834,835,836,837,838,839,840,841,842,843,844,845,846,847,848,849,850,851,852,853,854,855,856,857,858,859,860,861,862,863,864,865,866,867,868,869,870,871,872,873,874,875,876,877,878,879,880,881,882,883,884,885,886,887,888,889,890,891,892,893,894,895,896,897,898,899,900,901,902,903,904,905,906,907,908,909,910,911,912,913,914,915,916,917,918,919,920,921,922,923,924,925,926,927,928,929,930,931,932,933,934,935,936,937,938,939,940,941,942,943,944,945,946,947,948,949,950,951,952,953,954,955,956,957,958,959,960,961,962,963,964,965,966,967,968,969,970,971,972,973,974,975,976,977,978,979,980,981,982,983,984,985,986,987,988,989,990,991,992,993,994,995,996,997,998,999,1000,1001,1002,1003,1004,1005,1006,1007,

3

80058	Guimohar Residency	C		1601 N. Rupnaraina Reddy	Electrical - Inside flat	2.1	3,500	08-Dec-23	08-Dec-23	INR	doc_55127231564886.pdf	Spent the month doing works in C-602 flat @ 1600 P.C.
80059	Guimohar Residency	H	304	1360 N. Rupnaraina Reddy	Electrical - Inside flat	2.6	3,500	23-Nov-23	23-Nov-23	INR	doc_55127231564886.pdf	Spent the month doing works in C-602 flat @ 1360 P.C.
80060	Guimohar Residency	H	307	1360 B. Thirupathi Saly - Electrical work	Electrical - Inside flat	5.1	7,000	22-Dec-23	22-Dec-23	INR	doc_55127231564886.pdf	H Block flat inside electrical works done
80061	Guimohar Residency	C	504	1600 B. Thirupathi Saly - Electrical work	Electrical - Inside flat	4.8	8,000	22-Dec-23	22-Dec-23	INR	doc_55127231564886.pdf	H Block flat inside electrical works done
80062	Guimohar Residency	C		0 B. Thirupathi Saly - Electrical work	Electrical - Inside flat	0	20,000	14-Dec-23	14-Dec-23	INR	doc_55127231564886.pdf	C and D blocks inside electrical works done
80063	Guimohar Residency	A		13600 N. Nagarajulu - Electrical	Electrical - LS	0.1	16,400	30-Dec-23	30-Dec-23	INR	doc_55127231564886.pdf	Inside electrical works done
80064	Guimohar Residency	C	107	1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	2.4	4,000	18-Oct-23	18-Oct-23	INR	doc_55127231564886.pdf	A 7 B Block (17th floor) and 18th floor (17th floor)
80065	Guimohar Residency	C	401	1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	0.1	7,000	17-Nov-23	17-Nov-23	INR	doc_55127231564886.pdf	G Block 7th floor (17th floor) done
80066	Guimohar Residency	C	204	1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	2.4	4,000	18-Oct-23	18-Oct-23	INR	doc_55127231564886.pdf	G Block 7th floor (17th floor) done
80067	Guimohar Residency	C	104	1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	0.3	24,200	31-Oct-23	31-Oct-23	INR	doc_55127231564886.pdf	C Block 7th floor (17th floor) done
80068	Guimohar Residency	C	403	1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	2.4	4,000	18-Oct-23	18-Oct-23	INR	doc_55127231564886.pdf	C Block 7th floor (17th floor) done
80069	Guimohar Residency	G		1600 B. Thirupathi Saly - Electrical work	Electrical - MISC	0.7	9,300	30-Dec-23	30-Dec-23	INR	doc_55127231564886.pdf	A 7 B Block (17th floor) and 18th floor (17th floor)
80070	Guimohar Residency	CA		0 B. Thirupathi Saly - Electrical work	Electrical - MISC	0	15,216	19-Dec-23	19-Dec-23	INR	doc_55127231564886.pdf	Inside electrical works done
80071	Guimohar Residency	H		57120 N. Nagarajulu - Fire safety	Fire safety	2.9	1,62,400	03-Oct-23	03-Oct-23	INR	doc_55127231564886.pdf	Inside electrical works done
80072	Guimohar Residency	Club house		10820 Sali Kumar - Fire safety	Fire safety	3	32,775	16-Oct-23	16-Oct-23	INR	doc_55127231564886.pdf	Inside electrical works done
80073	Guimohar Residency	Club house		10820 Sali Kumar - Fire safety	Fire safety	4.5	48,367	26-Dec-23	26-Dec-23	INR	doc_55127231564886.pdf	Inside electrical works done
80074	Guimohar Residency	C	601	1600 Voulai All - False ceiling	False Ceiling	28.1	46,623	06-Oct-23	06-Oct-23	INR	doc_55127231564886.pdf	Towards the top floor C-602, false ceiling work
80075	Guimohar Residency	A	209	13600 Voulai All - False ceiling	False Ceiling	0.2	22,863	28-Nov-23	28-Nov-23	INR	doc_55127231564886.pdf	Work completed
80076	Guimohar Residency	A		13600 Voulai All - False ceiling	False Ceiling	15.1	20,569	25-Nov-23	25-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80077	Guimohar Residency	G		57120 Voulai All - False ceiling	False Ceiling	0.5	28,084	06-Oct-23	06-Oct-23	INR	doc_55127231564886.pdf	Work completed
80078	Guimohar Residency	H	507	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80079	Guimohar Residency	H	603	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80080	Guimohar Residency	H	403	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80081	Guimohar Residency	H	606	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80082	Guimohar Residency	H	406	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80083	Guimohar Residency	H	502	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80084	Guimohar Residency	H	505	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80085	Guimohar Residency	H	601	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80086	Guimohar Residency	H	604	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80087	Guimohar Residency	H	401	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80088	Guimohar Residency	H	604	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80089	Guimohar Residency	H	404	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80090	Guimohar Residency	H	607	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80091	Guimohar Residency	H	407	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80092	Guimohar Residency	H	503	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80093	Guimohar Residency	H	506	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)
80094	Guimohar Residency	H	602	1360 Piyasini Devi - Tiles work	Grantee Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	INR	doc_55127231564886.pdf	Towards the top floor false ceiling work of G Block (16th - 18th floor)

APPROVED BY
 14 MAY 2024
 PROJECT MANAGER

80033	Gulmohar Residency	H	402	1360 Piyasha Devi - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321ca1c40b5.pdf	Towards north, balcony, edge wall granite work in H-402
80030	Gulmohar Residency	H	605	1360 Piyasha Devi - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321b19b05.pdf	Towards north, balcony, edge wall granite work in H-405
80038	Gulmohar Residency	H	405	1360 Piyasha Devi - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321d0305d4c.pdf	Towards north, balcony, edge wall granite work in H-402
80039	Gulmohar Residency	H	501	1360 Piyasha Devi - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321d0305d4c.pdf	Towards north, balcony, edge wall granite work in H-501
80042	Gulmohar Residency	H	504	1360 Piyasha Devi - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321d0305d4c.pdf	Towards north, balcony, edge wall granite work in H-504
80087	Gulmohar Residency	Club House		10620 Mahaveer Gurjar - Tiles work	Granite Work - Kitchen Platform	8.1	11,000	01-Nov-23	01-Nov-23	NR	doc_554321d0305d4c.pdf	Towards north, balcony, edge wall granite work in H-504
80088	Gulmohar Residency	G		57120 Jaranthan Prasad (Ties)	Granite Work - Misc.	0.5	42,372	26-Dec-23	26-Dec-23	NR	doc_55504b9c953307.pdf	Clubhouse lift staircase work
80088	Gulmohar Residency	B		90400 Mahadeva Kumar Gurjar - Tiles	Granite Work - Misc.	0.3	30,492	05-Dec-23	05-Dec-23	NR	doc_55504b9c953307.pdf	Clubhouse lift staircase work
80120	Gulmohar Residency	CA		0 Kotturu Rani - Earthwork	Grading	0	26,136	06-Nov-23	06-Nov-23	NR	doc_55504b9c953307.pdf	G Block Granite works for passenger lift works done
80047	Gulmohar Residency	C		9600 Kotturu Rani - Earthwork	Grading	0	9,796	06-Nov-23	06-Nov-23	NR	doc_55504b9c953307.pdf	B Block 3 rd lift works done
80079	Gulmohar Residency	B		9040 B. Thirupathi Raju - Electrical work	Holes Drilling on rock	1.5	14,001	29-Nov-23	29-Nov-23	NR	doc_55504b9c953307.pdf	Clubhouse, C Block ramp, Club driveway shed 2 landing works
80046	Gulmohar Residency	H		0 Bohni Naveen Kumar - painter	Painting - Corridors	0	12,780	22-Dec-23	22-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80045	Gulmohar Residency	All floors		10620 A Barsha - Painting work	Painting - External	0	91,052	23-Nov-23	23-Nov-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80132	Gulmohar Residency	F		48860 Narsing Rao - Painting	Painting - External	0.7	1,12,867	04-Dec-23	04-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80131	Gulmohar Residency	F		48860 Narsing Rao - Painting	Painting - External	0.7	35,161	09-Nov-23	09-Nov-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80078	Gulmohar Residency	H	207	1360 Narsing Rao - Painting	Painting - External	2.2	1,09,570	09-Nov-23	09-Nov-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
81011	Gulmohar Residency	G	402	1360 Vivek Kumar - painter	Painting - Inside flat	7.5	10,270	02-Nov-23	02-Nov-23	NR	doc_554321b19b05.pdf	Block C - Lower basement floor flooring work
80089	Gulmohar Residency	C	601	1660 G Surjitha - Painting	Painting - Inside flat	11.2	15,232	31-Dec-23	31-Dec-23	NR	doc_554321b19b05.pdf	Block C - Lower basement floor flooring work
81014	Gulmohar Residency	G	501	1360 Vivek Kumar - painter	Painting - Inside flat	11.2	18,592	22-Dec-23	22-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
81017	Gulmohar Residency	G	504	1360 Vivek Kumar - painter	Painting - Inside flat	11.2	15,232	31-Dec-23	31-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
81020	Gulmohar Residency	G	507	1360 Vivek Kumar - painter	Painting - Inside flat	11.2	15,232	31-Dec-23	31-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
79661	Gulmohar Residency	C	102	1660 G Surjitha - Painting	Painting - Inside flat	9	13,380	03-Oct-23	03-Oct-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80085	Gulmohar Residency	H	601	1360 Bohni Naveen Kumar - painter	Painting - Inside flat	7.5	10,270	01-Nov-23	01-Nov-23	NR	doc_554321b19b05.pdf	Block C - Lower basement floor flooring work
81021	Gulmohar Residency	G	603	1360 Vivek Kumar - painter	Painting - Inside flat	11.2	15,232	31-Dec-23	31-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
79665	Gulmohar Residency	B	101	1660 G Surjitha - Painting	Painting - Inside flat	8	13,380	03-Oct-23	03-Oct-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80666	Gulmohar Residency	G	103	1360 Vivek Kumar - painter	Painting - Inside flat	8	10,880	30-Dec-23	30-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80660	Gulmohar Residency	H	303	1360 Hanurath - Painting	Painting - Inside flat	12.8	17,408	06-Dec-23	06-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
79872	Gulmohar Residency	F	101	1360 Shoba Ram - Painting	Painting - Inside flat	12.8	17,408	06-Dec-23	06-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80086	Gulmohar Residency	H	606	1360 Bohni Naveen Kumar - painter	Painting - Inside flat	7.5	10,270	01-Nov-23	01-Nov-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80670	Gulmohar Residency	G	305	1360 Vivek Kumar - painter	Painting - Inside flat	8	10,880	30-Dec-23	30-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80655	Gulmohar Residency	F	304	1360 Hanurath - Painting	Painting - Inside flat	12.8	17,408	06-Dec-23	06-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
79876	Gulmohar Residency	F	304	1360 Shoba Ram - Painting	Painting - Inside flat	12.8	17,408	06-Dec-23	06-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80081	Gulmohar Residency	H	501	1360 Bohni Naveen Kumar - painter	Painting - Inside flat	7.1	9,709	01-Nov-23	01-Nov-23	NR	doc_554321b19b05.pdf	Block C - Lower basement floor flooring work
80678	Gulmohar Residency	H	607	1360 Bohni Naveen Kumar - painter	Painting - Inside flat	7.5	10,270	01-Nov-23	01-Nov-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
80678	Gulmohar Residency	H	102	1360 Bohni Naveen Kumar - painter	Painting - Inside flat	12.8	17,408	06-Dec-23	06-Dec-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work
79682	Gulmohar Residency	H		57120 Bohni Naveen Kumar - painter	Painting - Inside flat	0.4	25,134	05-Oct-23	05-Oct-23	NR	doc_55504b9c953307.pdf	Block C - Lower basement floor flooring work

APPROVED BY
24 MAY 2024
PROJECT MANAGER

80073	Guimotari Residency	G	403	1360 Vivek Kumar - painter	Painting - inside flat	8	10,880	30-Dec-23	30-Dec-23	INR	doc_5539962c5f1b5.pdf	Painting - inside flat for stage 3 works completed
80000	Guimotari Residency	F	404	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
79879	Guimotari Residency	F	501	1360 Shoba Ram - Painting	Painting - inside flat	8	10,880	18-Oct-23	18-Oct-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80088	Guimotari Residency	D	303	1660 Hanumath (Painting)	Painting - inside flat	8	10,880	04-Dec-23	04-Dec-23	INR	doc_556063e3324d0.pdf	D Block Final Painting
80084	Guimotari Residency	H	504	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.1	9,709	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H-Block 2nd coat upturn work @ H-504 flat
80083	Guimotari Residency	H	201	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80085	Guimotari Residency	B	303	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
79882	Guimotari Residency	F	301	1360 Shoba Ram - Painting	Painting - inside flat	3	10,880	18-Oct-23	18-Oct-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80082	Guimotari Residency	D	308	1660 Hanumath (Painting)	Painting - inside flat	8	10,880	04-Dec-23	04-Dec-23	INR	doc_556063e3324d0.pdf	D Block Final Painting
80087	Guimotari Residency	H	507	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.1	9,709	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H-Block 2nd coat upturn work @ H-507 flat
80088	Guimotari Residency	B	403	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80073	Guimotari Residency	H	105	1360 Narsing Rao - Painting	Painting - inside flat	7.5	10,270	02-Nov-23	02-Nov-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80026	Guimotari Residency	C	501	1660 G.Suritha - Painting	Painting - inside flat	7.5	11,621	02-Nov-23	02-Nov-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80091	Guimotari Residency	B	603	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80075	Guimotari Residency	H	203	1360 Narsing Rao - Painting	Painting - inside flat	7.5	10,270	02-Nov-23	02-Nov-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80029	Guimotari Residency	B	501	1660 G.Suritha - Painting	Painting - inside flat	7.5	11,621	02-Nov-23	02-Nov-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80087	Guimotari Residency	B	501	1660 G.Suritha - Painting	Painting - inside flat	7.5	11,621	02-Nov-23	02-Nov-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
81012	Guimotari Residency	G	403	1360 Vivek Kumar - painter	Painting - inside flat	9.7	13,232	31-Dec-23	31-Dec-23	INR	doc_5500773b811.pdf	G Block painting work for stage 2 works 35 % all works completed
81015	Guimotari Residency	G	502	1360 Vivek Kumar - painter	Painting - inside flat	11.2	15,232	31-Dec-23	31-Dec-23	INR	doc_5500773b811.pdf	G Block painting work for stage 2 works 35 % all works completed
81018	Guimotari Residency	G	505	1360 Vivek Kumar - painter	Painting - inside flat	11.2	15,232	31-Dec-23	31-Dec-23	INR	doc_5500773b811.pdf	G Block painting work for stage 2 works 35 % all works completed
81021	Guimotari Residency	G	601	1360 Vivek Kumar - painter	Painting - inside flat	11.2	15,232	31-Dec-23	31-Dec-23	INR	doc_5500773b811.pdf	G Block painting work for stage 2 works 35 % all works completed
79663	Guimotari Residency	C	103	1660 G.Suritha - Painting	Painting - inside flat	8	13,280	03-Oct-23	03-Oct-23	INR	doc_5510d44758849.pdf	C Block inside flat final 75% painting work completed
80086	Guimotari Residency	H	204	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80086	Guimotari Residency	H	603	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.5	10,270	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H Block 2nd coat upturn work @ H-603 flat
80086	Guimotari Residency	H	602	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.5	10,270	24-Nov-23	24-Nov-23	INR	doc_554273807b643.pdf	H Block 2nd coat upturn work @ H-602 flat
80039	Guimotari Residency	H		0 Narsing Rao - Painting	Painting - inside flat	0	1,23,246	21-Nov-23	21-Nov-23	INR	doc_5554d4e85a0b.pdf	1st coat upturn painting 8 in H-305,306,307,405,406 & 407 flats
81024	Guimotari Residency	G	607	1360 Vivek Kumar - painter	Painting - inside flat	11.2	15,232	31-Dec-23	31-Dec-23	INR	doc_5500773b811.pdf	G Block painting work for stage 2 works 35 % all works completed
79666	Guimotari Residency	B	407	1660 G.Suritha - Painting	Painting - inside flat	8	13,280	03-Oct-23	03-Oct-23	INR	doc_5510d44758849.pdf	C Block inside flat final 75% painting work completed
80097	Guimotari Residency	G	207	1360 Vivek Kumar - painter	Painting - inside flat	3	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80091	Guimotari Residency	H	302	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
79873	Guimotari Residency	F	104	1360 Shoba Ram - Painting	Painting - inside flat	8	10,880	18-Oct-23	18-Oct-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80095	Guimotari Residency	H	606	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.5	10,270	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H Block 2nd coat upturn work @ H-606 flat
80094	Guimotari Residency	H	605	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.5	10,270	24-Nov-23	24-Nov-23	INR	doc_554273807b643.pdf	H Block 2nd coat upturn work @ H-605 flat
80097	Guimotari Residency	G	402	1360 Vivek Kumar - painter	Painting - inside flat	8	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80098	Guimotari Residency	F	402	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
79877	Guimotari Residency	F	305	1360 Shoba Ram - Painting	Painting - inside flat	8	10,880	18-Oct-23	18-Oct-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80081	Guimotari Residency	H	502	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.1	9,709	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H-Block 2nd coat upturn work @ H-502 flat
80079	Guimotari Residency	H	103	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done
80082	Guimotari Residency	G	505	1360 Vivek Kumar - painter	Painting - inside flat	8	10,880	30-Dec-23	30-Dec-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
79880	Guimotari Residency	F	504	1360 Shoba Ram - Painting	Painting - inside flat	8	10,880	18-Oct-23	18-Oct-23	INR	doc_5579561c65391.pdf	H Block Stage 1 40% bill work done
80090	Guimotari Residency	D	305	1360 Hanumath (Painting)	Painting - inside flat	8	10,880	04-Dec-23	04-Dec-23	INR	doc_556063e3324d0.pdf	D Block Final Painting
80095	Guimotari Residency	H	505	1360 Rohini Naveen Kumar - painter	Painting - inside flat	7.1	9,709	01-Nov-23	01-Nov-23	INR	doc_554273807b643.pdf	H-Block 2nd coat upturn work @ H-505 flat
80081	Guimotari Residency	H	202	1360 Hanumath (Painting)	Painting - inside flat	12.8	17,408	06-Dec-23	06-Dec-23	INR	doc_5570581a7a506.pdf	H Block Stage 1 40% bill work done

16 MAY 2024
PROJECT MANAGER

80386	Guinohar Residency	B	406	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	Painting - inside flat for Stage 3 works completed final 25%
80383	Guinohar Residency	A	309	1360 Hanuath (Painting)	Painting - inside flat	9.3	11.290	04-Dec-23	04-Dec-23	NR	doc_5356451380766.pdf	A Block final coat of paint for works completed final 25%
80389	Guinohar Residency	B	503	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	Painting - inside flat for Stage 3 works completed final 25%
80074	Guinohar Residency	H	106	1360 Narsing Rao - Painting	Painting - inside flat	7.5	10.270	02-Nov-23	02-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80077	Guinohar Residency	C	106	1360 Narsing Rao - Painting	Painting - inside flat	7.5	10.270	02-Nov-23	02-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80085	Guinohar Residency	C	604	1660 G Surtha - Painting	Painting - inside flat	8	13.280	22-Dec-23	22-Dec-23	NR	doc_53580f66772.pdf	C Block 1st coat of paint for works completed final 25%
80737	Guinohar Residency	C	All floors	96000 Narsing Rao - Painting	Painting - inside flat	1.5	15.0318	14-Dec-23	14-Dec-23	NR	doc_53580f66772.pdf	Interior paint work for Stage 3 works completed final 25%
80504	Guinohar Residency	D	Misc	0 Hanuath (Painting)	Painting - inside flat	D	66.480	06-Dec-23	06-Dec-23	NR	doc_5356451380766.pdf	A B D Blocks water proofing work for Stage 3 works completed final 25%
80077	Guinohar Residency	H	206	1360 Narsing Rao - Painting	Painting - inside flat	7.5	10.270	02-Nov-23	02-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80030	Guinohar Residency	V floor	1347	1347 Hanuath (Painting)	Painting - inside flat	23.2	33.880	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	Guinohar 1347 Hanuath (Painting) all works completed final 25%
81010	Guinohar Residency	G	304	1360 Vivek Kumar - Painter	Painting - inside flat	11.2	15.232	31-Dec-23	31-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
80088	Guinohar Residency	C	504	1660 G Surtha - Painting	Painting - inside flat	11.2	18.592	22-Dec-23	22-Dec-23	NR	doc_53580f66772.pdf	C Block 1st coat of paint for works completed final 25%
81013	Guinohar Residency	G	404	1360 Vivek Kumar - Painter	Painting - inside flat	11.2	15.232	31-Dec-23	31-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
81016	Guinohar Residency	G	503	1360 Vivek Kumar - Painter	Painting - inside flat	11.2	15.232	31-Dec-23	31-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
81019	Guinohar Residency	G	506	1360 Vivek Kumar - Painter	Painting - inside flat	11.2	15.232	31-Dec-23	31-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
80034	Guinohar Residency	H	601	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.5	10.270	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
81022	Guinohar Residency	G	604	1360 Vivek Kumar - Painter	Painting - inside flat	11.2	15.232	31-Dec-23	31-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
79654	Guinohar Residency	C	104	1660 G Surtha - Painting	Painting - inside flat	3	13.280	03-Oct-23	03-Oct-23	NR	doc_5310d5f9f0c1b.pdf	C Block 1st coat of paint for works completed final 25%
80508	Guinohar Residency	H	301	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
80027	Guinohar Residency	H	604	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.5	10.270	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80062	Guinohar Residency	H	603	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	52.3	71.880	24-Nov-23	24-Nov-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
79657	Guinohar Residency	B	308	1660 G Surtha - Painting	Painting - inside flat	3	13.280	03-Oct-23	03-Oct-23	NR	doc_5310d5f9f0c1b.pdf	C Block 1st coat of paint for works completed final 25%
80069	Guinohar Residency	G	301	1360 Vivek Kumar - Painter	Painting - inside flat	3	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
80553	Guinohar Residency	H	304	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
79874	Guinohar Residency	F	106	1360 Shoba Ram - Painting	Painting - inside flat	8	10.880	18-Oct-23	18-Oct-23	NR	doc_53580f66772.pdf	F Block 1st coat of paint for works completed final 25%
80454	Guinohar Residency	Club house		1547 Hanuath (Painting)	Painting - inside flat	38.5	59.590	04-Dec-23	04-Dec-23	NR	doc_53580f66772.pdf	Clubhouse 1st coat of paint for works completed final 25%
80060	Guinohar Residency	H	607	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.5	10.270	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80065	Guinohar Residency	H	606	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.5	10.270	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80071	Guinohar Residency	H	101	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
80072	Guinohar Residency	G	504	1360 Vivek Kumar - Painter	Painting - inside flat	3	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	G Block 1st coat of paint for works completed final 25%
80506	Guinohar Residency	H	403	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
79872	Guinohar Residency	F	404	1360 Shoba Ram - Painting	Painting - inside flat	8	10.880	18-Oct-23	18-Oct-23	NR	doc_53580f66772.pdf	F Block 1st coat of paint for works completed final 25%
80065	Guinohar Residency	H	503	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.1	9.709	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80261	Guinohar Residency	H	104	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
80384	Guinohar Residency	B	106	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	B Block 1st coat of paint for works completed final 25%
79883	Guinohar Residency	F	601	1360 Shoba Ram - Painting	Painting - inside flat	3	10.880	18-Oct-23	18-Oct-23	NR	doc_53580f66772.pdf	F Block 1st coat of paint for works completed final 25%
80493	Guinohar Residency	D	306	1660 Hanuath (Painting)	Painting - inside flat	8	13.280	04-Dec-23	04-Dec-23	NR	doc_53580f66772.pdf	D Block 1st coat of paint for works completed final 25%
80066	Guinohar Residency	H	506	1360 Bohini Naveen Kumar - Painter	Painting - inside flat	7.1	9.709	01-Nov-23	01-Nov-23	NR	doc_53436f6645138.pdf	H Block 1st coat of paint for works completed final 25%
80064	Guinohar Residency	H	203	1360 Hanuath (Painting)	Painting - inside flat	12.3	17.408	06-Dec-23	06-Dec-23	NR	doc_53580f66772.pdf	H Block 1st coat of paint for works completed final 25%
80087	Guinohar Residency	B	306	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	B Block 1st coat of paint for works completed final 25%
79112	Guinohar Residency	H	All floors	57120 Hanuath (Painting)	Painting - inside flat	1.1	32.717	07-Oct-23	07-Oct-23	NR	doc_53580f66772.pdf	Interior paint work for Stage 3 works completed final 25%
80090	Guinohar Residency	B	506	1660 Shoba Ram - Painting	Painting - inside flat	6.5	10.880	30-Dec-23	30-Dec-23	NR	doc_53580f66772.pdf	B Block 1st coat of paint for works completed final 25%

APPROVED BY
19 MAY 2024
PROJECT MANAGER

80071 Gulmohar Residency	H	604	1360 Shaik Moiz	Plumbing inside flat	3.4	4.650	01-Nov-23	01-Nov-23	doc_554274ec81808.pdf	H-block plumbing inside flat work @ H-604 flat.
80053 Gulmohar Residency	F	505	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_5515715d5eaa0.pdf	Plumbing works inside flats
80017 Gulmohar Residency	A	401	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_551441130c43.pdf	Plumbing final fitting works started inside flat
80020 Gulmohar Residency	A	509	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_551453969e41.pdf	Plumbing final fitting works started inside flat
79914 Gulmohar Residency	H	506	1360 Mohammed Khudosa - Plumbing	Plumbing inside flat	3.4	4.650	07-Oct-23	07-Oct-23	doc_55140244240e6.pdf	H-506 flat internal plumbing work.
80033 Gulmohar Residency	B	506	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_55146139ae28.pdf	Plumbing final fitting works started inside flat
80036 Gulmohar Residency	C	307	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_551440e0c07b.pdf	Plumbing final fitting works started inside flat
80030 Gulmohar Residency	C	605	1360 Mohammed Khudosa - Plumbing	Plumbing inside flat	3.4	4.650	02-Nov-23	02-Nov-23	doc_5514317c1f592.pdf	Internal plumbing work at H-605 flat.
80033 Gulmohar Residency	C	403	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_5514054a8eac.pdf	Plumbing work inside flats
80036 Gulmohar Residency	D	205	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_5514530b973.pdf	Plumbing work inside flats
80042 Gulmohar Residency	D	304	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_551433355172.pdf	Plumbing work inside flats
79915 Gulmohar Residency	D	507	1660 Shaik Jena	Plumbing inside flat	1.9	3.100	07-Dec-23	07-Dec-23	doc_55145411d40d.pdf	Plumbing work inside flats
80045 Gulmohar Residency	F	308	1660 Mohammed Khudosa - Plumbing	Plumbing inside flat	1.9	3.100	25-Oct-23	25-Oct-23	doc_5514079e4a21.pdf	Plumbing final fitting
80012 Gulmohar Residency	A	106	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_55145544a069.pdf	Plumbing work inside flats
80069 Gulmohar Residency	H	602	1360 Shaik Moiz	Plumbing inside flat	3.4	4.650	01-Nov-23	01-Nov-23	doc_5514211f09b0.pdf	Plumbing final fitting works done inside flat
80050 Gulmohar Residency	F	501	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_5514244c8b80.pdf	H-Block plumbing inside flat work @ H-602 flat.
80015 Gulmohar Residency	A	304	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_5514374e481.pdf	Plumbing work inside flats
80018 Gulmohar Residency	A	405	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_5514474033d4.pdf	Plumbing final fitting works started inside flat
80021 Gulmohar Residency	A	502	1360 Shaik Jena	Plumbing inside flat	2.3	3.100	07-Dec-23	07-Dec-23	doc_551451f29987.pdf	Plumbing final fitting works started inside flat
79915 Gulmohar Residency	H	507	1360 Mohammed Khudosa - Plumbing	Plumbing inside flat	3.4	4.650	07-Oct-23	07-Oct-23	doc_551456f4c949.pdf	H-507 flat internal plumbing work.
80026 Gulmohar Residency	A	209	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80071 Gulmohar Residency	B	604	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80074 Gulmohar Residency	C	501	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80077 Gulmohar Residency	C	306	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80070 Gulmohar Residency	Misc		31540 Sandeep Kumar - Polishing	Polishing	0.9	1.300	04-Dec-23	04-Dec-23	doc_5514685179813.pdf	All works done
80073 Gulmohar Residency	C	501	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80076 Gulmohar Residency	B	605	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80079 Gulmohar Residency	C	204	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80072 Gulmohar Residency	B	603	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80075 Gulmohar Residency	C	401	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80078 Gulmohar Residency	C	601	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80081 Gulmohar Residency	C	606	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80074 Gulmohar Residency	B	601	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80077 Gulmohar Residency	B	204	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80079 Gulmohar Residency	D	501	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
80073 Gulmohar Residency	C	604	1660 Sandeep Kumar - Polishing	Polishing	0.8	1.300	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	All works done
79907 Gulmohar Residency	C		96000 Sandeep Kumar - Polishing	Polishing	0.4	3.300	07-Oct-23	07-Oct-23	doc_551453180x89.pdf	Towards the 2nd coat remaining door polishing of B, C, and D blocks 35 flats
80072 Gulmohar Residency	A	204	1360 Sandeep Kumar - Polishing	Polishing	1	1.300	27-Nov-23	27-Nov-23	doc_5514685179813.pdf	All works done
80015 Gulmohar Residency	CA		O O Velesh	RCC - Misc.	1	5.500	16-Dec-23	16-Dec-23	doc_5514685179813.pdf	Minor works done near Northern driveway
80026 Gulmohar Residency	CA		O SSM centring contractors - RCC	RCC - Misc.	1	2.11.466	06-Dec-23	06-Dec-23	doc_5514685179813.pdf	H-block northern driveway slab @ 114.4 m
80029 Gulmohar Residency	CA		O SSM centring contractors - RCC	RCC - Misc.	1	3.17.866	06-Dec-23	06-Dec-23	doc_5514685179813.pdf	Centering & casting
79909 Gulmohar Residency	Club house		1547 B Mani - Electrician	RCC - Misc.	20.3	31.470	25-Oct-23	25-Oct-23	doc_5514685179813.pdf	Clubhouse ramp slab 2 - electrical locksetting work
80024 Gulmohar Residency	CA		O SSM centring contractors - RCC	RCC - Misc.	1				doc_5514685179813.pdf	Between 6&8th block upperment column casting

PROJECT MANAGER

80267 Guimohar Residency	H		105	1360 New Chand - Tiles	24	32,600	24-Nov-23	24-Nov-23	doc_5550008_misran.pdf	The laying work @ m 125
81003 Guimohar Residency	H		303	1360 Janadhan prasad (Tiles)	23.7	32,265	30-Dec-23	30-Dec-23	doc_5550006_misran.pdf	Finishing the inside wall of G Block & G2
80295 Guimohar Residency	G		407	1360 Mahaveer Gurjar - Tiles	21.8	29,682	17-Nov-23	17-Nov-23	doc_55501715_misran.pdf	G 407 flat floor - masonry stone m. part - masonry
81007 Guimohar Residency	H		504	1360 Janadhan prasad (Tiles)	20.1	27,373	31-Dec-23	31-Dec-23	doc_5550006_misran.pdf	Finishing the inside wall of G Block & G2
79887 Guimohar Residency	H		305	1360 Janadhan prasad (Tiles)	24	32,600	24-Oct-23	24-Oct-23	doc_55501715_misran.pdf	Finishing the inside wall of G Block & G2
80268 Guimohar Residency	CA	CA	204	1360 Mahaveer Gurjar - Tiles	24.091	24,091	17-Oct-23	17-Oct-23	doc_5550006_misran.pdf	Finishing the inside wall of G Block & G2
79922 Guimohar Residency	H		304	1360 Mahaveer Gurjar - Tiles	24	32,600	24-Nov-23	24-Nov-23	doc_5550006_misran.pdf	Finishing the inside wall of G Block & G2
80072 Guimohar Residency	C		601	1660 Mahaveer Gurjar - Tiles	23.1	38,994	26-Oct-23	26-Oct-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
79957 Guimohar Residency	D		104	1660 Mahaveer Gurjar - Tiles	23.1	38,994	02-Nov-23	02-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80296 Guimohar Residency	G		407	1360 Mahaveer Gurjar - Tiles	23.1	38,994	31-Oct-23	31-Oct-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
81008 Guimohar Residency	H		507	1360 Mahaveer Gurjar - Tiles	11.2	15,232	17-Nov-23	17-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80794 Guimohar Residency	A		101	1660 Mahaveer Gurjar - Tiles	20.1	27,373	31-Dec-23	31-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80797 Guimohar Residency	A		404	1660 Mahaveer Gurjar - Tiles	0.4	704	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80799 Guimohar Residency	C		107	1660 Mahaveer Gurjar - Tiles	0.6	800	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80792 Guimohar Residency	C		304	1660 Mahaveer Gurjar - Tiles	0.5	660	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80793 Guimohar Residency	C		305	1660 Mahaveer Gurjar - Tiles	0.6	800	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80796 Guimohar Residency	C		401	1660 Mahaveer Gurjar - Tiles	0.5	660	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80798 Guimohar Residency	D		404	1660 Mahaveer Gurjar - Tiles	0.5	660	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80795 Guimohar Residency	D		303	1660 Mahaveer Gurjar - Tiles	0.3	480	16-Dec-23	16-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80793 Guimohar Residency	CA	CA		0 541 Sai civil contractors - CIVIL	0	9,39,136	06-Dec-23	06-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80734 Guimohar Residency	CA	Upper Basement	407	1360 Mahaveer Gurjar - Tiles	20.5	6,45,106	13-Dec-23	13-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80241 Guimohar Residency	A	Misc		12900 Borenda Murali - CIVIL work	1.8	22,759	07-Nov-23	07-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80207 Guimohar Residency	G	All Floors		57120 P. Praveen Kumar - Fabrication Work	0.3	16,800	05-Dec-23	05-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80458 Guimohar Residency	CA	Misc		0 P. Praveen Kumar - Fabrication Work	0	17,882	29-Nov-23	29-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80377 Guimohar Residency	CA	CA		0 P. Praveen Kumar - Fabrication Work	0	24,200	25-Nov-23	25-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
79709 Guimohar Residency	C	All Floors		96000 Praveen (welding)	0.3	30,400	07-Oct-23	07-Oct-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80509 Guimohar Residency	G	All Floors		57120 Praveen (welding)	0.4	21,120	05-Dec-23	05-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80222 Guimohar Residency	Club house	All Floors		10829 B. Thirupathi Raju - Electrical work	2.4	26,250	14-Nov-23	14-Nov-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry
80487 Guimohar Residency	Club house	All Floors		10829 Praveen (welding)	0.8	9,000	04-Dec-23	04-Dec-23	doc_55501715_misran.pdf	C 504 flat floor - masonry stone m. part - masonry

APPROVED BY
14 MAY 2024
PROJECT MANAGER