Company	Silver oak villas LLP		Certified By	K Purshotham	
Project	Silver oak villas		Prepared By	A I dishotham	
Date	15-04-2024		purdu Dy	K. Tulasi Kani	
Sl.No	Description	HP/Phase	Units	Location	
1	Borewell Submreible Pump	3HP	Working		Remarks
2	Borewell Submreible Pump	3HP	Working	Near Sanjeev Reddy House	
3	Borewell Submrcible Pump	3HP	Working	Near villa no.33	
4	Borewell Submreible Pump	3HP	Working	Near villa no.50	
5	Borewell Submreible Pump	3HP	Working	Near villa no.95	
6	Borewell Submrcible Pump	3HP	Working	Near villa no.96	
7	Borewell Submrcible Pump	3HP	Working	Near Labour Quoters	
8	Borewell Submreible Pump	3HP	Working	Near CC Camera Tower Beside	
9	Cutter Type Pump	1.5HP	Working	Near Welding Shed Side	
10	Cutter Type Pump	3HP		dewatering of water from footing while casting	
11	Self Priming Pump	5HP		dewatering of water from footing while casting	
			Working	near villa no 146	





Company	Silver oak v	illas-III	Certified By	K Purshotham
Project	Silver oak villas-III		Prepared By	
Date	15-04-2024			
Sl.No		Service Number	Used for	Service provider
1	Bore	Submreible Pump-1	Near office Building	Working
2	Bore	Submreible Pump-2	Near Transformer Beside	Working
3	Bore	Submreible Pump-3	Near Villa no 33 line	Working
4	Bore	Submrcible Pump-4	Near Villa no 50 line	Working
5	Bore	Submreible Pump-5	Near Villa no 95 line	Working
6	Bore	Borewell Submrcible Pump-1	Near Lboure quaters	Working
7	Bore	Borewell Submrcible Pump-1	NearCC camara Tower Beside	Working
8	Bore	Borewell Submrcible Pump-1	Near welding shed side	Working
9	Bore	Self Priming pump	near villa no 146	Working
10	Bore	Cutter Type pump	dewatering of water from footing while casting	Working
11	Bore	Cutter Type pump	dewatering of water from footing while casting	Working
				-
	-			



