Internal memo no. 903/35/A Annexure -A INSTALLATION REPORT

ackspa

Supplier: Rainbow UPVC doors and Windows Details of installation: SI. Date of Installation Unit no. Installation (Installation) (Installati		pany/ firm:		Modi reality P	ocharam LLP	Requisition nos		20240523037		
Details of installation: SI. Date of installation OI 18.07.24 405, 507, 508, 407, 903 & 908 Details of installation Unit no. installation OI 18.07.24 405, 507, 508, 407, 903 & 908 Details of installation OI 18.07.24 405, 507, 508, 407, 903 & 908 Details of installation I 18.07.24 405, 507, 508, 407, 903 & 908 Details of installation I 2400W x 2100H 6 No's nesh	Projec	ct:				PO no.:		20240523061		
Sl. Date of installation Oli 18.07.24 405, 507, 508, 407, 903 & 908 UPVC French door with mesh 2400W x 2100H 6 No's					'C doors and	Material type:		UPVC french	door.	S
SI Date of installation OI 18.07.24 405, 507, 508, 407, 903 & 908 OI OI OI OI OI OI OI O							E+1	79	7-	,
01 18.07.24 405, 507, 508, 407, 903 & 908 UPVC French door with mesh 2400W x 2100H 6 No's	Ŝl.	Date of	Unit	t no.	Material de	etails				
Total: 6 N	01 18.07.24 405			507, 508, 407, & 908		nch door with	2400W x 2100H		61	No's
narks: work completed. Close PO.								То	tal:	6 No
	narks: v	work comple	eted . C	Close PO .						
Project manager Security Admin (Audit)	narks: v									6 No

Note: 1. Report to be sent on completion of work. 2. For partial completion report must be sent once a month. 3. This report is required for installation of windows, french windows, balcony/ staircase railing, fire doors and such materials where PO for material being set to E&D. 4. One or more reports can be made per PO. Avoid multiple POs in one report. 5. Provide report on defaults, poor quality, missing items, etc. 6. Reports to be sent to purchase@modiproperties.com regularly. However, report must be provided within one working day of request from purchase. 7. Maintain signed original at site.