EHS Audit - Site Visit Report

| Company | | Nextropolis | Audited by | B Lokesh Kumar | | | | | | |
|--|--|----------------------|--------------------------------|----------------|------------|--|--|--|--|--|
| Site | | NRK | Sign | 100 km | 10 And | | | | | |
| Project manager name | | Ramakrishan | Date | 23-07-2024 | 23-07-2024 | | | | | |
| Sign | | Va | Previous site visit date | 28-05-2024 | | | | | | |
| Note: 1. Original copy of report + ATR to be sent to MD (Ashaiya). 2. This report to be sent on site viber group on same day. 3. All major sites to be visited by Lokesh atleast once a week and this report to be sent. 4. All other sites may be visited once in two weeks. 5. Sites like Serene and AGH may be visited once in a month/quarter. 6. Rating should be good, avg., poor. 7. In ATR required fill Yes/No. 8. Project manager/Engineer must send ATR within 3 days of this report. | | | | | | | | | | |
| Sl. No. | | | | | | | | | | |
| 1. | Labour complian | Good | | | | | | | | |
| 2. | Tying of safety n | Poor | | | | | | | | |
| 3. | Material stored sa | Good | | | | | | | | |
| 4. | Engineers awarer | Good | | | | | | | | |
| 5. | Maintenance of la | Avg | | | | | | | | |
| 6. | Electrical power | Good | | | | | | | | |
| 7. | Working of guard | Good | | | | | | | | |
| 8. | Working of came | Avg | | | | | | | | |
| 9. | Maintenance of c | Good | | | | | | | | |
| 10. | Safety procedures | Good | | | | | | | | |
| S No. | Suggested rectific | ATR required | | | | | | | | |
| 1. | Safety nets cleaning require ,As Well As in some places ,need to tie safety nets | | | | | | | | | |
| 2. | | | | | | | | | | |
| 3. | | | | | | | | | | |
| Sl. No. | Suggested improvements in SOP (that can be easily taken up) | | | | | | | | | |
| 1. | | | | | | | | | | |
| 2. | | | | | | | | | | |
| 3. | 0 11: | roments in SOP (to h | e implemented after discussion | with MD/ | | | | | | |
| Sl. No. | Suggested improved Admin/Construct | ion Team/Etc.) | · mpremented arrest 2.3000000 | | | | | | | |
| 1. | | | | | | | | | | |
| 2. | | | | | | | | | | |
| 3. | | | | | | | | | | |

EHS Audit - Site Visit Report

| Compa | ny | 6 | | | | | |
|---|--|---------------------------|---|--|----------------------|--|--|
| Site | | Cresentail Labs | Audited by | B Lokesh Ku | ımar | | |
| Project manager name | | GV 1 | Sign | 1000 | | | |
| Sign | | S V Subha reddy | Date | 24-07-2024 | | | |
| Note 1 Original copy of report + A7 to visited by Lokesh atteast once a work. AGH may be visited once in a month, must send ATP posts. | | of of | Previous site visit date | 27-06-2024 | | | |
| AGH may | by Lokesh atleast once a w | eck and this report to be | This report to be sent on site viber g All other sites may be visited once in Lavg., poor 7. In ATR required fill | troup on same day | 3 All major sites to | | |
| must send | ATTA WILLIAM & days of the | remark should be sook | ave poor 7 In ATR required fill | two weeks. 5 Site: Yes/No. 8. Project | s like Serene and | | |
| 31. No. | Description/compliance with cofee | | | | | | |
| 1. | Labour compliance | Rating | | | | | |
| 2. | Tying of safety ne | Avg | | | | | |
| 3. | Material stored sa | Good | | | | | |
| 4. | Engineers awaren | Good | | | | | |
| 5. | Engineers awaren | Good | | | | | |
| 6. | Maintenance of la | Avg | | | | | |
| 7. | Electrical power s | Good | | | | | |
| 8. | Working of guard | Good | | | | | |
| 9. | Working of camer | Avg | | | | | |
| 10. | Maintenance of cr | Good | | | | | |
| | Safety procedures | Good | | | | | |
| S No. | Suggested rectifications/corrections | | | | ATR required | | |
| 1. | Some of the labour (4%) are not following safety rules and regulations | | | | | | |
| 2. | Sai kiran please ch | | | | | | |
| 3. | Labour bathroom c | | | | | | |
| Sl. No. | Suggested improvements in SOP (that can be easily taken up) | | | | | | |
| 1. | | | | | | | |
| 2. | | | | | | | |
| 3. | | | | | | | |
| | Suggested improve | | | | | | |
| | Admin/Construction | n Team/Etc.) | | | | | |
| 1. | | | | | | | |
| 2. | | | | | | | |
| 3. | | | | | | | |

