



List of tools equipments at serene farms site

Company :		serene construction llp			Approved By :		syed golam sarwar	
Project :		serene farms			Date :		15-06-2024	
Prepared By :		chandrashakarreddy						
Sl.no	Item Description	Make	TYPE	Capacity	Quantity	Units	Installed	Status
1	Drilling Machine	Bosh	Electrical	-	1	No's	At Site	Working
2	Rod Cutting-Hand Machine	Bosh	Electrical	-	1	No's	At Site	not Working
3	Rod Cutting-Big Machine	Bosh	Electrical	-	0	No's	-	-
4	Die Grinder	Bosh	Electrical	-	0	No's	-	-
5	Roots Cleaning Machine	Roots	Electrical	-	0	No's	-	-
6	Roots Cleaning Machine-Sweeper	Roots	Electrical	-	0	No's	-	-
7	Blower	NA	Electrical	-	0	No's	-	-
8	Water Pressure Machine	NA	Electrical	-	0	No's	-	-
9	RO Plant	Icon Water Solutions		-	0	No's	-	-
10	Electric powered lawn mover	proton	electrical	-	1	nos	-	working
11	petrol powered grass cutter		petrol	-	1	nos	-	not working


Certified by:
R. ENGANNOR
Team House - 1001 LP

List of Pumps & electricity meter details:									
Company:	SERENE CONSTRUCTION LLP	Approved By:	Syed Golam Sarwar						
Project:	SERENE FARMS	Date:	15-06-2024						
Contractor Details:	SERENE FARMS								
Prepared By:	chandrashekarreddy								
	1		1						
SI No:	Item Description	Make	Type	Capacity	Quantity	Units	Installed	Status	
1	Open well Submersible pump	KSB	Electrical	3 HP/ 1 ph	1	No's	Store	Working	
2	Open well Submersible pump	KSB	Electrical	1 HP/ 1 ph	1	No's	Store	Not Working	
3	Open well Submersible pump	KSB	Electrical	3 HP/ 3 ph	1	No's	sump room	Working	
4	Open well Submersible pump	KSB	Electrical	7.5 HP/ 3 ph	1	No's	sump room	Working	
5	submersible pump Borewell	KSB	Electrical	3 HP/ 3 ph	1	No's	49 villa	Working	
6	submersible pump Borewell	KSB	Electrical	3 HP/ 3 ph	1	No's	28 villa	Not Working	
7	submersible pump Borewell	KSB	Electrical	3 HP/ 3 ph	1	No's	48 villa	Not Working	
8	submersible pump Borewell	KSB	Electrical	3 HP/ 3 ph	1	No's	villa no 44	Working	
9	self priming motar	KIRLOSKAR	Electrical	3 HP/ 3 ph	1	No's	swimming pool	Working	
10	Generator	ashokleylond	deisel	20KVA	1	no's	guest corrage back side	not Working	

Certified by:

 S. A. ENGINEER
 Modil Farm, Serene Farms, Hyderabad