


Construction Division
Additions & Alteration Charges Approval Form

Company Name:		MRMLLP	Site	Gulmohar Residency
Name of the customer		Chaitanya Gangadhar.		
Villa/ Flat No.		D-507		
Sl No	Description	Amount		
1	Total extra Charges	46140		
2	Total refundable amount	3230		
3	Net amount to be charges (if any)	42910.		
4	Net amount to be refunded (if any)	<u> </u>		

Remarks :

Extra charges of Rs - forty two thousand Nine hundred & ten Rupees only.

Approved by Project Manager	Approved by Design Team	Approved by MD
Date 30/8/2023	Date	Date
Sign: 	Sign:	Sign:

Note: 1. Enclose measurement & estimate sheet. 2. Send scanned copy by email to plans@modiproperties.com & CR. 3. Maintain originals in A&A of customers at site.

ESTIMATE SHEET

Company Name:

MRM LLP

Approved by: Narander Reddy

Sign:

Project:

Gulmohar Residency

Work Description:

Extra Specs

Flat No.

D 507 Chatanya Gangadhar

Prepared By

Srinivas N


Date:

27-08-2023

S No.	Item Head	Item Description	Quantity	Units	Rate	Amount
1	Extra Charges	Beige tiles 4' x 2' Flooring (Living & Dining)	1129	Sft	35	39508.00
		MBR, Children Bed Room, Guest Bedroom, Kitchen	88	Sft	35	3080.00
		Skirting - 18 % of SBUA 1660 sft	102	Sft	35	3552.50
						46140.50
2	Refund Amount	Kitchen Platform	34.00	Sft	65	2210.00
		Kitchen Dadoo Tiles	34.00	Sft	30	1020.00
						3230.00
		Total Amount				42910.00

In words Forty Two Thousand Nine Hundred Ten Rupees only

Construction Division
Additions & Alteration Charges Approval Form

Company Name:	MRMLLP	Site	Gulmohar Residency
Name of the customer	Chaitanya Gangrahar.		
Villa/ Flat No.	D - 507.		
Sl.No	Description	Amount	
1	Total extra Charges	42911	
2	Total refundable amount	—	
3	Net amount to be charges (if any)	42911 ✓	
4	Net amount to be refunded (if any)	—	
Remarks :			
Total extra charges towards tiles works.			
Approved by Project Manager		Approved by Design Team	
Date 26/08/23.		Date	
Sign: 		Sign:	

Note: 1. Enclose measurement & estimate sheet. 2. Send scanned copy by email to plans@modiproperties.com & CR. 3. Maintain originals in A&A of customers at site.

ESTIMATE SHEET

Company Name	MRMLLP	Approved by Ramprasad						
Project	Guinmohar Residency	Sign:						
Work Description	Extra Specs							
Fiat No.	D 507 Chaitanya Gangadhar							
Prepared By	N Srinivas							
Date	24-08-2023							
S No	Item Head	Item Description	A Length	B Width	C Height	D Nos	E-AXBXCXD Quantity	F Units
1	Regal Beige tiles 4' x 2' Flooring	Regal Beige tiles 4' x 2' Flooring (Living & Dining), MBR, Children Bed Room, Guest Bedroom,	11.29	1	1	1	11.29	Sft
3	Skirting	Kitchen 68 % of 1660 sft	11	8	1	1	88	Sft
4	Granite Platform	Skirting - 21 % of SBUA 1660 sft	20.3	1	0	1	102	Sft
5	Kitchen Dadoo Tiles	Granite Platform Kitchen Dadoo Tiles	17	2	1	1	34	Sft
			17	2	1	1	34	Sft

ESTIMATE SHEET

Company Name:

Project:

Work Description:

Flat No.

Prepared By

Date:

S No.

MRMLLP

Gulmohar Residency

Extra Specs

D 507 Chaitanya Gangadhar

Srinivas N

24-08-2023

Item Head

1 Beige tiles 4' x 2' Flooring (Living & Dining)

Item Description

Beige tiles 4' x 2' Flooring (Living & Dining)

MBR, Children Bed Room, Guest Bedroom,

Kitchen

Skirting - 18 % of SBUA 1660 sft

Kitchen Platform

Kitchen Dadoo Tiles

Total Amount

Quantity

1129

Units

Sft

Rate

35

Amount

39508.00

88

Sft

35

3080.00

102

Sft

35

3552.50

-34.00

Sft

65

-2210.00

-34.00

Sft

30

-1020.00

In words Forty Two Thousand Nine Hundred Eleven Rupees only

42911

**Construction Division
Additions & Alteration Charges Approval Form**

Company Name:		MRMLLP	Site	Gulmohar Residency
Name of the customer		Chaitanya		
Villa/ Flat No.		D- 507		
Sl.No	Description	Amount		
1	Total extra Charges	58015/-		
2	Total refundable amount	-		
3	Net amount to be charges (if any)	58015/-		
4	Net amount to be refunded (if any)			
Remarks :				
Approved by Project Manager		Approved by Design Team		Approved by MD
Date 16.02.23		Date		Date
Sign: 16 FEB 2023		Sign:		Sign:

Note: 1. Enclose measurement & estimate sheet. 2. Send scanned copy by email to plans@modiproperties.com & CR. 3. Maintain originals in A&A of customers at site.

MEASUREMENT SHEET									
Company Name:	MRMLLP					Approved by:	Ramprasad		
Project:	Gulmohar Residency					Sign:			
Work Description:	Extra Specifications flat no D-507								
Prepared By	P.Sai Kumar								
Date:	16-02-2023								
S No.	Item Head	Item Description	A Length	B Width	C Height	D Nos	E = AxBxCxD Quantity	F Units	
1	D-507 flat	Extra Amount							
	Tiles 4' X 2'	Drawing	1122.00	1.00	1.00	1.00	1122.00	sft	
		skirting (18%)	348.00	1.00	1.00	1.00	348.00	ft	
	4' X 2'	Kitchen	87.00	1.00	1.00	1.00	87.00	sft	
	Urban Wood dark	Balcony	88.00	1.00	1.00	1.00	88.00	sft	

⊕ Granite.

* Kitchen =

Quality Control Check Report, Stage: After Finishing Stage III (Apartments)

Flat No	D-106	Other	SI. No.	41246
Company	MEM-CLP	Project	Phase	-
Prepared by	R.S. SATHIRAN	Sign	Date	28-01-2023
Project Manager	RAM PRASAD	Sign	Date	28-01-2023
Previous stage report no.	40378	Report filed and signed by PM	Yes ☒ No ☐	
Checked By MD on	MD Sign	For filling	Yes ☐ No ☐	

Recommendation:

- ☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- ☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- ☒ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- ☐ Proceed with further work. ATR not required.

Inspection should be done after:

- Completing stage II works
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage
- Provide video door phone in this stage
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made

Miscellaneous check:

Modular kitchen to be provided	☒ Yes ☐ No	Modular kitchen provided	☐ Yes ☐ No
Modular kitchen workman ship	☐ Good ☐ Avg ☐ Poor	Modular kitchen granite & dado workman ship & finishing	☐ Good ☐ Avg ☐ Poor
Video door phone /wifi cam to be provided	☒ Yes ☐ No	Video door phone/wifi cam provided	☐ Yes ☒ No
Painting marks and drops are cleaned from floor, windows, walls.		☐ Good ☒ Avg ☐ Poor	

Quality Control Check Report. Stage: After Finishing Stage III (Apartments)

		Rate the quality of (Good ✓, Avg X, Poor - needs correction ✗ X, NA)												
S No	Room	Door, door knob & door stopper fitting	Door, door knob & door stopper cleaning	Window grills & quality	Window grills fitting & finishing	Windows quality	Window fitting & finishing	Balcony railing quality & finishing	French door quality & fitting	CP jali quality and fitting	Edge building	Switch boards fitting & covering with plastic covers	Junction box covers painting	
1	Bedroom 1 m. Bed	✓	✓	✓	✗	✓	✓	✓	✓	✓	✗	✓	✓	
2	Bedroom 2 C. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
3	Bedroom 3 C. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
6	Lobby 1 PUSA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
7	Utility / balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
8	Utility / balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
9	Utility / balcony 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
11	Toilet 1 m. Toi	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
12	Toilet 2 C. Toi	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
13	Toilet 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✗	✓	✓	
14	Other													
15	Other													
Remarks		NOTE :- (1) In kitchen, window was not placed. (2) At couple of painting work & cement finish appears on wall. (3) C-toi was not cleaned.												

ATR on Quality Control Check Repot. (Apartments)

Flat No	QC report stage	Sl. No.
D-507	III	41343
Company	Project	Phase
MRMLLP	GMR	
Prepared by	Sign	Date
T. RAHUL	T. Rahul	23-3-23
Project Manager	Sign	Date
Ram Prasad	Ram Prasad	23-3-23
Receipt by QC date	Sign	Other
Receipt at HO date	Sign	Other
Checked By MD on	MD Sign	For filling
		☐ Yes ☐ No

Recommendation that was made by QC:

- ☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- ☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.

Notes:

1. Attach a copy of the QC report to this sheet.
2. Circle each correction with a red pen – tick (✓) each circle for work completed and cross (X) each circle where work has not been completed.
3. Give remarks for each case where work has not completed on this sheet.
4. Make 2 copied of the ATR – send one to MD and other to QC.
5. Enclose required photographs – hard copy.

Remarks:

All work completed

Quality Control Check Report. Stage: After Finishing Stage III (Apartments)

Flat No	D-507	Other	SI. No.	41343
Company	MM-LLP	Project	Phase	
Prepared by	P. Phadali	Sign	Date	17-02-23
Project Manager	Rampdas	Sign	Date	17-02-23
Previous stage report no.			Report filed and signed by PM	☒ Yes ☐ No
Checked By MD on	110919	MD Sign	For filling	☐ Yes ☐ No

Recommendation:

☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.

☒ Stop further work. Proceed with work after submitting ATR on QC report to QC team.

☐ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.

☐ Proceed with further work. ATR not required.

Inspection should be done after :

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Miscellaneous check:

Modular kitchen to be provided	☐ Yes ☒ No	Modular kitchen provided	☐ Yes ☐ No
Modular kitchen workman ship	☐ Good ☐ Avg ☐ Poor	Modular kitchen granite & dado workman ship & finishing	☐ Good ☐ Avg ☐ Poor
Video door phone /wifi cam to be provided	☒ Yes ☐ No	Video door phone/wifi cam provided	☐ Yes ☒ No
Painting marks and drops are cleaned from floor, windows, walls.			☐ Good ☒ Avg ☐ Poor

Quality Control Check Report Stage: After Finishing Stage III (Apartments)

		Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)											
S No	Room	Door, door knob & door stopper fitting	Door, door knob & door stopper cleaning	Window grills & quality	Window grills fitting & finishing	Windows quality	Window fitting & finishing	Balcony railing quality & finishing	French door quality & fitting	CP Jali quality and fitting	Edge building	Switch boards fitting & covering with plastic covers	Junction box covers painting
1	Bedroom-1 M. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom-2 K. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Bedroom-3 Gr. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Lobby+ Pooja	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility/ balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Utility/ balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Utility/ balcony 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Toilet-1 M. Toi	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	Toilet-2 C-Toi	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
13	Toilet-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
14	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
15	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Remarks		1) French door was not provided. 2) For (-Toi, M. Toi) top of tiles painting not done, M. Toi for one S. Board cover not provided. 3) white cement for PVC lines not provided.											

Quality Control Check Report. Stage: After Finishing Stage II (Apartments)

Flat No	D-507	Other	Sl. No.	40949
Company	MEM-UP	Project	Phase	-
Prepared by	R.S. SATHIRAN	Sign	Date	09-12-2022
Project Manager	RAM PRASAD	Sign	Date	09-12-2022
Previous stage report no.			Report filed and signed by PM	☐ Yes ☐ No
Checked By MD on		MD Sign	For filling	☐ Yes ☐ No

Recommendation:

- ☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- ☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- ☒ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- ☐ Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, first coat of paint.
- Completion of doors, windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	☒ Yes ☐ No	Granite soffit for balcony provided	☒ Yes ☐ No
Granite soffit for balcony required	☒ Yes ☐ No	Balcony granite soffit edge polishing	☐ Good ☒ Avg ☐ Poor
Balcony granite soffit workmanship	☐ Good ☒ Avg ☐ Poor	Granite soffit for main door provided	☒ Yes ☐ No
Granite soffit for main door required	☒ Yes ☐ No	Main door granite soffit edge polishing	☐ Good ☒ Avg ☐ Poor
Main door granite soffit workmanship	☐ Good ☒ Avg ☐ Poor		

Certified that all corrections mentioned in the QC Report have been completed. Work can Proceed to next Stage.

Project In-charge	Sign	Date
Ram Prasad		13/12/22

Quality Control Check Report. Stage: After Finishing Stage II (Apartments)

Flat No	D-507	Other	Sl. No.	40949
Company	MEM-UP	Project	Phase	-
Prepared by	R.S. SATHIRAN	Sign	Date	09-12-2022
Project Manager	RAM PRASAD	Sign	Date	09-12-2022
Previous stage report no.			Report filed and signed by PM	☐ Yes ☐ No
Checked By MD on		MD Sign	For filling	☐ Yes ☐ No

Recommendation:

- ☐ Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- ☐ Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- ☒ Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- ☐ Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, first coat of paint.
- Completion of doors, windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	☒ Yes ☐ No	Granite soffit for balcony provided	☒ Yes ☐ No
Granite soffit for balcony required	☒ Yes ☐ No	Balcony granite soffit edge polishing	☐ Good ☒ Avg ☐ Poor
Balcony granite soffit workmanship	☐ Good ☒ Avg ☐ Poor	Granite soffit for main door provided	☒ Yes ☐ No
Granite soffit for main door required	☒ Yes ☐ No	Main door granite soffit edge polishing	☐ Good ☒ Avg ☐ Poor
Main door granite soffit workmanship	☐ Good ☒ Avg ☐ Poor		

Certified that all corrections mentioned in the QC Report have been completed. Work can Proceed to next Stage.

Project In-charge	Sign	Date
Ram Prasad		13/12/22

Quality Control Check Report Stage: After Finishing Stage II (Apartments)

S No	Room	Flooring workman ship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	Windows check	Rate the quality of (Good ✓, Avg. X, Poor - needs correction X X, NA)					
		Color variation of floor tiles								General quality of painting & finishing	Door & frame painting quality	Door heading, luppam and painting quality.	Edge building		
1	Bedroom 1 m. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom 2 C. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Bedroom 3 C. Bed	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Lobby 1 PUSA	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility/balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Utility/balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Utility/balcony 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
12	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Remarks		NOTE:- 1) For main door painting was pending. 2) false ceiling work was pending in m. w. & c. r. o. i. 3) In utility, hole packing work was not done.													

Tiling & granite work		Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)													
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform	
1	Toilet 1 M-toi	✓		✓	X	X	✓	✓	✓	✓	✓	✓	✓	✓	
2	Toilet 2 C-toi	✓	X		✓	X	✓	✓	✓	✓	✓	✓	✓	✓	
3	Toilet 3	✓	X	X	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4	Toilet 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
5	Wash basin in dining area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
6	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
7	Utility	✓	X	X	X	X	✓	✓	✓	X	✓	✓	✓	✓	
8	Other														
9	Other														
Remarks		NOTE :- 1) In M-toi & C-toi, painting work was pending. 2) provision for modular kitchen.													



GULMOHAR RESIDENCY

Sy. No. 19, Mallapur Village, Uppal, Hyderabad.
Owned & Developed by: M/s. Modi Realty Mallapur LLP.
Head office; 5-4-187/3&4 M G Road Secunderabad.

Details of Additions & Alterations

Flat No	507	Block no.	' D '
Flat Area	1660 sft	Type	Deluxe / Luxury
Buyer Name	Chaitanya Gangadhar Dontabhaktuni		
Phone No.	9703178833	Email	ganga 91221 @ gmail.com

I hereby confirm that I have given the details of the minor additions and alterations that are required in the above referred flat in the pages attached herein. Please complete the changes suggested by me. I agree to pay the charges, if any, for the additions and alterations that I have asked you to make, as per the rates suggested by you. I shall deliver all the materials that are required to be provided by me at the site on or before _____. In case I fail to deliver these items to the site by the specified date, you may complete the works in the flat as per the standard items provided by you.


Buyers sign		Engg. Sign	
Date:	11/09/2021	Date	11/09/2021

Note:


1. Colour shades of paints may vary from batch to batch & company to company. The Builder will not take responsibility of quality of work for dark shades especially green & blue.
2. Shade / colour of natural material like marble and granite can't be guaranteed and may vary from lot to lot. Cracks like appearance in marble is a natural feature and Builder shall not be responsible for repairs or replacement.
3. Availability of bathroom or flooring tiles of the same type /colour/make can not be guaranteed and closest possible type/colour/make may be used in its place.
4. No further change shall be permitted from this day.
5. Please sign on all pages.

Buyers sign:

Engg. Sign:




Date:



Description	Direction	Owners & Developers :	Date :	Promoted by
WORKING PLAN-1660 Sft-B1 TYPE	N	Modi Reality Mallapur LLP	25.09.2020	Modi Properties Pvt Ltd
		Project Name & Phase :	Prepared By :	Modi Properties Pvt Ltd
		Gulmohar Residency	Approved By :	Modi Properties Pvt Ltd
			Scale :	Phone : +91-40-66335551


T. P. P.



LEGEND

	HEALTH FAUCET
	ANGLE VALVE
	NANI TRAP
	3" RAIN WATER PIPE
	GEASER POINT
	WALL MIXTURE
	TAP / LONG BODY

Description PLUMBING PLAN-1660 SR (B1-TYPE)	Direction	Owners & Developers :	Date :	04.09.20	Promoted by
	N 	Modi Reality Mallapur LLP	Prepared By :	Jayapradha	Modi Properties Pvt Ltd
		Project Name & Phase :	Approved By :	Soham Modi	
		Gulmohar Residency	Scale :	N.T.S	Phone: +91-40-66335551



LEGEND:-

S.NO	ITEM	SYMBOL	HEIGHTS From FFL
1.	Distribution Board & Change over	DB	7' TO 7'6"
2.	Switch board	SB	4' OR 4'6"
3.	Miniature circuit breaker	MCB	7' TO 7'6"
4.	1 amp plug point	1A	2'
5.	Calling line	CL	8' OR 7'6"
6.	Open point-USA	OP	7'6"
7.	Exhaust fan	EF	7'6"
8.	15 amp plug point	15A	2' OR 2'6" OR 7'6"
9.	Telephone point	TP	2'
10.	Telephone point	TP	2'
11.	Calling line	CL	4'6"
12.	Bed Point	BP	4'
13.	Calling light	CL	7'6"
14.	AC Compressor	AC	7' TO 7'6"
15.	AC Blower	AB	7' TO 7'6"
16.	Switch board with 1A	SB	4' TO 4'6"

Note:- Switch boards must be bed side must be
 @ 5'0" from center of bed.

Description

ELECTRICAL PLAN -B1 TYPE-1660 sq ft

Direction



Owners & Developers :

Modi Reality Mallapur LLP

Project Name & Phase :

Gulmohar Residency

Date :

23.09.2020

Prepared By :

Jayapradha

Approved By :

Soham Modi

Scale :

N.T.S

Promoted by

Modi Properties Pvt Ltd

Phone:-+91-40-66335551

Choice of colours:

Changes in flooring:

Buyers sign:

Engg. Sign:

Date:

Changes in electrical points: (mark on plan)

Choice of Bathroom tiles, CP fittings & Sanitary ware:

Buyers sign:

Engg. Sign:

Date:

Changes in kitchen platform: (mark on plan)

Other Changes:

Buyers sign:

Engg. Sign:

Date:

Complaints And Suggestions from Gulmohar Residency

From: Gulmohar Residency (info@modiproperties.com)

To: cr@modiproperties.com; feedback@modiproperties.com; kprasad@modiproperties.com;
gbrambabu@modiproperties.com; gmr-const@modiproperties.in; ganga91221@gmail.com

Date: Sunday, August 18, 2024 at 08:48 AM GMT+5:30

Complaint Id : 151797

Project Name : Gulmohar Residency

Block No / Phase : Block D

Flat No/Villa :507

Nature of complaint :Construction

Customer Name : Chaitanya Gangadhar

Email : ganga91221@gmail.com

Complaints :

1. The POP on the walls is getting peeled off in the master bedroom and other walls
2. The taps in the kitchen have got a thin line of water, Taps cleaning to be done
3. The second coat of painting in the common areas is not completed
4. The water clogging in the common areas is not addressed causing inconvenience to reach our homes during rains
5. Tiles in the washroom are not properly layered one or the other tile is loosened eventually and comes out
6. The Manjeera or lofted tank is not connected to kitchen tap for usage till date
7. Cleaning of duct areas is not being done on regular basis

Note:

1. Please allow atleast two weeks for us to attend your complaint.
2. In general written response / reply to complaints shall not be given.
3. In case the complaint is not attended to for over two weeks customers are requested to send a reminder using the form given.

ACTION TAKEN REPORT (FOR COMPLAINTS)

Flat / bungalow No.	D-507	ATR Date	11-09-2024
Project	GMR	Complaint Date	18-08-2024
Customer Name	Chaitanya Gangadhar		
Prepared By	Sk.Goushee Begum		
Project Manager's Sign	N.Srinivas	Admin Officer's Sign	SK.Goushee

Note: Original ATR should be sent to CR & a copy to MD. CR to file original in customer's file.

[illegible]

Note: 1. Keep the report brief. 2. Do not repeat the complaint. 3. Use terms like "Work completed", "Changes not permitted – work not taken up", "Kept pending at customer's request", "Beyond our scope of work", etc.

Quality Control Check Report for ATR on Complaints

Flat / bungalow No.		D-507		ATR Date		11-09-2024	
Project		GMR		Complaint Date		18-08-2024	
Customer Name		Chaitanya gangadhar					
Prepared by	Saikiran	Date	13-09-2024	Sign	Saikiran		
Project Manager	Srinivas/Sanket	Date	13-09-2024	Sign	sanket		
HO receipt date				Sign			
Checked by MD on				MD Sign			
MD's Remarks:							
CR to send letter to customer		☐ Yes ☐ No		For filling		☐ Yes ☐ No	

Note: CR will send a copy of ATR and complaint to QC immediately after the receipt of the ATR. QC will send their report on the ATR to the MD within 3 working days. Aruna to file to file it in MDs pending complaints file.

[illegible]

Complaints And Suggestions from Gulmohar Residency

From: Gulmohar Residency (info@modiproperties.com)

To: cr@modiproperties.com; feedback@modiproperties.com; kprasad@modiproperties.com;
gbrambabu@modiproperties.com; gmr-const@modiproperties.in; ganga91221@gmail.com

Date: Sunday, March 10, 2024 at 06:32 PM GMT+5:30

Complaint Id : 595193

Project Name : Gulmohar Residency

Block No / Phase : Block D

Flat No/Villa :507

Nature of complaint :Day to Day Maintenance

Customer Name : D Chaitanya Gangadhar

Email : ganga91221@gmail.com

Complaints :

1. Overhead tanks of D Block are not being cleaned since possession
2. Requested to cover the common areas with CC surveillance
3. Often facing water issues as tanks gets emptied now and then
4. Some of the tiles in the common areas needs to be fixed again
5. The second lift should be completed asap and corridors to be cleaned daily after work

Note:

1. Please allow atleast two weeks for us to attend your complaint.
2. In general written response / reply to complaints shall not be given.
3. In case the complaint is not attended to for over two weeks customers are requested to send a reminder using the form given.

ACTION TAKEN REPORT (FOR COMPLAINTS)

Flat / bungalow No.	D-507	ATR Date	14-03-2024
Project	GMR	Complaint Date	01-03-2024
Customer Name	Chaitaya gangadhar	Com.ID.no:	14193
Prepared By	Meenakshi		
Project Manager's Sign	K.Narender	Admin Officer's Sign	Meenakshi

Note: Original ATR should be sent to CR & a copy to MD. CR to file original in customer's file.

[illegible]

Note: 1. Keep the report brief. 2. Do not repeat the complaint. 3. Use terms like "Work completed", "Changes not permitted – work not taken up", "Kept pending at customer's request", "Beyond our scope of work", etc

Quality Control Check Report for ATR on Complaints .

Flat / bungalow No.		D-507		ATR Date		14-03-2024	
Project		GMR		Complaint Date		01-03-2024	
Customer Name		Chaitaya gangadhar					
Prepared by		Saikiran		Date		16-03-2024	
				Sign		Saikiran	
Project Manager		Narendar		Date		16-03-2024	
				Sign		Narendar	
HO receipt date				Sign			
Checked by MD on				MD Sign			
MD's Remarks:							
CR to send letter to customer		☐ Yes ☐ No		For filling		☐ Yes ☐ No	

Note: CR will send a copy of ATR and complaint to QC immediately after the receipt of the ATR. QC will send their report on the ATR to the MD within 3 working days. Aruna to file to file it in MDs pending complaints file.

Complaint S No.	Quality of action taken by Site Engg on complaint?	If action on the complaint was not taken then, was the reason for not taking action justified?
1.	Avg.	☐ Yes ☐ No
2.	Avg.	☐ Yes ☐ No
3.	Avg.	☐ Yes ☐ No
4.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
5.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
6.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
7.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
8.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
9.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
10.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
11.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
12.	☐ Good ☐ Avg. ☐ Bad	☐ Yes ☐ No
Remarks:		